

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20000666/KPS3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497777-02

Claimant
Vehicle No : SHD9935C **Insured Vehicle No :** SLK3143B

Date of Loss: 06/01/2020 **Nature of Claim:** TP **Claim No:** 0844146347SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9935C
Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C001330
Reg. Date: 05/06/2014 (Man. Year: 2014) **Chassis No:** VF1ABL15AUC277894
Colour: Metallic White/Red **Odometer:** 992979 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 **Rear Tyre Size:** 215/60 R16
Front Left Side: Sailun 9 mm **Rear Left Side:** Sailun 9 mm
Front Right Side: Sailun 9 mm **Rear Right Side:** Sailun 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 17,542.53 | 4,479.35 | 13,063.18 | 74.47 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 18,230.00 | 1,520.00 | 16,710.00 | 91.66 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 35,772.53 | 5,999.35 | 29,773.18 | 83.23 |
| Approved Total (Overridden) (S\$) | | 4,800.00 | | |
| (S\$) | 35,772.53 | 4,800.00 | 30,972.53 | 86.58 |
| + GST 7.00/7.00% (S\$) | 2,504.08 | 336.00 | 2,168.08 | 86.58 |
| Nett Amount (S\$) | 38,276.61 | 5,136.00 | 33,140.61 | 86.58 |
| + Loss of Use (5.0 x S\$50.00/day) (S\$) | | 250.00 | | |
| + Car Rental (5.0 x S\$95.04/day) (S\$) | | 475.20 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 5,868.65 | | |
| Global Sum Settlement (S\$) | | 5,850.00 | | |

INSPECTION

Date of Assignment: 09/01/2020

Date Inspected: 09/01/2020 **Inspected At:** Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-------------------|-------------|--------------|
| 1 | 1 | | *BUMPER COVER REAR | Buckled / Cracked | 561.70 FL | *561.70 FL |
| 2 | 1 | | *BUMPER LOWER REAR | Dented | 411.90 FL | *411.90 FL |
| 3 | 1 | | *BUMPER BRACKET CTR REAR | Serviceable | 98.10 FL | *- FL |
| 4 | 1 | | *BUMPER BRACKET SIDE RH REAR | Serviceable | 82.10 FL | *- FL |
| 5 | 1 | | *BUMPER RETAINER RH REAR | Serviceable | 59.80 FL | *- FL |
| 6 | 1 | | *BUMPER REFLECTOR RH | Serviceable | 16.60 FL | *- FL |
| 7 | 1 | | *BUMPER BRACKET SIDE LH REAR | Serviceable | 80.80 FL | *- FL |
| 8 | 1 | | *BUMPER RETAINER LH REAR | Serviceable | 54.20 FL | *- FL |
| 9 | 1 | | *BUMPER REFLECTOR LH | Serviceable | 16.60 FL | *- FL |
| 10 | 1 | | *BUMPER BEAM REAR | Bent | 547.80 FL | *547.80 FL |
| 11 | 1 | | *BUMPER BEAM BRACKET LH REAR | Repair | 114.50 FL | *- FL |
| 12 | 1 | | *BUMPER BEAM BRACKET RH REAR | Bent | 100.90 FL | *100.90 FL |
| 13 | 1 | | *OUTER PANEL PANEL (END PANEL) | Bent | 745.80 FL | *745.80 FL |
| 14 | 1 | | *OUTER PANEL PANEL (END PANEL)TRIM | Dented | 404.56 FL | *404.56 FL |
| 15 | 1 | | *TAILLAMP RH | Serviceable | 313.10 FL | *- FL |
| 16 | 1 | | *TAILLAMP PANEL RH | Repair | 401.40 FL | *- FL |
| 17 | 1 | | *TAILLAMP LH | Serviceable | 401.40 FL | *- FL |
| 18 | 1 | | *TAILLAMP PANEL LH | Repair | 401.40 FL | *- FL |
| 19 | 1 | | *BOOT REAR | Bent | 1,677.20 FL | *1,677.20 FL |
| 20 | 1 | | *BOOT FINISHER | Serviceable | 344.70 FL | *- FL |
| 21 | 1 | | *BOOT WEATHERSTRIP (50%) | Cut | 160.38 FS | *89.10 FS |
| 22 | 1 | | *BOOT REFLECTOR LAMP LH | Serviceable | 277.70 FL | *- FL |
| 23 | 1 | | *BOOT REFLECTOR LAMP RH | Serviceable | 277.70 FL | *- FL |
| 24 | 1 | | *BOOT BADGE RENAULT | Necessary | 82.40 FL | *82.40 FL |
| 25 | 1 | | *BOOT BADGE | Necessary | 95.80 FL | *95.80 FL |
| 26 | 1 | | *BOOT STRUT LH | Serviceable | 145.10 FL | *- FL |
| 27 | 1 | | *BOOT STRUT RH | Serviceable | 145.10 FL | *- FL |
| 28 | 1 | | *BOOT HINGE LH | Repair | 254.20 FL | *- FL |
| 29 | 1 | | *BOOT HINGE RH | Repair | 253.80 FL | *- FL |
| 30 | 2 | | *BOOT RUBBER PLUG | Serviceable | 139.90 FL | *- FL |
| 31 | 1 | | *BOOT LOCK LINKAGE | Serviceable | 20.60 FL | *- FL |
| 32 | 1 | | *BOOT LOCK LINKAGE HOLDER | Serviceable | 99.50 FL | *- FL |
| 33 | 1 | | *BOOT INNER TRIM BOARD | Serviceable | 611.00 FL | *- FL |
| 34 | 1 | | *BOOT SWITCH | Serviceable | 113.00 FL | *- FL |
| 35 | 1 | | *BOOT LOCK | Repair | 246.60 FL | *- FL |
| 36 | 1 | | *BOOT LOCK CATCH | Repair | 41.70 FL | *- FL |
| 37 | 1 | | *EXHAUST CAP REAR | Repair | 125.40 FL | *- FL |
| 38 | 1 | | *EXHAUST REAR | Repair | 5,263.60 FL | *- FL |
| 39 | 1 | | *SPARE WHEEL PANEL | Repair | 1,229.40 FL | *- FL |
| 40 | 1 | | *SPARE TYRE BOARD | Serviceable | 680.90 FL | *- FL |
| 41 | 1 | | *SPARE WHEEL PANEL TRIM | Serviceable | 612.21 FL | *- FL |
| 42 | 1 | | *SET PARKING AID | Serviceable | 700.00 FS | *- FS |
| 43 | 1 | | *SET REAR BUMPER CLIP | Necessary | 66.00 FS | *66.00 FS |
| 44 | 1 | | *SET BUMPER BRACKET CTR CLIP | Necessary | 33.00 FS | *33.00 FS |
| 45 | 1 | | *SET BUMPER BRACKET SIDE CLIP RH RR | Not Necessary | 10.00 FS | *- FS |
| 46 | 1 | | *SET BUMPER RETAINER RH CLIP RR | Not Necessary | 20.00 FS | *- FS |
| 47 | 1 | | *SET BUMPER BRACKET SIDE CLIP LH RR | Not Necessary | 10.00 FS | *- FS |
| 48 | 1 | | *SET BUMPER RETAINER CLIP LH RR | Not Necessary | 20.00 FS | *- FS |
| 49 | 1 | | *SET BUMPER LOWER REAR RIVET | Not Necessary | 22.00 FS | *- FS |
| 50 | 1 | | *SET BUMPER LOWER REAR CLIP | Necessary | 66.00 FS | *66.00 FS |
| 51 | 1 | | *BOOT STICKER TRANS-CAB | Necessary | 30.00 FS | *30.00 FS |
| 52 | 1 | | *BOOT STICKER 6555-3333 | Necessary | 30.00 FS | *30.00 FS |
| 53 | 2 | | *REAR WINDSCREEN SEALANT | Not Necessary | 80.00 FS | *- FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|------------|--------|
| 54 | 1 | | *WINDSCREEN MOULDING | Not Necessary | 100.00 FS | *- FS |
| 55 | 1 | | *REAR WINDSCREEN INNER SPONGE SEAL | Not Necessary | 100.00 FS | *- FS |
| 56 | 1 | | *BOOT INNER TRIM CLIP | Not Necessary | 45.00 FS | *- FS |
| 57 | 1 | | *SET BOOT FINISHER CLIP | Not Necessary | 24.20 FS | *- FS |
| 58 | 1 | | *TAILLAMP CLIP LH | Not Necessary | 5.00 FS | *- FS |
| 59 | 1 | | *TAILLAMP CLIP RH | Not Necessary | 5.00 FS | *- FS |
| 60 | 1 | | *REAR BUMPER PROTECTOR | Not Necessary | 100.00 FS | *- FS |
| 61 | 1 | | *EXHAUST MOUNTING REAR | Not Necessary | 16.00 FS | *- FS |
| 62 | 1 | | *EXHAUST BRACKET REAR | Not Necessary | 24.80 FS | *- FS |
| 63 | 1 | | *SET REAR LICENCE PLATE WITH HOLDER | Serviceable | 80.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (S\$) | 19,297.55 | 4,942.16 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 1,755.02 | 462.81 |
| Total Parts (S\$) | 17,542.53 | 4,479.35 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|------------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 60.00 |
| 2 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 60.00 |
| 3 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 60.00 |
| 4 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| 5 | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 6 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 7 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 7,500.00 | 600.00 |
| 8 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 9 | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 170.00 | 0.00 |
| 10 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 60.00 |
| 11 | TO REPAIR AND REALIGN REAR EXHAUST PIPE | New | 170.00 | 0.00 |
| 12 | TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 13 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 14 | TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE | New | 170.00 | 0.00 |
| 15 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 7,500.00 | 660.00 |
| 16 | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 17 | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING | New | 380.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 18,230.00 | 1,520.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >