Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000668/UDS3Q2

Date: 14/04/2020

REFERENCE

Price:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082887

Claimant
Vehicle No: SFQ89J

Insured Vehicle No: SJS5243P

Date of Loss: 08/01/2020 Nature of Claim: TP Claim No: 3265571040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFQ89J

 Make & Model:
 MERCEDES-BENZ E200, 1.8 (A)
 Engine No:
 27492031780458

 Reg. Date:
 19/09/2019 (Man. Year: 2019)
 Chassis No:
 WDD2130422A625979

 Colour:
 Red
 Odometer:
 5560 km

Colour: Red Engine Capacity: 1991 cc

Market Value/New Car

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/30Z R20 Rear Tyre Size: 235/30Z R20
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm
Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,343.00	2,627.10	2,715.90	50.83
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,195.00	820.00	1,375.00	62.64
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,538.00	3,447.10	4,090.90	54.27
	+ GST 7.00/7.00% (S\$)	527.66	241.30	286.36	54.27
	Nett Amount (S\$)	8,065.66	3,688.40	4,377.26	54.27
	+ Loss of Use (3.0 x S\$	6100.00/day) (S\$)	300.00		
	+ Doc	/Search Fee (S\$)	2.00		
	N	Nett Liability (S\$)	3,990.40		

INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 10/01/2020 Inspected At: Specialists Motor Pte Ltd (HQ)

Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHAN JIA LE

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount			
1	1	*REAR BUMPER FASCIA	Dented / Deformed	Dented / Deformed 2,241.00 F				
2	1	*SET REAR BUMPER CLIPS	Necessary	36.00 F	*36.00 FL			
3	1	*REAR BUMPER TOWING COVER	Not Necessary	95.00 F	*- FL			
4	1	*REAR BUMPER LOWER LIP CHROI	ME Not Necessary	335.00 F	*- FL			
5	1	*REAR BUMPER LOWER LIP GARNI	SH (BLACK) Scratched	302.00 F	*302.00 FL			
6	2	*REAR BUMPER SIDE RETAINER L	RR Not Necessary	90.00 F	*- FL			
7	1	*REAR BUMPER REINFORCEMENT	BEAM Serviceable	886.00 F	*- FL			
8	2	*REAR BUMPER REFLECTOR L&R	Not Necessary	64.00 F	*- FL			
9	2	*REAR BUMPER PARKING SENSOR	Serviceable	608.00 F	*- FL			
10	1	*SET REAR BUMPER RIVET	Necessary	126.00 F	*60.00 FL			
11	1	*REAR EXHAUST TIP L&R	O/S Scratched	560.00 F	*280.00 FL			
F=Fra	inchise	part. L=ListItemDisc.	Sub Total (S\$)	5,343.00	2,919.00			
- List Item Discount on L Items 0.00/10.00% (S\$)					291.90			
			Total Parts (S\$)	5,343.00	2,627.10			
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CUT OUT ,RENEW ,KNOCKING & WELDING REAR LAMP PANEL,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	980.00	400.00
2	SPRAY PAINTING ON DAMAGE PARTS	New	680.00	300.00
3	REMOVE & REFIX REAR BUMPER SENSOR	New	100.00	50.00
4	CHECK ALL LIGHTING AFTER REPAIR	New	35.00	20.00
5	REMOVE & REFIX REAR EXHAUST SENSOR	New	100.00	50.00
6	DIAGNOSTIC & RESET	New	300.00	0.00
	Gross Labour Cost (S\$)		2,195.00	820.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >