



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Mr Tan Gee Hock (chen Rufu) Reg No/Reg Date SMG9204D / 04/01/2019 Date In/Mileage 07/01/2020/ 0 Chassis No GF7W0600281 Engine No 4J11AA4189 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim W01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000034	Credit	08/01/2020/ 11:49	DS	218 / MarsLer	39657				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC / SCANNING							250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS							80 100.00
S	MIPNT88088	TO REMOVE AND RE-INSTALL RAD & A/C TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS per day 600							180.00
S	MIPNT88088	TO REPLACE FRONT BUMPER, REINFORCEMENT, ETC -REPLACE UPR & LH SUPPORT PANEL STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS							200 2400.00
S	MIPNT98088	SPRAY PAINTING							840.00 840.00
M	JJ6400K147	FACE, FR BUMPER	X NH		1.00	851.00	0.00		851.00
P	JJ6405A269HA	EXTENSION, FR BUMPER	✓ SCR		1.00	509.00	0.00		509.00
M	JJMU488006	CLIP, FR BUMPER	✓ NH		20.00	2.00	0.00		40.00
M	JJMR590000HB	CLIP, FR BUMPER	✓ NH		10.00	3.00	0.00		30.00
M	JJMU001657	RIVET, FR BUMPER	✓ NH		6.00	5.00	0.00		30.00
M	JJ6400J294	COVER, FR BUMPER	✓ SCR		1.00	355.00	0.00		355.00
M	JJ6400J447	LH GARNISH, FR BUMPER	X (SVC)		1.00	48.00	0.00		48.00
M	JJ6400H314	RH SIDE BRACKET, FR B	X (SVC)		1.00	18.00	0.00		18.00
M	JJ6400H313	LH SIDE BRACKET, FR B	✓ NH		1.00	18.00	0.00		18.00
P	JJ6407A145	GARNISH, FR BUMPER S	✓ NH		1.00	220.00	0.00		220.00
P	JJ6407A143	GARNISH, FR BUMPER S	X (SVC)		1.00	112.00	0.00		112.00
M	JJ6407A141	GARNISH, FR BUMPER SI	X (SVC)		1.00	48.00	0.00		48.00
M	JJ6400J626	REINFORCEMENT, FR BUM	X (SVC)		1.00	524.00	0.00		524.00
M	JJ8301D329	LH HEADLAMP ASSY	X (SVC)		1.00	1938.00	0.00		1938.00
M	JJ6400G576	REINFORCEMENT, FR BUM	X (SVC)		1.00	134.00	0.00		134.00
M	JJ6400D581	LH SIDE REINFORCEMENT	X (SVC)		1.00	60.00	0.00		60.00
M	JJ6400D977	SIDE REINFORCEMENT, F	X (SVC)		2.00	22.00	0.00		44.00
M	JJ5256C259	UPR LH PANEL, HEADLAMP	X (R)		1.00	58.00	0.00		58.00
M	JJ5256C555	UPR PANEL, HEADLAMP S	X (R)		1.00	182.00	0.00		182.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Mr Tan Gee Hock (Tan Rufu)
Contact No	Reg No/Reg Date SMG9204D / 04/01/2019
	Date In/Mileage 07/01/2020/ 0
	Chassis No GF7W0600281
	Engine No 4J11AA4189
	Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim W01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	08/01/2020/ 11:49	DS	218 / MarsLer	39657

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M JJ7407A315 LH MOULDING, FR BUMP ✓ <i>As per</i>	1.00	116.00	0.00	116.00
Z NOTES ACCIDENT ON 06/01/2020 ALONG JUNCTION OF BISHAN ROAD & BISHAN ST 14 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SHA1689G TP INS : MS FIRST CAPITAL				

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by


Parts	5,335.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,190.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	9,525.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877  Contact No	Cust No/Name	/Mr Tan Gee Hock (chen Rufu)
	Reg No/Reg Date	SMG9204D / 04/01/2019
	Date In/Mileage	07/01/2020/ 0
	Chassis No	GF7W0600281
	Engine No	4J11AA4189
	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim	W01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000034	Credit	10/01/2020/ 11:20	DS	218 / MarsLer	39657				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088								
	ZERTONA PAINT PROTECTION								
Z	NOTES								
	SUPPLEMENTARY ITEM								550.00

✓ (vehicle delivery certificate)  
refer

# Estimate

Confirm & accepted by	Parts	0.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	550.00
	Others(Lub,etc)	0.00
	Sundry	0.00
Authorized signatory and company stamp	Total(w/o GST)	550.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877  Contact No	Cust No/Name	/Mr Tan Gee Hock (chen Rufu)
	Reg No/Reg Date	SMG9204D / 04/01/2019
	Date In/Mileage	10/02/2020/ 24371
	Chassis No	GF7W0600281
	Engine No	4J11AA4189
	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim	W01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000034	Credit	14/02/2020/ 10:19	DS	218 / MarsLer	39657			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC / SCANNING						250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS						80.00
S	MIPNT88088	TO REPLACE FR BUMPER EXTENSION & LH CHROME GARNISH,ETC -REPAIR FR BUMPER & REINFORCEMENT & UPR & LH SUPPORT PANEL STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS						1200.00
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS						840.00
S	MIPNT88088	ZERTONA PAINT PROTECTION						550.00
X	JJ6405A269HA	EXTENSION,FR BUMPER			5.00	509.00	0.00	509.00
X	JJMR200300	CLIP, BUMPER			20.00	2.00	0.00	40.00
X	JJMR288150	CLIP,RR BUMPER			10.00	3.00	0.00	30.00
X	WMCD112	RIVET			6.00	5.00	0.00	30.00
X	JJ6400J294	COVER,FR BUMPER			1.00	355.00	0.00	355.00
X	JJ6400H313	LH SIDE BRACKET,FR B			1.00	18.00	0.00	18.00
X	JJ6407A145	GARNISH, FR BUMPER S			1.00	220.00	0.00	220.00
X	JJ7407A315	LH MOULDING, FR BUMP			1.00	116.00	0.00	116.00
Z	NOTES							
ACCIDENT ON 06/01/2020 ALONG JUNCTION OF BISHAN ROAD & BISHAN ST 14								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT CAR (CHAN'S)								
TP # SHA1689G TP INS : MS FIRST CAPITAL								
Confirm & accepted by					Parts			1,318.00
					Labour			0.00
					Standard Menu			0.00
					Specialist Job			2,920.00
					Others(Lub,etc)			0.00
					Sundry			0.00
					Total(w/o GST)			4,238.00

Finalization

Authorized signatory and company stamp

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.