

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20000675/QGA3Q2

**Date:** 24/06/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHB630B	<b>Insured Vehicle No :</b>	SHB4375L
Date of Loss: 07/01/2020	Nature of Claim: TP	Claim No: MCT20010170

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB630B</b>	Engine No:	2ZR6115464
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U305747973
Reg. Date:	03/09/2014 (Man. Year: 2014)	Odometer:	598394 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,352.27	604.24	15,748.03	96.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	820.00	3,450.00	80.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,622.27</b>	<b>1,424.24</b>	<b>19,198.03</b>	<b>93.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,622.27</b>	<b>1,450.00</b>	<b>19,172.27</b>	<b>92.97</b>
<b>+ Car Rental (5.0 x S\$133.75/day) (S\$)</b>		668.75		
		<b>Nett Liability (S\$)</b>	<b>2,118.75</b>	

#### INSPECTION

Date of Assignment:	10/01/2020	
Date Inspected:	10/01/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

**Adjuster:** LEE HOCK ANN

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2020)
<b>Parts:</b> 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB630B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.92 F
2	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
3	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
4	1		*BUMPER FRT	Serviceable	482.00 F	*- F
5	10		*BUMPER CLIPS	Serviceable	16.10 F	*- F
6	1		*BUMPER SUPPORT F/RH	Serviceable	76.40 F	*- F
7	1		*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F
8	1		*BUMPER ENERGY ABSORBER FRT	Serviceable	78.80 F	*- F
9	1		*BUMPER REINFORCEMENT FRT	Serviceable	498.40 F	*- F
10	1		*ARM SUB-ASSY ,FR BUMPER LH	Serviceable	250.40 F	*- F
11	1		*ARM SUB-ASSY ,FR BUMPER RH	Serviceable	250.40 F	*- F
12	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Serviceable	311.10 F	*- F
13	1		*BUMPER LIP FRT	Serviceable	139.60 F	*- F
14	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
15	1		*UNDER COVER CENTER	Serviceable	448.30 F	*- F
16	1		*UNDER COVER SIDE/LH	Serviceable	46.10 F	*- F
17	1		*HINGE LOWER LHF ,DOOR	Serviceable	90.10 F	*- F
18	1		*HINGE UPPER LHF,DOOR	Serviceable	80.50 F	*- F
19	1		*CHECK ASSY ,FR DOOR	Serviceable	150.30 F	*- F
20	1		*MIRROR ASSY ,LH	Serviceable	1,224.90 F	*- F
21	1		*MIRROR LAMP LH	Serviceable	65.30 F	*- F
22	1		*TYRE	Serviceable	126.74 F	*- F
23	1		*WHEEL DISC	Serviceable	1,484.20 F	*- F
24	1		*WHEEL HUB REAR	Serviceable	489.40 F	*- F
25	1		*BUMPER REAR	Serviceable	458.60 F	*- F
26	10		*BUMPER CLIPS	Serviceable	21.00 F	*- F
27	2		*PIXEL STICKER	Serviceable	120.00 F	*- F
28	1		*ANTENNA ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
29	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
30	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
31	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
32	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
33	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
34	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
35	1		*COVER ,OUTER MIRROR ,LH	Serviceable	107.40 F	*- F
36	1		*FENDER PROTECTOR FRT/LH UPPER	Serviceable	46.10 F	*- F
37	1		*PROTECTOR FRONT FENDER SIDE PANEL LH	Serviceable	114.50 F	*- F
38	1		*FENDER LINER FRT/LH	Serviceable	171.70 F	*- F
39	1		*FENDER LINER PAD,FR WHEEL ,LH	Serviceable	49.30 F	*- F
40	1		*WHEEL DISC,FRONT	Serviceable	1,484.20 F	*- F
41	1		*TYRE	Serviceable	126.74 F	*- F
42	1		*WHEEL HUB FRT	Serviceable	549.70 F	*- F
43	1		*MOULDING BODY ,LH	Serviceable	673.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
44	1		*DOOR GLASS RR/LH	Serviceable	420.30 F	*- F	
45	1		*SEAL REAR DOOR REAR GUIDE LH	Serviceable	88.90 F	*- F	
46	1		*SCUFF STEP PLATE LH ,RR DR	Serviceable	107.49 F	*- F	
47	1		*FENDER RR/LH	Serviceable	766.80 F	*- F	
48	1		*SMRT LOGO	Serviceable	7.80 F	*- F	
49	1		*STICKER DECAL 65558888	Serviceable	21.60 F	*- F	
50	1		*DOOR FRT/LH	Repair	894.40 F	*- F	
51	1		*FENDER FRT/LH	Repair	723.40 F	*- F	
52	1		*DOOR RR/LH	Repair	954.50 F	*- F	
53	1		*ADVERTISEMENT STICKER (SN)	Necessary	742.20 F	*445.32 F	
54	1		*SOLAR FILM	Not Necessary	125.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>16,352.27</b>	<b>604.24</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	2,790.00	600.00
3	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
4	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
5	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
6	TO DO WHEEL ALIGNMENT/TYRE BALANCING	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	20.00
8	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
10	TOWING CHARGE	New	84.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>4,270.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >