

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000681/T1BA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800139638

Claimant
Vehicle No : SKU6502M **Insured Vehicle No :** SMF7527R

Date of Loss: 09/01/2020 Nature of Claim: TP Claim No: 2801648384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU6502M**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX520616
 Reg. Date: 11/08/2015 (Man. Year: 2015) Chassis No: MR053REH104535663
 Colour: Blue Odometer: 321047 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
 Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,022.97	5,015.52	8,007.45	61.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,750.00	3,380.00	3,370.00	49.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	19,772.97	8,395.52	11,377.45	57.54
Approved Total (Overridden) (\$)		6,700.00		
(\$)	19,772.97	6,700.00	13,072.97	66.12
+ GST 7.00/7.00% (\$)	1,384.11	469.00	915.11	66.12
Nett Amount (\$)	21,157.08	7,169.00	13,988.08	66.12
+ Car Rental (9.0 x \$100.00/day) (\$)		900.00		
+ Doc/Search Fee (\$)		36.45		
Nett Liability (\$)		8,105.45		
Global Sum Settlement (\$)		8,100.00		

INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 10/01/2020 Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi
 Industrial Park
 Singapore 408934

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	822.25 FL	*655.70 FL
2	1		*BOOTLID EMBLEM LOGO	Necessary	69.00 FL	*69.00 FL
3	1		*BOOTLID EMBLEM -COROLLA	Necessary	46.00 FL	*46.00 FL
4	1		*BOOTLID EMBLEM -ALTIS	Necessary	50.60 FL	*50.60 FL
5	1		*BOOTLID CHROME GARNISH	Cracked	265.66 FL	*231.30 FL
6	2		*BOOTLID LICENCE PLATE LAMP	Not Necessary	72.40 FL	*- FL
7	2		*BOOTLID LAMP	Cracked	763.30 FL	*656.20 FL
8	2		*BOOTLID LAMP INNER SEAL	Necessary	56.00 FL	*56.00 FL
9	1		*BOOTLID LOCK	Bent	417.00 FL	*382.00 FL
10	1		*BOOTLID LOCK CATCH	Not Necessary	23.00 FL	*- FL
11	2		*BOOTLID HINGE	Repair	131.10 FL	*- FL
12	1		*BOOTLID INNER TRIM	Not Necessary	315.00 FL	*- FL
13	2		*BOOTLID STOPPER	Necessary	35.00 FL	*35.00 FL
14	1		*END PANEL	Bent	672.75 FL	*537.10 FL
15	1		*END PANEL TOP GARNISH	Deformed	241.50 FL	*200.30 FL
16	1		*REAR BUMPER	Deformed	557.75 FL	*557.75 FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	131.10 FL	*- FL
18	1		*REAR BUMPER BRACKET	N/S Deformed /O/SNot Necessary	149.50 FL	*74.75 FL
19	1		*REAR BUMPER RETAINER	N/S Deformed /O/SNot Necessary	119.60 FL	*59.80 FL
20	4		*REAR PDC SENSOR	Not Necessary	722.20 FL	*- FL
21	1		*REAR PDC SENSOR WIRE HARNESS	Not Necessary	438.15 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	454.25 FL	*386.70 FL
23	1		*REAR LH FENDER	Buckled	1,124.70 FL	*986.00 FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	809.60 FL	*- FL
25	1		*REAR WINDSCREEN MOULDING	Necessary	89.70 FL	*89.70 FL
26	1		*REAR SPARE TYRE	Repair	898.15 FL	*- FL
27	1		*SPARE TYRE TOP BOARD	Deformed	326.60 FL	*326.60 FL
28	1		*REAR TAILLAMP	Cracked	901.60 FL	*760.20 FL
29	1		*REAR LH TAILLAMP PANEL	Repair	450.80 FL	*- FL
30	1		*REAR RH TAILLAMP PANEL	Not Necessary	450.80 FL	*- FL
31	1		*REAR EXHAUST SILENCER	Not Necessary	1,059.15 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	46.00 FL	*- FL
33	1		*REAR EXHAUST MOUNTING	Not Necessary	40.00 FL	*- FL
34	1		*REAR NUMBER PLATE	Cut	70.00 FS	*45.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
36	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
37	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
38	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
39	1		*SET FLOOR INSULATOR	Not Necessary	120.00 FS	*- FS
40	1		*JOINT SEALANT	Necessary	100.00 FS	*60.00 FS
41	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
42	1		*FLOOR PANEL	Repair	992.50 FL	*- FL
43	1		*REAR LH CHASSIS FRAME	Repair	1,261.25 FL	*- FL
44	1		*SET REAR REVERSE SENSOR	Not Working	800.00 FS	*200.00 FS

F=Franchise part. S=SpocNett. L=ListItemDisc.

Sub Total (\$\$) 16,773.96 **6,555.70**
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,750.99 1,540.18

Total Parts (\$\$) 13,022.97 **5,015.52**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	70.00	30.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR EXHAUST	New	120.00	0.00
4	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
5	REMOVE AND REFIT FUEL TANK	New	150.00	60.00
6	REMOVE AND RENEW FLOOR INSULATOR	New	120.00	60.00
7	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
8	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
9	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	1,500.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	2,600.00	1,400.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	60.00
12	MOUNT VEHICLE ON BENCH FOR CHASSIS ALIGNMENT	New	500.00	0.00
Gross Labour Cost (\$\$)			6,750.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >