

ASS. REC. BY:

REF:

F02/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 88dc

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 4815 Yr Regn: 11. 17.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy PROJ C.G. 17P8Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 225749 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB31U X 0 3576160Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 1P5/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 9/1/20D.O.I. 10/1/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

First Capital

Kh



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLU 481 S

Finalized

Parts (a) Cost / List Price Items

\$ 5177.42 11,002.97

Plus/Less 25%

\$ 1294.36 2,750.74

Total of Cost / List

\$ 3883.06 8,252.23

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

\$ 700.00

Total Parts Cost

\$ 8,952.23

Labour

\$ 2000.00 2,000.00


Total

\$ 5883.06 12,442.23

NOT Authorized

Resurvey B4 paint

85883.06



The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

LKK

Survey conducted on

:

10/1/2020

at

10am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair :

07

day(s)

(c) Resurvey

:

Required / ~~Not Required~~

(d) Excess

:

\$

(e) Signature of surveyor

:

De

Date:

10/1/2020



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLU 481 S
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FUX03576160

Submit By : SERENGE
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Bu</i>	1	\$450.80		<i>✓</i>
2	Front bumper clip <i>bu</i>	10	\$40.00		<i>✓</i>
3	Front bumper side retainer LH <i>CM</i>	1	\$107.20		<i>✓</i>
4	LH front fender <i>Bu</i>	1	\$868.70		<i>✓</i>
5	LH front fender undershield <i>CM</i>	1	\$195.60		<i>✓</i>
6	LH front fender undershield clip <i>bu</i>	10	\$25.00		<i>✓</i>
7	LHF fender wording "HYBRID" <i>bu</i>	1	\$44.17		<i>✓</i>
8	LH front rim <i>R</i>	1	\$1,555.10		<i>X</i>
	LH front tyre <i>bu</i>		\$250.00		<i>X</i>
	LH front hub cap <i>DC</i>	1	\$195.60		<i>✓</i>
11	LH side skirt <i>CM</i>	1	\$721.50		<i>✓</i>
12	LH front door <i>Red/warp</i>	1	\$1,121.75		<i>✓</i>
13	LH front door hinge top <i>R</i>	1	\$78.30		<i>✓</i>
14	LH front door hinge bottom <i>R</i>	1	\$78.30		<i>✓</i>
15	LH front door weatherstrip <i>bu</i>	1	\$211.69		<i>X</i>
16	LHF door glass outer moulding <i>bu</i>	1	\$122.95		<i>X</i>
17	LHF power window motor <i>bu</i>	1	\$543.25		<i>✓</i>
18	LHF power window regulator <i>R</i>	1	\$211.78		<i>✓</i>
19	LH rear door <i>Red/warp</i>	1	\$1,211.40		<i>✓</i>
20	LH rear door hinge top <i>R</i>	1	\$78.34		<i>X</i>
21	LH rear door hinge bottom <i>R</i>	1	\$78.34		<i>X</i>
22	LH rear door weatherstrip <i>bu</i>	1	\$198.70		<i>X</i>
23	LHR door glass outer moulding <i>bu</i>	1	\$107.80		<i>X</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

4481-77

195'65

ESTHEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

Labour

Vehicle No. : SLU 481 S

Submit By : SERENCE

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

2000