Adjuster Report Page 1 of 5

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000689/AEA3Q2

**Date:** 20/08/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SMA1634E Insured Vehicle No: SJG9789T

Date of Loss: 07/01/2020 Nature of Claim: TP Claim No: 4006859204SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMA1634E

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR5218631

Reg. Date: 30/05/2018 (Man. Year: 2018) Chassis No: MR2B23F3401121929

Colour: Silver Odometer: 51068 km

Engine Capacity: 1496 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,552.60	1,436.35	2,116.25	59.57
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,380.00	1,110.00	1,270.00	53.36
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	5,932.60	2,546.35	3,386.25	57.08
	+ GST 7.00/7.00% (S\$)	415.28	178.24	237.04	57.08
	Nett Amount (S\$)	6,347.88	2,724.59	3,623.29	57.08
	+ Loss of Use (5.0 x S\$	100.00/day) (S\$)	500.00		
	+ Doc	/Search Fee (S\$)	2.00		
	N	Nett Liability (S\$)	3,226.59		

**INSPECTION** 

Date of Assignment: 09/01/2020

Date Inspected: 09/01/2020 Inspected At: Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

### SPECIAL REMARKS

THIRD PARTY TRAINING VEHICLE

Adjuster Report Page 4 of 5

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	582.70 FL	*582.70 FL	
2	1		*REAR BUMPER REINFORCEMENT	Bent	316.10 FL	*316.10 FL	
3	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	287.20 FL	*-FL	
4	2		*REAR BUMPER SMALL RETAINERS	Not Necessary	137.60 FL	*-FL	
5	1		*BOOT LID	Repair	758.70 FL	*-FL	
6	1		*BOOT LID LOGO	Necessary	52.50 FL	*52.50 FL	
7	1		*BOOT LID VIOS EMBLEM	Necessary	43.60 FL	*43.60 FL	
8	1		*BOOT LID E EMBLEM	Necessary	38.30 FL	*38.30 FL	
9	1		*BOOT LID RUBBER	Cut	166.40 FL	*166.40 FL	
10	1		*BOOT LID LOCK	Not Necessary	360.40 FL	*-FL	
11	1		*BOOT LID LOCK CHECKER	Not Necessary	29.90 FL	*- FL	
12	1		*TAIL LAMP -RH	Not Necessary	357.10 FL	*- FL	
13	1		*REAR PANEL	Repair	720.10 FL	*-FL	
14	1		*REAR PANEL TRIM	Deformed	262.20 FL	*262.20 FL	
15	2		*L PLATE BRACKET	Necessary	70.00 FS	*70.00 FS	
16	1		*SET REAR BUMPER STICKER	Necessary	195.00 FS	*195.00 FS	
17	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS	
18	1		*BOOT LID 609 STICKER	Necessary	35.00 FS	*35.00 FS	
19	1		*SET REAR FENDER TRIM CLIPS	Not Necessary	40.00 FS	*-FS	
20	1		*SET BOOTLID TRIM CLIPS	Not Necessary	40.00 FS	*-FS	
21	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS	
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.	_			
				Sub Total (S\$)	4,580.80	1,801.80	
	- List Item Discount on L Items 25.00/25.00% (S\$) 1,028.20 365.4						
				Total Parts (S\$)	3,552.60	1,436.35	
	Report was unsubmitted during this print-out.						

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 20/8/2020

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,000.00	400.00
2	TO SPRAY PAINTING	New	1,000.00	600.00
3	TO SPRAY UNDERSEAL	New	100.00	50.00
4	TO REPLACE REAR INNER TRIM	New	150.00	30.00
5	TO CHECK WIRING	New	50.00	30.00
6	TO REPLACE STICKER	New	80.00	0.00
	Gross I	_abour Cost (S\$)	2,380.00	1,110.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.