

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000751/KEA3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMR504P

Insured Vehicle No : SMD5205T

Date of Loss: 23/12/2019

Nature of Claim: TP

Claim No: 1170442946SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR504P**

Make & Model: TOYOTA AQUA HYBRID, 1.5 E S CVT (A)

Engine No: 1NZR606782

Reg. Date: 17/12/2019 (Man. Year: 2017)

Chassis No: NHP106695002

Colour: Metallic Dark Blue

Odometer: 4621 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,281.29	2,197.59	83.70	3.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,830.00	470.00	20.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,581.29	4,027.59	553.70	12.09
+ GST 7.00/7.00% (\$\$)	320.69	281.93	38.76	12.09
Nett Amount (\$\$)	4,901.98	4,309.52	592.46	12.09
+ Car Rental (6.0 x S\$114.00/day) (\$\$)		684.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,995.52		

INSPECTION

Date of Assignment: 09/01/2020

Date Inspected: 09/01/2020 Inspected At:

9A SERANGOON NORTH AVE 5
SINGAPORE 554500

Repairer: Optima Werkz Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	619.75 FL	*619.75 FL
2	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	78.75 FL	*78.75 FL
3	1		*FRONT FENDER INNER LINER RH	Distorted	153.20 FL	*153.20 FL
4	10		*FRONT FENDER INNER LINER CLIPS RH	Necessary	58.00 FL	*58.00 FL
5	1		*FRONT DOOR RH	Bent	1,005.90 FL	*1,005.90 FL
6	1		*FRONT DOOR FRAME PROTECTIVE STICKER RH	Necessary	56.10 FL	*56.10 FL
7	10		*FRONT DOOR INNER TRIM CLIPS RH	Not Necessary	62.00 FL	*- FL
8	1		*REAR DOOR RH	Bent	902.30 FL	*902.30 FL
9	1		*REAR DOOR FRAME PROTECTIVE STICKER RH	Necessary	56.12 FL	*56.12 FL
10	8		*REAR DOOR INNER TRIM CLIPS RH	Not Necessary	49.60 FL	*- FL
11	1		*RUNNING BOARD PANEL RH (NPA)	Repair	0.00 FL	*- FL
12	1		*REAR QUARTER PANEL RH (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,041.72	2,930.12
- List Item Discount on L Items 25.00/25.00% (\$\$)	760.43	732.53
Total Parts (\$\$)	2,281.29	2,197.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST SIDE ACCIDENT AREAS & ETC	New	600.00	600.00
2	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC	New	100.00	60.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC	New	100.00	60.00
4	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER RH ,FRONT DOOR RH ,REAR DOOR RH ,REAR QUARTER PANEL RH ,RUNNING COARD PANEL RH & ETC	New	1,250.00	1,000.00
5	LABOUR CHARGES TO CHECK DOOR CETRAL LOCKING & ELECTRICAL WIRING SYSTEMS & ETC	New	100.00	20.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	90.00
Gross Labour Cost (\$\$)			2,300.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >