



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2100849

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/02/2021
Reference CC6/CTI20000756/Ura3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLA 7270T
Insured Veh. SV 8288T
Claim No. SNM20D200613/LKKDS
Policy No. DMPCSNA00020172001
Accident Date 09/01/2020
Inspection Date 13/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI20000756/Ura3q2	
			Date: 08/02/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SV 8288T	Veh. Inspected	SLA 7270T	
Policy No.	DMPCSN00020172001	Coverage (\$)	0.00	
Claim No.	SNM20D200613/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	13/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11112059	Colour	BLUE	
Odometer	104683 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R18	DUNLOP	6 mm	
L/H Front Tyre	225/45Z R18	DUNLOP	6 mm	
R/H Rear Tyre	225/45Z R18	DUNLOP	6 mm	
L/H Rear Tyre	225/45Z R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/01/2020	Inspection Date	13/01/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7270T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN MOULDING	NECESSARY	50.20	50.20
1	TAILGATE	BADLY DENTED	1,100.90	953.00
1	TAILGATE OUTER GARNISH	NOT NECESSARY	315.20	-
1	TAILGATE 'H' LOGO	NOT FITTED	32.50	-
1	TAILGATE 'VEZEL' EMBLEM	NOT FITTED	48.50	-
2	TAILGATE REFLECTORS @\$364.60	NOT NECESSARY	729.20	-
1	TAILGATE INNER LOCK	TWISTED	181.90	181.90
1	TAILGATE LOCK STRIKER	NOT NECESSARY	48.60	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	368.20	368.20
1	TAILGATE INNER HANDLE HOLDER	NOT NECESSARY	30.50	-
2	TAILGATE ABSORBERS @\$192.50	NOT NECESSARY	385.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	135.20	135.20
1	REAR BUMPER	DENTED	863.50	701.00
2	REAR BUMPER SIDES @\$295.80	N/S DEFORMED / TORN	591.60	295.80
2	REAR BUMPER REFLECTORS @\$151.00	N/S CRACKED	302.00	151.00
1	REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	REAR BUMPER UNDER COVER	TORN	158.40	158.40
1	SET REAR BUMPER UNDER COVER CLIPS	NECESSARY	45.00	45.00
2	REAR BUMPER SIDE RETAINERS @\$35.50	NOT NECESSARY	71.00	-
1	REAR END PANEL	DENTED / BENT	514.00	514.00
1	REAR END PANEL TOP GARNISH	TWISTED	86.40	86.40
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,330.20	-
1	REAR FLOOR PANEL TOP BOARD	TORN	326.90	326.90
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	485.30	485.30
2	TAILLAMPS @\$386.20	CRACKED	772.40	772.40
1	REAR LOCK SENSOR	SHORTED	259.20	259.20
2	REAR FENDERS @\$891.10	TO REPAIR SEE LABOUR	1,782.20	-
2	REAR FENDER INNER TRIMS @\$279.30	N/S TORN	558.40	279.30

Report Ref No. CC6/CTI20000756/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER	NOT NECESSARY	777.40	-
2	REAR EXHAUST MUFFLER MOUNTINGS @\$34.90	NOT NECESSARY	69.80	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	166.50	-
1	CENTRE EXHAUST PIPE	NOT NECESSARY	866.50	-
2	CENTRE EXHAUST PIPE MOUNTINGS @\$34.90	NOT NECESSARY	69.80	-
2	REAR FENDER OUTER PROTECTORS @\$172.40	TORN	344.80	344.80
	LESS 20% DISCOUNT		-	-1,230.60
			13,912.20	4,922.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE W/HOLDER (SN)	CRACKED	100.00	60.00
			510.00	350.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		100.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN .		150.00	120.00
	TO DISMANTLE & REFIX TAILGATE COMPONENTS .		100.00	60.00
	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY .		180.00	80.00
	TO DISMANTLE & REPLACING REAR EXHAUST .	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX PETROL TANK .	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING .		150.00	60.00
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND REAR FENDERS.		2,500.00	600.00
	TO PUTTY & SPRAY PAINTING .		2,000.00	1,000.00
	CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-
			5,840.00	2,000.00
	GRAND TOTAL		20,262.20	7,272.40

Report Ref No. CC6/CTI20000756/Ura3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,800.00
---	--	--	-----------------

Report Ref No. CC6/CTI20000756/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 7270T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 7270T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 7270T

RE-INSPECTION

