



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 4036A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (WCP)	DISTORTED	250.00	250.00
1	L/FASTENING CLIP (WCP)	NECESSARY	20.00	20.00
1	L/F BUMPER BRACKET (WCP)	CRACKED	10.00	10.00
1	L/F DRIVE SHAFT (WCP)	NOT NECESSARY	500.00	-
1	L/F SHOCK ABSORBER (WCP)	BENT	120.00	120.00
1	L/F STEERING KNUCKLE (WCP)	WARPED	160.00	160.00
1	L/F WHEEL BEARING (WCP)	NECESSARY	75.00	75.00
1	L/F WHEELHOUSE COVER (WCP)	TORN	50.00	50.00
1	L/F WING (WCP)	DISTORTED	165.00	165.00
1	L/LOWER CONTROL ARM (WCP)	BENT	150.00	150.00
1	LEFT HEADLAMP ASSY (WCP)	CRACKED	220.00	220.00
1	SCREW (WCP)	NOT NECESSARY	20.00	-
1	STEERING GEAR (WCP)	NOT NECESSARY	1,200.00	-
1	FRT LH ABS WIRE (WCP)	CRACKED	195.00	195.00
	COST PLUS 10%		313.50	141.50
			3,448.50	1,556.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRY PARTS CLIPS (SN)	NECESSARY	58.80	31.13
1	FRONT SPORT RIM LH (SN)	NECESSARY	250.00	250.00
			308.80	281.13
<b><u>LABOUR</u></b>				
	TOTAL PAINT LABOUR.		328.50	238.50
	TOTAL PAINT MATERIALS.		136.43	132.23
	TOTAL PANEL/MECHANICAL LABOUR.		445.50	202.50
			-	-
			-	-
			-	-
			910.43	573.23
<b>GRAND TOTAL</b>			<b>4,667.73</b>	<b>2,410.86</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00
---	--	--	----------

Report Ref No. CC4/FCI20000760/Uka3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.