




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20000760/Uka3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2020		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 923B	Veh. Inspected	SKC 4036A	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20000171MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	10/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CERATO FORTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KNAFW411MB5459830	Colour	BLACK	
Odometer	318119	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	TOYO	6 mm	
L/H Front Tyre	225/45 R17	TOYO	6 mm	
R/H Rear Tyre	225/45 R17	TOYO	6 mm	
L/H Rear Tyre	225/45 R17	TOYO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/01/2020	Inspection Date	10/01/2020	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		