

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20000762/T1SD3E2

**Date:** 09/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100453526-04
<b>Claimant Vehicle No :</b> SLN1893S	<b>Insured Vehicle No :</b>	SLA4484M
Date of Loss: 15/11/2019	Nature of Claim: TP	Claim No: 8191083875SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLN1893S</b>	Engine No:	1ZRY331113
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104557517
Reg. Date:	26/04/2017 (Man. Year: 2016)	Odometer:	218425 km
Colour:	Black	Engine Capacity:	1598 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	<b>Market Value/New Car Price</b>

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	751.00	398.25	352.75	46.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	400.00	50.00	11.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,201.00</b>	<b>798.25</b>	<b>402.75</b>	<b>33.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>650.00</b>		
<b>Nett Amount (S\$)</b>	<b>1,201.00</b>	<b>650.00</b>	<b>551.00</b>	<b>45.88</b>

### INSPECTION

Date of Assignment:	10/01/2020	
Date Inspected:	14/01/2020 Inspected At:	Blk 753 Woodlands Circle #11-556 Repairer : Ng Motor Vehicle Spray Painting (HQ)
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		<b>*BUMPER</b>	Deformed	531.00 F	*531.00 FL	
2	2		<b>*SENSORS</b>	Not Necessary	220.00 F	*- FL	
					<b>Sub Total (S\$)</b>	<b>751.00</b>	<b>531.00</b>
					<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	0.00	132.75
					<b>Total Parts (S\$)</b>	<b>751.00</b>	<b>398.25</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND FIXING	New	250.00	200.00
2	SPRAY PAINTING	New	200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>450.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >