

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20000763/UKA3Q2**Date:** 08/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900151093
Claimant
Vehicle No : SGF3306J **Insured Vehicle No :** GBE723Y
Date of Loss: 11/01/2020 Nature of Claim: TP Claim No: 4227327714SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF3306J**
Make & Model: NISSAN LATIO, 1.5 L T (A) Engine No: HR15140019
Reg. Date: 07/04/2006 (Man. Year: 2005) Chassis No: SC11028016
Colour: Silver Odometer: 333705 km
Engine Capacity: 1498 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,751.40	3,986.44	6,764.96	62.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,180.00	2,040.00	48.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,971.40	6,166.44	8,804.96	58.81
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	14,971.40	4,200.00	10,771.40	71.95
+ GST 7.00/7.00% (S\$)	1,048.00	294.00	754.00	71.95
Nett Amount (S\$)	16,019.40	4,494.00	11,525.40	71.95
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,796.00		

INSPECTION

Date of Assignment: 13/01/2020
Date Inspected: 13/01/2020 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	787.50 F	*787.50 FL
2	1		*BOOTLID REAR LOGO	Necessary	59.70 F	*50.70 FL
3	1		*BOOTLID LATIO EMBLEM	Necessary	73.60 F	*73.60 FL
4	1		*BOOTLID OUTER GARNISH	Bent / Cracked	280.60 F	*280.60 FL
5	1		*BOOTLID INNER LOCK	Twisted	109.00 F	*109.00 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	97.20 F	*97.20 FL
7	1		*BOOTLID INNER TRIM	Not Necessary	266.00 F	*- FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	35.00 F	*- FL
9	1		*REAR BUMPER	Distorted	456.30 F	*456.30 FL
10	1		*REAR BUMPER LOWER SKIRTING	Deformed / Torn	580.00 F	*554.60 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	73.20 F	*- FL
12	1		*REAR BUMPER BRACKETS	N/S Dented	130.00 F	*65.00 FL
13	1		*REAR BUMPER SPONGE	Torn	68.50 F	*68.50 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
15	1		*REAR END PANEL	Badly Dented	477.80 F	*434.40 FL
16	1		*REAR END PANEL TOP GARNISH	Cracked	288.00 F	*92.40 FL
17	1		*REAR END PANEL LOCK SENSOR	Not Necessary	265.00 F	*- FL
18	2		*TAILLAMPS	Cracked	610.00 F	*556.80 FL
19	2		*TAILLAMP HOUSING PANELS	Repair	530.00 F	*- FL
20	1		*REAR FLOOR PANEL	Repair	1,140.00 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Cracked	495.00 F	*495.00 FL
22	2		*REAR FENDERS	Repair	2,290.00 F	*- FL
23	2		*REAR FENDER INNER TRIMS	Not Necessary	576.00 F	*- FL
24	1		*REAR EXHAUST	Not Necessary	513.00 F	*- FL
25	2		*REAR EXHAUST MOUNTINGS	Not Necessary	70.00 F	*- FL
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
28	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,751.40	4,401.60
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	415.16
Total Parts (\$)	10,751.40	3,986.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	80.00	0.00
4	TO DISMANTLE & REFIX PETROL TANK	New	80.00	0.00
5	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	100.00	80.00
8	TO SPRAY RUST PROOFING	New	150.00	60.00
9	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	800.00
11	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
			Gross Labour Cost (\$\$)	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >