Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000772/KKA3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800035694-01 Claimant SJW5706A Insured Vehicle No: SDQ905C

Vehicle No:

Date of Loss: 07/01/2020 Nature of Claim: TP Claim No: 6025893292SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJW5706A Reg No:

Make & Model: HONDA CIVIC, 1.6 5AT (A) Engine No: R16A14001739 Chassis No: Reg. Date: 31/03/2010 (Man. Year: 2008) JHMFD46209S200533 Odometer: 180398 km

Colour: Metallic Silver

Engine Capacity: 1595 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16 Front Left Side: Toyo 6 mm Rear Left Side: Michelin 2 mm Front Right Side: Toyo 6 mm Rear Right Side: Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,232.32	1,570.48	1,661.84	51.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	770.00	850.00	52.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,852.32	2,340.48	2,511.84	51.77
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	4,852.32	1,850.00	3,002.32	61.87
+ GST 7.00/7.00% (S\$)	339.66	129.50	210.16	61.87
Nett Amount (S\$)	5,191.98	1,979.50	3,212.48	61.87
+ Loss of Use (3.0 x S\$5	50.00/day) (S\$)	150.00		
+ Doc/Se	earch Fee (S\$)	2.00		
Net	tt Liability (S\$)	2,131.50		

INSPECTION

Date of Assignment: 13/01/2020

Date Inspected: 14/01/2020 Inspected At: Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	O/S Cut	1,806.40 FL	*903.20 FL
2	2		*FRONT HEADLAMP LOWER BRACKET	Serviceable	117.70 FL	*- FL
3	1		*FRONT CENTRE GRILLE BASE	Mtg Cracked	336.40 FL	*336.40 FL
4	1		*FRONT CENTRE GRILLE CHROME	Serviceable	282.50 FL	*- FL
5	1		*FRONT CENTRE GRILLE HONDA LOGO	Serviceable	58.50 FL	*- FL
6	1		*FRONT BUMPER	Buckled / Cracked	638.00 FL	*638.00 FL
7	10		*FRONT BUMPER CLIP	Necessary	37.00 FL	*37.00 FL
8	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	97.00 FL	*48.50 FL
9	1		*FRONT BUMPER GRILLE	Serviceable	125.50 FL	*- FL
10	1		*FRONT BUMPER RH SIDE COVER	Serviceable	150.50 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Repair	328.40 FL	*- FL
12	1		*SET FRONT NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	4,027.90	1,963.10
	- List Item Discount on L Items 20.00/20.00% (S\$)				795.58	392.62
				Total Parts (S\$)	3,232.32	1,570.48

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TOWING	New	60.00	50.00				
2	WIRING	New	80.00	20.00				
3	TUFF KOTE	New	80.00	0.00				
4	SPRAY PAINTING	New	600.00	400.00				
5	LABOUR CHARGES	New	800.00	300.00				
		Gross Labour Cost (S\$)	1,620.00	770.00				

Report was unsubmitted during this print-out.

< END OF ESTIMATES >