

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000781/HKS3Q2

**Date:** 28/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100416703

**Claimant**  
**Vehicle No :** SLQ3215X **Insured Vehicle No :** SKU258H

Date of Loss: 10/01/2020 Nature of Claim: TP Claim No: 1046706321SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLQ3215X</b>		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Engine No:	2ZR8090194
Reg. Date:	04/07/2017 (Man. Year: 2017)	Chassis No:	ZYX102033653
Colour:	White	Odometer:	324556 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R16	Rear Tyre Size:	225/50 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,521.77	3,679.30	13,842.47	79.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	1,430.00	2,670.00	65.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>21,621.77</b>	<b>5,109.30</b>	<b>16,512.47</b>	<b>76.37</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,100.00</b>		
<b>(\$\$)</b>	21,621.77	4,100.00	17,521.77	81.04
<b>+ GST 7.00/7.00% (\$\$)</b>	1,513.52	287.00	1,226.52	81.04
<b>Nett Amount (\$\$)</b>	<b>23,135.29</b>	<b>4,387.00</b>	<b>18,748.29</b>	<b>81.04</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 10/01/2020 Inspected At: Stk Auto (s) Pte Ltd (HQ)  
8 kaki bukit ave4, #03-21  
Singapore 415875

Estimated Period of Repair: 5.0 days

**Adjuster:** LEE HOCK ANN

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	3,800.00 FL	*930.50 FL
2	1		*FRONT BUMPER RETAINER RH	Serviceable	60.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER LH	Crumpled	60.00 FL	*60.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,500.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Serviceable	250.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GARNISH CENTRE	Serviceable	550.00 FL	*- FL
7	1		*FRONT BUMPER LOWER LH (LIP)	Cracked	280.00 FL	*280.00 FL
8	1		*FRONT BUMPER TOP GARNISH	Serviceable	250.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Repair	1,600.00 FL	*- FL
10	1		*BONNET	Repair	2,500.00 FL	*- FL
11	1		*LH HEADLAMP (ASSY)	Cracked	3,800.00 FL	*1,955.20 FL
12	1		*BONNET LOGO	Not Necessary	185.00 FL	*- FL
13	1		*LH HEADLAMP ECU	Not Necessary	1,800.00 FL	*- FL
14	1		*LH HEADLAMP PANEL	Repair	450.00 FL	*- FL
15	1		*LH FRONT FENDER	Bent	1,800.00 FL	*600.50 FL
16	1		*LH FRONT FENDER INNER SHIELD	Serviceable	455.00 FL	*- FL
17	1		*FORNT GRILLE & CHROME	Serviceable	1,900.00 FL	*- FL
18	1		*FRONT BUMPER DRY RUNNING LIGHT LH	Missing	450.00 FL	*230.50 FL
19	1		*LH FRONT BUMPER SENSOR	Shorted	650.00 FL	*100.00 FL
20	1		*LH FRONT FENDER WHEEL HOUSE GARNISH	Crumpled	155.70 FL	*155.70 FL
21	10		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	100.00 FS	*20.00 FS
22	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*25.00 FS
23	1		*LH FRONT SPORT RIM	Scratched	450.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>23,145.70</b>	<b>4,757.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	5,623.93	1,078.10
<b>Total Parts (\$\$)</b>	<b>17,521.77</b>	<b>3,679.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR TO FACILITATE REPAIR	New	2,500.00	700.00
2	R&R REAR FRONT SUPPORT CAP COMPARTMENT	New	250.00	0.00
3	RUST PROOF ON AFFECTED AREAS	New	150.00	30.00
4	TO SPRAY PAINT BONNET }	New	250.00	700.00
5	TO SPRAY PAINT FRONT BUMPER }	New	250.00	0.00
6	TO SPRAY PAINT FRONT FENDER LH }	New	250.00	0.00
7	TO SPRAY PAINT FRONT BUMPER REINFORCEMENT }	New	250.00	0.00
8	TO SPRAY PAINT FRONT SUPPORT PANEL }	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,100.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >