

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20000785/AGYD3E2  
**Date:** 08/04/2020

**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 1000890478
<b>Claimant Vehicle No :</b> JLG3287	<b>Insured Vehicle No :</b> SKP5738H
Date of Loss: 11/01/2020	Nature of Claim: TP <span style="float: right;">Claim No: 237330</span>

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: <b>JLG3287</b>	Engine No: R18A11933267
Make & Model: HONDA CIVIC, 1.8 L (A)	Chassis No: PMHFD16308D303296
Reg. Date: 29/10/2008 (Man. Year: 2008)	Odometer: 125695 km
Colour: Black	Engine Capacity: 1799 cc
Market Value/New Car Price: N/A	Sum Insured (S\$): <b>Market Value/New Car Price</b>

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40 R18	Rear Tyre Size: 225/40 R18
Front Left Side: Presa 6 mm	Rear Left Side: Presa 6 mm
Front Right Side: Presa 6 mm	Rear Right Side: Presa 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,498.56	3,205.57	5,292.99	62.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,600.00	1,260.00	32.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,358.56</b>	<b>5,805.57</b>	<b>6,552.99</b>	<b>53.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,358.56</b>	<b>4,600.00</b>	<b>7,758.56</b>	<b>62.78</b>

**INSPECTION**

Date of Assignment: 15/01/2020	Inspected At: Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883
Date Inspected: 13/01/2020	
Estimated Period of Repair: 7.0 days	

**Adjuster:** XING GUO QIANG **Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Apr 2020)
<b>Parts:</b> 143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> LKK Auto Consultants Pte Ltd/JLG3287/08/04/2020 11:29	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	621.40 F	*621.40 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	96.00 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	35.00 F	*35.00 FL
4	1		*REAR BOOT LID CIVIC LOGO	Necessary	38.80 F	*38.80 FL
5	1		*REAR BOOT LID 1.8 LOGO	Necessary	32.00 F	*32.00 FL
6	1		*REAR BOOT LID IVTEC LOGO	Necessary	36.10 F	*36.10 FL
7	1		*REAR BOOT LID SIDE REFLECTOR	O/S Cut	404.40 F	*202.20 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.20 F	*- FL
10	1		*REAR BOOT LID INNER LOCK	Damaged	194.50 F	*194.50 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	137.60 F	*137.60 FL
12	2		*REAR TAIL LAMP	Cracked	657.40 F	*657.40 FL
13	4		*REAR TAIL LAMP CLIP	Necessary	26.00 F	*26.00 FL
14	1		*REAR BUMPER	Deformed	645.30 F	*645.30 FL
15	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	66.20 F	*66.20 FL
17	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
18	2		*REAR BUMPER BRACKET	Not Necessary	55.20 F	*- FL
19	1		*REAR END PANEL	Dented	318.30 F	*318.30 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	161.20 F	*161.20 FL
21	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	465.60 F	*- FL
22	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
23	1		*REAR SPARE TYRE PANEL	Repair	1,254.40 F	*- FL
24	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	329.96 F	*329.96 FL
25	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Necessary	450.00 FS	*180.00 FS
26	1		*REAR EXHAUST	Repair	728.50 F	*- FL
27	2		*REAR EXHAUST CHROME PIPE	Not Necessary	372.00 FS	*- FS
28	1		*REAR CENTER EXHAUST	Not Necessary	637.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,498.56</b>	<b>3,911.96</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	706.39
<b>Total Parts (S\$)</b>	<b>8,498.56</b>	<b>3,205.57</b>

LKK Auto Consultants Pte Ltd/JLG3287/08/04/2020 11:29. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT REAR CUSHION	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR EXHAUST	New	280.00	80.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	60.00
6	TOWING FEE	New	150.00	0.00
7	PANEL BEATING	New	1,400.00	1,200.00
8	SPRAY PAINTING	New	1,400.00	1,100.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,860.00</b>
				<b>2,600.00</b>

LKK Auto Consultants Pte Ltd/JLG3287/08/04/2020 11:29. Not valid without Reference section.

< END OF ESTIMATES >