

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jan 2020 Edit Reg		13 Jan 2020 00:00 Edit Adj Rpt	S\$17,000.00 Edit Estimates	S\$17,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Yip Wai Mun , ID: S7206602B									
Main Claimant: LEE MEOW CHENG , ID: S0225295C									
Vehicle Reg. No.: SLJ1759T		Date of Loss: 11/01/2020 00:00 - :59 [37 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1202000002354		Policy/Cover Note No.: PNPV2018-00001060-01 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): EQ7979G		Policy No. (Claimant):							
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/01/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- FWD_SG (10/09/2020): Alert - Adj Mandate Approved (S\$18897.45) - SLJ1759T - Claim Handler: Josey Loh - FWD_SG (02/09/2020): Alert - Adj Mandate Maintained - SLJ1759T - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ1759T (1202000002354)**

[EQ7979G]

TP

LEE MEOW CHENG

Jan 11 2020 12:00AM

[Yip Wai Mun]

Fastech Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Letters/Correspondences

1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/09/20 08:48	Odometer Reading		Load JPG
2	03/09/20 08:49	Chassis Number		Load JPG
3	03/09/20 08:49	General View		Load JPG
4	03/09/20 08:49	General View		Load JPG
5	03/09/20 08:49	General View		Load JPG
6	03/09/20 08:49	General View		Load JPG
7	03/09/20 08:49	General View		Load JPG
8	03/09/20 08:49	General View		Load JPG
9	03/09/20 08:49	General View		Load JPG
10	03/09/20 08:49	General View		Load JPG
11	03/09/20 08:49	General View		Load JPG
12	03/09/20 08:49	General View		Load JPG
13	03/09/20 08:49	General View		Load JPG
14	03/09/20 08:49	General View		Load JPG
15	03/09/20 08:49	General View		Load JPG
16	03/09/20 08:49	General View		Load JPG
17	03/09/20 08:49	General View		Load JPG
18	03/09/20 08:49	General View		Load JPG
19	03/09/20 08:49	General View		Load JPG
20	03/09/20 08:49	General View		Load JPG
21	03/09/20 08:49	General View		Load JPG
22	03/09/20 08:49	General View		Load JPG
23	03/09/20 08:49	General View		Load JPG
24	03/09/20 08:49	General View		Load JPG
25	03/09/20 08:49	General View		Load JPG
26	03/09/20 08:49	General View		Load JPG
27	03/09/20 08:50	General View		Load JPG
28	03/09/20 08:50	General View		Load JPG
29	03/09/20 08:50	General View		Load JPG
30	03/09/20 08:50	General View		Load JPG
31	03/09/20 08:50	General View		Load JPG
32	03/09/20 08:50	General View		Load JPG
33	03/09/20 08:50	General View		Load JPG
34	03/09/20 08:50	General View		Load JPG
35	03/09/20 08:50	General View		Load JPG
36	03/09/20 08:50	General View		Load JPG
37	03/09/20 08:50	General View		Load JPG

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	03/09/20 08:50	General View		Load JPG	☒
39	03/09/20 08:50	General View		Load JPG	☒
40	03/09/20 08:50	General View		Load JPG	☒
41	03/09/20 08:50	General View		Load JPG	☒
42	03/09/20 08:50	General View		Load JPG	☒
43	03/09/20 08:50	General View		Load JPG	☒
44	03/09/20 08:50	General View		Load JPG	☒
45	03/09/20 08:50	General View		Load JPG	☒
46	03/09/20 08:50	General View		Load JPG	☒
47	03/09/20 08:50	General View		Load JPG	☒
48	03/09/20 08:50	General View		Load JPG	☒
49	03/09/20 08:50	General View		Load JPG	☒
50	03/09/20 08:50	General View		Load JPG	☒
51	03/09/20 08:50	General View		Load JPG	☒
52	03/09/20 08:50	General View		Load JPG	☒
53	03/09/20 08:50	General View		Load JPG	☒
54	03/09/20 08:50	General View		Load JPG	☒
55	03/09/20 08:50	General View		Load JPG	☒
56	03/09/20 08:50	General View		Load JPG	☒
57	03/09/20 08:50	General View		Load JPG	☒
58	03/09/20 08:50	General View		Load JPG	☒
59	03/09/20 08:50	General View		Load JPG	☒
60	03/09/20 08:50	General View		Load JPG	☒
61	03/09/20 08:50	General View		Load JPG	☒
62	03/09/20 08:50	General View		Load JPG	☒
63	03/09/20 08:50	General View		Load JPG	☒
64	03/09/20 08:50	General View		Load JPG	☒
65	03/09/20 08:50	General View		Load JPG	☒
66	03/09/20 08:50	General View		Load JPG	☒
67	03/09/20 08:50	General View		Load JPG	☒
68	03/09/20 08:50	General View		Load JPG	☒
69	03/09/20 08:50	General View		Load JPG	☒
70	03/09/20 08:50	General View		Load JPG	☒
71	03/09/20 08:50	General View		Load JPG	☒
72	03/09/20 08:50	General View		Load JPG	☒
73	03/09/20 08:50	General View		Load JPG	☒
74	03/09/20 08:50	General View		Load JPG	☒
75	03/09/20 08:50	General View		Load JPG	☒
76	03/09/20 08:50	General View		Load JPG	☒
77	03/09/20 08:50	General View		Load JPG	☒
78	03/09/20 08:50	General View		Load JPG	☒
79	03/09/20 08:50	General View		Load JPG	☒
80	03/09/20 08:50	General View		Load JPG	☒
81	03/09/20 08:50	General View		Load JPG	☒
82	03/09/20 08:51	General View		Load JPG	☒
83	03/09/20 08:51	General View		Load JPG	☒
84	03/09/20 08:51	General View		Load JPG	☒
85	03/09/20 08:51	General View		Load JPG	☒
86	03/09/20 08:51	General View		Load JPG	☒
87	03/09/20 08:51	General View		Load JPG	☒
88	03/09/20 08:51	General View		Load JPG	☒
89	03/09/20 08:51	General View		Load JPG	☒
90	03/09/20 08:51	General View		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
91	03/09/20 08:51	General View		Load JPG	☒
92	03/09/20 08:51	General View		Load JPG	☒
93	03/09/20 08:51	General View		Load JPG	☒
94	03/09/20 08:51	General View		Load JPG	☒
95	03/09/20 08:51	General View		Load JPG	☒
96	03/09/20 08:51	General View		Load JPG	☒
97	03/09/20 08:51	General View		Load JPG	☒
98	03/09/20 08:51	General View		Load JPG	☒
99	03/09/20 08:51	General View		Load JPG	☒
100	03/09/20 08:51	General View		Load JPG	☒
101	03/09/20 08:51	General View		Load JPG	☒
102	03/09/20 08:51	General View		Load JPG	☒
103	03/09/20 08:51	General View		Load JPG	☒
104	03/09/20 08:51	General View		Load JPG	☒
105	03/09/20 08:53	Reinspection Photo		Load JPG	☒
106	03/09/20 08:53	Reinspection Photo		Load JPG	☒
107	03/09/20 08:53	Reinspection Photo		Load JPG	☒
108	03/09/20 08:53	Reinspection Photo		Load JPG	☒
109	03/09/20 08:53	Reinspection Photo		Load JPG	☒
110	03/09/20 08:53	Reinspection Photo		Load JPG	☒
111	03/09/20 08:53	Reinspection Photo		Load JPG	☒
112	03/09/20 08:53	Reinspection Photo		Load JPG	☒
113	03/09/20 08:53	Reinspection Photo		Load JPG	☒
114	03/09/20 08:53	Reinspection Photo		Load JPG	☒
115	03/09/20 08:53	Reinspection Photo		Load JPG	☒
116	03/09/20 08:53	Reinspection Photo		Load JPG	☒
117	03/09/20 08:53	Reinspection Photo		Load JPG	☒
118	03/09/20 08:53	Reinspection Photo		Load JPG	☒
119	03/09/20 08:53	Reinspection Photo		Load JPG	☒
120	03/09/20 08:53	Reinspection Photo		Load JPG	☒
121	03/09/20 08:53	Reinspection Photo		Load JPG	☒
122	03/09/20 08:53	Reinspection Photo		Load JPG	☒
123	03/09/20 08:53	Reinspection Photo		Load JPG	☒
124	03/09/20 08:53	Reinspection Photo		Load JPG	☒
125	03/09/20 08:53	Reinspection Photo		Load JPG	☒
126	03/09/20 08:53	Reinspection Photo		Load JPG	☒
127	03/09/20 08:53	Reinspection Photo		Load JPG	☒
128	03/09/20 08:53	Reinspection Photo		Load JPG	☒
129	03/09/20 08:53	Reinspection Photo		Load JPG	☒
130	03/09/20 08:53	Reinspection Photo		Load JPG	☒
131	03/09/20 08:53	Reinspection Photo		Load JPG	☒
132	03/09/20 08:53	Reinspection Photo		Load JPG	☒
133	03/09/20 08:53	Reinspection Photo		Load JPG	☒
134	03/09/20 08:53	Reinspection Photo		Load JPG	☒
135	03/09/20 08:53	Reinspection Photo		Load JPG	☒
136	03/09/20 08:53	Reinspection Photo		Load JPG	☒
137	03/09/20 08:53	Reinspection Photo		Load JPG	☒
138	03/09/20 08:53	Reinspection Photo		Load JPG	☒
139	03/09/20 08:53	Reinspection Photo		Load JPG	☒
140	03/09/20 08:53	Reinspection Photo		Load JPG	☒
141	03/09/20 08:53	Reinspection Photo		Load JPG	☒
142	03/09/20 08:53	Reinspection Photo		Load JPG	☒
143	03/09/20 08:53	Reinspection Photo		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
144	03/09/20 08:53	Reinspection Photo		Load JPG	☒
145	03/09/20 08:53	Reinspection Photo		Load JPG	☒
146	03/09/20 08:53	Reinspection Photo		Load JPG	☒
147	03/09/20 08:53	Reinspection Photo		Load JPG	☒
148	03/09/20 08:53	Reinspection Photo		Load JPG	☒
149	03/09/20 08:54	Reinspection Photo		Load JPG	☒
150	03/09/20 08:54	Reinspection Photo		Load JPG	☒
151	03/09/20 08:54	Reinspection Photo		Load JPG	☒
152	03/09/20 08:54	Reinspection Photo		Load JPG	☒
153	03/09/20 08:54	Reinspection Photo		Load JPG	☒
154	03/09/20 08:54	Reinspection Photo		Load JPG	☒
155	03/09/20 08:54	Reinspection Photo		Load JPG	☒
156	03/09/20 08:54	Reinspection Photo		Load JPG	☒
157	03/09/20 08:54	Reinspection Photo		Load JPG	☒
158	03/09/20 08:54	Reinspection Photo		Load JPG	☒
159	03/09/20 08:54	Reinspection Photo		Load JPG	☒
160	03/09/20 08:54	Reinspection Photo		Load JPG	☒
161	03/09/20 08:54	Reinspection Photo		Load JPG	☒
162	03/09/20 08:54	Reinspection Photo		Load JPG	☒
163	03/09/20 08:54	Reinspection Photo		Load JPG	☒
164	03/09/20 08:54	Reinspection Photo		Load JPG	☒
165	03/09/20 08:54	Reinspection Photo		Load JPG	☒
166	03/09/20 08:54	Reinspection Photo		Load JPG	☒
167	03/09/20 08:54	Reinspection Photo		Load JPG	☒
168	03/09/20 08:54	Reinspection Photo		Load JPG	☒
169	03/09/20 08:54	Reinspection Photo		Load JPG	☒
170	03/09/20 08:54	Reinspection Photo		Load JPG	☒
171	03/09/20 08:54	Reinspection Photo		Load JPG	☒
172	03/09/20 08:54	Reinspection Photo		Load JPG	☒
173	03/09/20 08:54	Reinspection Photo		Load JPG	☒
174	03/09/20 08:54	Reinspection Photo		Load JPG	☒
175	03/09/20 08:54	Reinspection Photo		Load JPG	☒
176	03/09/20 08:54	Reinspection Photo		Load JPG	☒
177	03/09/20 08:54	Reinspection Photo		Load JPG	☒
178	03/09/20 08:54	Reinspection Photo		Load JPG	☒
179	03/09/20 08:54	Reinspection Photo		Load JPG	☒
180	03/09/20 08:54	Reinspection Photo		Load JPG	☒
181	03/09/20 08:54	Reinspection Photo		Load JPG	☒
182	03/09/20 08:54	Reinspection Photo		Load JPG	☒
183	03/09/20 08:54	Reinspection Photo		Load JPG	☒
184	03/09/20 08:54	Reinspection Photo		Load JPG	☒
185	03/09/20 08:54	Reinspection Photo		Load JPG	☒
186	03/09/20 08:54	Reinspection Photo		Load JPG	☒
187	03/09/20 08:54	Reinspection Photo		Load JPG	☒
188	03/09/20 08:54	Reinspection Photo		Load JPG	☒
189	03/09/20 08:54	Reinspection Photo		Load JPG	☒
190	03/09/20 08:54	Reinspection Photo		Load JPG	☒
191	03/09/20 08:54	Reinspection Photo		Load JPG	☒
192	03/09/20 08:54	Reinspection Photo		Load JPG	☒
193	03/09/20 08:54	Reinspection Photo		Load JPG	☒
194	03/09/20 08:54	Reinspection Photo		Load JPG	☒
195	03/09/20 08:55	Reinspection Photo		Load JPG	☒
196	03/09/20 08:55	Reinspection Photo		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
197	03/09/20 08:55	Reinspection Photo		Load JPG	☒
198	03/09/20 08:55	Reinspection Photo		Load JPG	☒
199	03/09/20 08:55	Reinspection Photo		Load JPG	☒
200	03/09/20 08:55	Reinspection Photo		Load JPG	☒
201	03/09/20 08:55	Reinspection Photo		Load JPG	☒
202	03/09/20 08:55	Reinspection Photo		Load JPG	☒
203	03/09/20 08:55	Reinspection Photo		Load JPG	☒
204	03/09/20 08:55	Reinspection Photo		Load JPG	☒
205	03/09/20 08:55	Reinspection Photo		Load JPG	☒
206	03/09/20 08:55	Reinspection Photo		Load JPG	☒
207	03/09/20 08:55	Reinspection Photo		Load JPG	☒
208	03/09/20 08:55	Reinspection Photo		Load JPG	☒
209	03/09/20 08:55	Reinspection Photo		Load JPG	☒
210	03/09/20 08:55	Reinspection Photo		Load JPG	☒
211	03/09/20 08:55	Reinspection Photo		Load JPG	☒
212	03/09/20 08:55	Reinspection Photo		Load JPG	☒
213	03/09/20 08:55	Reinspection Photo		Load JPG	☒
214	03/09/20 08:55	Reinspection Photo		Load JPG	☒
215	03/09/20 08:55	Reinspection Photo		Load JPG	☒
216	03/09/20 08:55	Reinspection Photo		Load JPG	☒
217	03/09/20 08:55	Reinspection Photo		Load JPG	☒
218	03/09/20 08:55	Reinspection Photo		Load JPG	☒
219	03/09/20 08:55	Reinspection Photo		Load JPG	☒
220	03/09/20 08:55	Reinspection Photo		Load JPG	☒
221	03/09/20 08:55	Reinspection Photo		Load JPG	☒
222	03/09/20 08:55	Reinspection Photo		Load JPG	☒
223	03/09/20 08:55	Reinspection Photo		Load JPG	☒
224	03/09/20 08:55	Reinspection Photo		Load JPG	☒
225	03/09/20 08:55	Reinspection Photo		Load JPG	☒
226	03/09/20 08:55	Reinspection Photo		Load JPG	☒
227	03/09/20 08:55	Reinspection Photo		Load JPG	☒
228	03/09/20 08:55	Reinspection Photo		Load JPG	☒
229	03/09/20 08:55	Reinspection Photo		Load JPG	☒
230	03/09/20 08:55	Reinspection Photo		Load JPG	☒
231	03/09/20 08:55	Reinspection Photo		Load JPG	☒
232	03/09/20 08:55	Reinspection Photo		Load JPG	☒
233	03/09/20 08:55	Reinspection Photo		Load JPG	☒
234	03/09/20 08:55	Reinspection Photo		Load JPG	☒
235	03/09/20 08:55	Reinspection Photo		Load JPG	☒
236	03/09/20 08:55	Reinspection Photo		Load JPG	☒
237	03/09/20 08:55	Reinspection Photo		Load JPG	☒
238	03/09/20 08:55	Reinspection Photo		Load JPG	☒
239	03/09/20 08:55	Reinspection Photo		Load JPG	☒
240	03/09/20 08:55	Reinspection Photo		Load JPG	☒
241	03/09/20 08:55	Reinspection Photo		Load JPG	☒
242	03/09/20 08:55	Reinspection Photo		Load JPG	☒
243	03/09/20 08:56	Reinspection Photo		Load JPG	☒
244	03/09/20 08:56	Reinspection Photo		Load JPG	☒
245	03/09/20 08:56	Reinspection Photo		Load JPG	☒
246	03/09/20 08:56	After Repair Photo		Load JPG	☒
247	03/09/20 08:56	After Repair Photo		Load JPG	☒
248	03/09/20 08:56	After Repair Photo		Load JPG	☒
249	03/09/20 08:56	After Repair Photo		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
250	03/09/20 08:56	After Repair Photo		Load JPG	☒
251	03/09/20 08:56	After Repair Photo		Load JPG	☒
252	03/09/20 08:56	After Repair Photo		Load JPG	☒
253	03/09/20 08:56	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/01/20 17:38	ACKNOWLEDGEMENT EMAIL TO FWD DD13012020		Load PDF	
2	14/01/20 14:21	EMAIL - FWD TO OI DD 13.01.2020		Load PDF	
3	21/01/20 09:38	TP GIA REPORT		Load PDF	
4	17/02/20 09:15	TP ESTIMATE-MARKED		Load PDF	
5	02/09/20 12:56	ATA		Load PDF	
6	02/09/20 12:56	LOD		Load PDF	
7	02/09/20 12:56	RENTAL AGREEMENT		Load PDF	
8	02/09/20 12:56	RENTAL INVOICE		Load PDF	
9	02/09/20 12:56	SEARCH INVOICE		Load PDF	
10	02/09/20 12:56	TAX INVOICE		Load PDF	
11	02/09/20 12:56	TP FINAL EST LIST 1		Load PDF	
12	02/09/20 12:56	TP FINAL EST LIST 2		Load PDF	
13	02/09/20 12:56	TP FINAL EST LIST 3		Load PDF	
14	02/10/20 15:44	Release Voucher		Load PDF	
15	02/10/20 15:44	WORKSHOP INVOICE		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	25/03/20 17:19	E-filed GIA report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EQ7979G (Insd veh)	Model:	NISSAN QASHQAI 1.2 DIG-T
	SLJ1759T (TP veh)		CVT ABS 2WD 5DR (A)
Date of Accident:	11/01/2020		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	: \$	57,970.46	
Final Repair Cost	: \$	18,800.00	
Loss of Use	: \$	_____ days at \$0.00 per day	
Rental (if any)	: \$	7 days	
LTA / GIA Search Fee	: \$	_____	
Others:	: \$	_____	
	: \$	_____	
Final Settlement Sum (GLOBAL SUM)	: \$	18,800.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	: \$	18,800.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

02 Oct
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD20000788/UGS3S2**Date:** 02/10/2020REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00001060-01
Claimant Vehicle No : SLJ1759T **Insured Vehicle No :** EQ7979G
 Date of Loss: 11/01/2020 Nature of Claim: TP Claim No: 1202000002354

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ1759T**
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2307861A
 Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: SJNFEAJ11U1719293
 Colour: Silver Odometer: 82561 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,888.00	17,598.24	28,289.76	61.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,290.00	3,840.00	4,450.00	53.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	54,178.00	21,438.24	32,739.76	60.43
Approved Total (Overridden) (S\$)		17,000.00		
(S\$)	54,178.00	17,000.00	37,178.00	68.62
+ GST 7.00/7.00% (S\$)	3,792.46	1,190.00	2,602.46	68.62
Nett Amount (S\$)	57,970.46	18,190.00	39,780.46	68.62
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		18,897.45		
Global Sum Settlement (S\$)		18,800.00		

INSPECTION

Date of Assignment: 13/01/2020
 Date Inspected: 13/01/2020 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Oct 2020)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ1759T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,855.30 F	*- FN
2	1		*REAR WINDSCREEN MOULDING	Necessary	195.30 F	*195.30 FN
3	2		*REAR WINDSCREEN INNER SIDE GARNISH	Not Necessary	330.00 F	*- FN
4	1		*TAILGATE	Dented / Bent	3,066.20 F	*3,062.60 FN
5	1		*TAILGATE OUTER GARNISH	Not Necessary	450.00 F	*- FN
6	1		*TAILGATE REAR LOGO	Not Necessary	38.50 F	*- FN
7	1		*TAILGATE QASHQAI EMBLEM	Necessary	78.50 F	*78.50 FN
8	2		*TAILGATE REFLECTORS	Not Necessary	1,300.00 F	*- FN
9	1		*TAILGATE REAR WIER MOTOR	Not Necessary	966.00 F	*- FN
10	1		*TAILGATE REAR WIPER ARM	Not Necessary	315.00 F	*- FN
11	1		*TAILGATE REAR WIPER BLADE	Not Necessary	65.00 F	*- FN
12	1		*TAILGATE INNER LOCK	Shorted	292.00 F	*173.20 FN
13	1		*TAILGATE INNER TRIM BOARD	Not Necessary	595.30 F	*- FN
14	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 F	*- FN
15	1		*TAILGATE WEATHERSTRIP	Twisted	166.20 F	*166.20 FN
16	1		*TAILGATE REVERSE CAMERA	Not Necessary	485.00 F	*- FN
17	1		*TAILGATE INNER TOP BOARD	Not Necessary	492.30 F	*- FN
18	2		*TAILGATE LICENCE PLATE LAMPS	Not Necessary	106.00 F	*- FN
19	1		*REAR BUMPER	Distorted	891.00 F	*796.70 FN
20	1		*REAR BUMPER TOW COVER	Deformed	22.00 F	*22.00 FN
21	2		*REAR BUMPER REFLECTORS	Not Necessary	136.00 F	*- FN
22	2		*REAR BUMPER SIDE RETAINERS	Bent / Necessary	50.00 F	*50.00 FN
23	1		*REAR BUMPER REINFORCEMENT	Bent	721.00 F	*691.50 FN
24	2		*TAILLAMPS	Not Necessary	1,160.00 F	*- FN
25	2		*TAILLAMP HOUSING PANELS	Not Necessary	530.00 F	*- FN
26	2		*REAR FENDERS	Repair	2,300.00 F	*- FN
27	2		*REAR FENDER OUTER PROTECTORS	Not Necessary	1,082.00 F	*- FN
28	2		*REAR FENDER INNER TRIMS	Not Necessary	962.00 F	*- FN
29	1		*REAR FENDER UNDER SHIELD N/S	Not Necessary	266.00 F	*- FN
30	1		*REAR FENDER INNER AIR VENT N/S	Not Necessary	68.00 F	*- FN
31	1		*REAR FENDER GLASS W/MOULDING N/S	Not Necessary	820.00 F	*- FN
32	1		*REAR END PANEL	Dented	720.00 F	*540.90 FN
33	1		*REAR END PANEL TOP GARNISH	Not Necessary	408.00 F	*- FN
34	1		*REAR END PANEL LOCK SENSOR	Not Necessary	265.00 F	*- FN
35	1		*REAR FLOOR PANEL	Repair	1,288.30 F	*- FN
36	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	622.00 F	*- FN
37	2		*REAR FLOOR PANEL TOOLS SPONGES	Not Necessary	610.00 F	*- FN
38	1		*REAR FLOOR PANEL TOOLS SPONGE CENTRE	Not Necessary	308.30 F	*- FN
39	1		*REAR FLOOR PANEL SPARE TYRE NUT	Not Necessary	62.20 F	*- FN
40	1		*REAR EXHAUST ASSY	Repair	1,122.30 F	*- FN
41	2		*REAR EXHAUST MOUNTINGS	Not Necessary	60.00 F	*- FN
42	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	188.00 F	*- FN
43	2		*FRONT FENDER PROTECTORS	Torn	810.50 F	*810.50 FN
44	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FN
45	1		*INTER COOLER	Punctured	1,844.00 F	*1,220.00 FN
46	1		*FRONT BUMPER	Distorted	801.00 F	*614.50 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER REINFORCEMENT	Bent	665.00 F	*665.00 FN
48	1		*FRONT BUMPER SPONGE	Torn	302.00 F	*302.00 FN
49	2		*FRONT BUMPER SIDE RETAINERS	Bent	70.00 F	*70.00 FN
50	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FN
51	1		*FRONT BUMPER TOW COVER	Not Necessary	28.00 F	*- FN
52	2		*HEADLAMPS	Cracked	5,700.00 F	*1,773.00 FN
53	1		*FRONT GRILLE	Cracked	803.30 F	*461.20 FN
54	1		*FRONT GRILLE LOGO	Necessary	65.00 F	*65.00 FN
55	1		*BONNET	Buckled	923.30 F	*923.30 FN
56	1		*FRONT SUPPORT PANEL	Twisted	792.50 F	*792.50 FN
57	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	368.40 F	*368.40 FN
58	1		*AIR CON CONDENSER	Bent / Punctured	911.00 F	*911.00 FN
59	2		*AIR CON CONDENSER SIDE GARNISH	Torn	416.00 F	*416.00 FN
60	1		*COOLER PIPE 1	Bent	150.00 F	*150.00 FN
61	1		*COOLER PIPE 2	Bent	166.00 F	*166.00 FN
62	1		*AIR CON PIPE	Serviceable	105.00 F	*- FN
63	2		*FRONT BUMPER REINFORCEMENT BRACKETS	Bent	410.00 F	*410.00 FN
64	1		*OIL COOLER	Punctured	620.00 F	*620.00 FN
65	1		*OIL COOLER HOSE	Not Necessary	30.00 F	*- FN
66	1		*RADIATOR	Punctured	885.00 F	*885.00 FN
67	1		*RADIATOR FAN ASSY	Cracked / Jammed	820.00 F	*820.00 FN
68	2		*FRONT FOG LAMP COVERS	Scratched	190.00 F	*190.00 FN
69	2		*FRONT FOG LAMPS	Cracked	683.30 F	*683.30 FN
70	1		*SET REAR BUMPER REVERSE SENSOR (4 PCS)	Shorted	380.00 FS	*200.00 FS
71	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
72	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS
73	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
74	1		*REAR FENDER GLASS SEALANT N/S	Not Necessary	50.00 FS	*- FS
75	1		*SET REAR VIEW CAMERA CAM	Not Necessary	500.00 FS	*- FS
76	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	300.00 FS	*- FS
77	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
78	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
79	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	45,888.00	19,513.60
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	1,915.36
Total Parts (\$\$)	45,888.00	17,598.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE.	New	120.00	50.00
2	TO CHECK WIRING.	New	80.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR.	New	80.00	50.00
4	TO DISMANTLE & REPLACING REAR WINDSCREEN.	New	150.00	120.00
5	TO DISMANTLE & REPLACING REAR EXHAUST.	New	150.00	60.00
6	TO DISMANTLE & REPLACING REAR FENDER GLASS N/S.	New	150.00	0.00
7	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	New	150.00	80.00
8	TO DISMANTLE & REFIX PETROL TANK.	New	100.00	0.00
9	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	New	380.00	0.00
10	TO CONDUCT WHEEL ALIGNMENT.	New	120.00	0.00
11	TO SPRAY RUST PROOFING.	New	180.00	90.00
12	TO REFILL AIR CON GAS.	New	150.00	100.00
13	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
14	TO TRANSFER TAILGATE COMPONENTS.	New	100.00	60.00
15	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	New	3,000.00	1,400.00
16	TO PUTTY & SPRAY PAINTING.	New	3,000.00	1,800.00
Gross Labour Cost (S\$)			8,290.00	3,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >