

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20000793/R1DS3Q2**Date:** 28/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322
Claimant
Vehicle No : FBH677G **Insured Vehicle No :** SMN2537C
Date of Loss: 24/12/2019 Nature of Claim: TP Claim No: 4933167348SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH677G**
Make & Model: HONDA CBR, 150cc 150M (M) Engine No: KC178E0101566
Reg. Date: 27/02/2013 (Man. Year: 2012) Chassis No: MLHKC1788C5101566
Colour: Multi-colour Odometer: 0 km
Engine Capacity: 150 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 160/70-17 Rear Tyre Size: 130/70-17
Front Left Side: Metzeler 3 mm Rear Left Side: Metzeler 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,943.10	1,615.40	327.70	16.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	290.00	150.00	140.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,233.10	1,765.40	467.70	20.94
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,233.10	1,400.00	833.10	37.31
+ GST 7.00/7.00% (S\$)	156.32	98.00	58.32	37.31
Nett Amount (S\$)	2,389.42	1,498.00	891.42	37.31
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
Nett Liability (S\$)		1,558.00		

INSPECTION

Date of Assignment: 10/01/2020
Date Inspected: 13/01/2020 Inspected At: Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2,
#01-10
Singapore 159762
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLUTCH LEVER	Scratched	38.00 FL	*38.00 FL
2	1		*HANDLE BAR	Bent	145.00 FL	*145.00 FL
3	1		*HANDLE GRIP	Scratched	35.00 FL	*35.00 FL
4	1		*BRAKE LEVER	Not Necessary	38.00 FL	*- FL
5	1		*GEAR LEVER	Scratched	95.00 FL	*95.00 FL
6	1		*LOWER COWLING	Scratched	385.00 FL	*385.00 FL
7	1		*MEGNETO COVER	Scratched	165.00 FL	*165.00 FL
8	1		*CENTRE FAIRING	Scratched	430.00 FL	*430.00 FL
9	1		*TAIL COVER	Scratched	285.00 FL	*285.00 FL
10	1		*BODY SLIDER	Scratched	120.00 FL	*120.00 FL
11	1		*FRONT SIGNAL	Cracked	58.00 FL	*58.00 FL
12	1		*EXHAUST PIPE COVER	Not Necessary	165.00 FL	*- FL
13	1		*JACK FORK	Not Necessary	85.00 FS	*- FS
14	1		*ENGINE OIL	Necessary	20.00 FS	*20.00 FS
15	1		*GASKET	Necessary	15.00 FS	*15.00 FS
16	1		*ALIGNMENT FRONT SPORT RIM	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,139.00	1,791.00
- List Item Discount on L Items 10.00/10.00% (S\$)	195.90	175.60
Total Parts (S\$)	1,943.10	1,615.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	40.00	0.00
2	LABOR	New	250.00	150.00
Gross Labour Cost (\$)			290.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >