

22/03/2002

ASS. REC. BY:

REF: CS/C11 200008311 Etf3<sup>ST</sup>

Special Instruction:

Surveyor: Stive

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of C11Date/Time: 14.1.20 8.45a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 12916

Insured:

at Workshop m/s Performance MotorsTel: 63 190174of 303 Alexandra RoadPolicy No: DMPCSV3079 651800Claim No: SNM 20000162001

Sum Insured:

Excess: \$1000.00

Make of Veh:

D.O.A. 10.01.2020

(Client's Record)

CA (REV / REP. / REV 24 HRS)

Joseph

H.O.D. Endorsement:

Date/Time: 14.1.2020 9.57pm

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGT 12916 - X
14/1@16:30	revert via menmen
15/1@12:43	Approval by Alfred Toh
15/1@2:59pm	authorise repair inform Joseph excess \$1000

Surveyor

Star

REF:

CS/CTI 20000831/E4B3

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP-RES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured.

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

87K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGT 1791 G

Yr Regn:

26/2/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

BMW 3181

C.C

1499

Colour

Black

AVC: Insured / Std / NI / NA

Sp. Reading

76912

T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo:

WBA 8E-32910K 497936

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Contin

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/1/20

D.O.I.

14/1/20

Survey held at

Perforce Motors

Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-87K

Part by part \$16002.15 (Red 6196.40; 27%)

RECEIVED 12 MAR 2020

Date/Time, File Pass to?

☐

Proll. Report

Days Of Repair:

9

1) 11/3 Typist.  
Date/Time, File Return to?

☒

Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS - SI

) P/B

) Others

TOTAL

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Report Format :

OD

Lump Sum / I.B.I. (\$

16002.15

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2020		14 Jan 2020 08:45 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHONG CHOONG HIAN, ID: S6921936E, Tel: +6598224406, Email: CHONGCHOONGHIAN@GMAIL.COM			
Vehicle Reg. No.:	SGT1291G	Date of Loss:	10/01/2020 16:00 - :59	
Claim Type:	OD / SNM20D200162C01	Policy/Cover Note No.:	DMPCSN3079651800 (Comprehensive)	
		Excess:	S\$1,000.00	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/01/2020]			
Driver/Custodian:	CHONG CHOONG HIAN (50 / Male), NRIC: S6921936E, Tel: +6598224406 Email: CHONGCHOONGHIAN@GMAIL.COM			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 15 January 2020 2:59 PM  
**To:** yaguel.renan.joseph@simedarby.com.sg  
**Cc:** Chua Kee Sin; SUR  
**Subject:** SGT 1291G / OD / CHINA TAIPING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGT 1291G (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*SGT1291G (SNM20D200162C01)**

OD

Jan 10 2020 4:00PM

[CHONG CHOONG HIAN]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 15/01/2020 12:43 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (\$16862.50) - SGT1291G - Claim Handler: Chong Boon Sen

Approved:16862.50:Please proceed to authorize repairs at \$16,862.50 BEFORE Excess of \$1,000.00.

### DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 14 Jan 2020

**Preliminary Advice**

Vehicle No	: SGT1291G	Accident Date	: 10/01/2020
Make	: BMW 318i	Policy No.	: DMPCSN3079651800
Assignment Date	: 14/01/2020	Excess	: S\$1,000.00
Date of Inspection	: 14/01/2020	Est. Duration of Repair	: 9.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,198.55
Revised Amount	:S\$	16,862.50
Check Items (Estimated)	:S\$	3,328.25
Total	:S\$	20,190.75

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	87,000.00
COE / PARF Rebate	:S\$	42,925.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,075.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

*Celine* 14/1/2020

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/01/2020 11:07
Date Of Accident	10/01/2020 16:20
Exact Location Of Accident	AFTER LORNIE HIGHWAY TOWARDS PIE JURONG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT1291G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHONG CHOONG HIAN
NRIC No	SXXXX936E
Email Address	CHONGCHOONGHIAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98224406
Alternative Phone No	OTHERS-98224406

### Vehicle Particulars

Manufacturer	BMW
Model	318I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3079651800
Cover Note Number	

### Driver

Name of Driver	CHONG CHOONG HIAN
NRIC No	SXXXX936E
Date Of Birth	22/06/1969
Occupation	INDOOR
Date Of Driving Pass	04/05/1995
Driving Experience	24 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98224406
Fax Number	
Contact Number	OTHERS-98224406
Email Address	CHONGCHOONGHIAN@GMAIL.COM

Address	9 DAIRY FARM HEIGHTS #12-21
Postcode	677670
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD6648L
Vehicle Make/Model/Colour	CEMENT MIXER TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHUA SENG KOON
NRIC/Passport Number	SXXXX479F
Contact Number	63896116
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT
No. Of Passenger (Including Driver)	1




**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

 11/1/2020  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/1/20 at 4.19 pm, I was driving toward PIE Juvong. After checking for traffic clearance and signalled, I slowly filtered to the right. After I have filtered three quarter into the right lane (shown in the photo), the cement mixer truck (XD6648L) came in and squeezed ~~into~~ besides my car. Based on the video, my speed is slow as it was raining. The cement truck was behind me all the time and the driver should have seen my car. But he came in fast and tried to squeezed his way (based on the video). When the cement truck hit my car, I horned to alert him to stop his car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:  
 11/1/20 20

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Police Personnel's Signature  
 Name:  
 NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	936E
<b>Vehicle Details</b>	
Vehicle No.:	SGT1291G
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	318i SEDAN LED
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	F0021305B38B15A
Chassis No.:	WBA8E32010K497936
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,677.00
Original Registration Date:	26 Feb 2016
First Registration Date:	26 Feb 2016
Transfer Count:	1
Actual ARF Paid:	\$25,748.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2026
PARF Rebate Amount:	\$19,311.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Feb 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$23,614.00
<b>Total Rebate Amount:</b>	<b>\$42,925.00</b>

The information contained herein is correct as at 14 Jan 2020

OK

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 54092  
Date Estimated : 11/01/2020  
Prepared By : Joseph Yaguel

Page No. : 1 of 5

## - ESTIMATE REPAIR FOR -

Chong Choong Hian  
9 Dairy Farm Height  
#12-21  
Singapore  
Singapore 677670

## - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT1291G	WBA8E32010K497936	26/02/2016	318iA/4Dr	0

## DESCRIPTION

Replacing right front door, right wing mirror, right rear door, right rear fender, etc to knock out dents caused by the accident 850

VALUE  
6,800.00

Spray right rear fender, right rear door, right front door and wing mirror 2456

2,729.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs. 715 (photo)

873.00

To replace rear windscreen glass.

574.00

To conduct water leak tests.

75.00

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests. 451 (photo)

531.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

531.00

To replace tyre and wheel rim including balancing. (1x). right rear rim 80

94.00

To check electrical wiring systems and lightings at the rear section for proper function. 150

177.00

To carry out body cavity preservation. (For cut panel). 451

531.00

Sundries

150.00

To supply and install rear windscreen solar film.

531.00

To supply and install rear right window glass solar film.

425.00

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601  
64796624

CLK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- (After Sales) (No Complaint)
- Any supplementary item(s) must be resurveyed and is subject to final approval from insurance Company



GST REG. NO : M2 - 0020081

## ESTIMATE

Acknowledged by Repairer

Signature:

Date:

Estimate No. : b1 54092  
Date Estimated : 11/01/2020  
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT1291G	WBA8E32010K497936	26/02/2016	318iA/4Dr	0

## DESCRIPTION

To tow accident vehicle to PML workshop.

VALUE

195.00

Total Labour 1: 14,216.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND PLUG	10	1.00	10.00
RR RH FENDER	1	1,643.30	1,643.30
REAR RH DOOR	1	1,273.85	1,273.85
FRT RH DOOR	1	1,273.85	1,273.85
RH C-PILLAR REINFORCEMENT PLATE	1	53.75	53.75
RH SILL REINFORCEMENT PLATE	1	53.75	53.75
RH LOWER REAR DOOR HINGE	1	58.90	58.90
RH MIRROR GLASS HEATED WIDE ANGLE	1	683.80	683.80
RH HEATED OUTSIDE MIRROR	1	865.35	865.35
REAR WINDOW	1	736.80	736.80
FRT DOOR WEATHERSTRIP	1	141.40	141.40
REAR DOOR WEATHERSTRIP	1	141.40	141.40
REAR RH SIDE WINDOW FIXED	1	172.55	172.55
BLIND RIVET HEMLOCK 813	10	2.65	26.50
BLIND RIVET AVIBVLB	12	0.55	6.60
SCREW (SF PLUS M5X15)	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	112.70
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	39	0.55	21.45
(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 7,982.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date &amp; Time 14/1/20, 11.00am Excess \$

Surveyor's Name Steve CLKK Sign

Surveyor's Tel Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend

P/P, Rj Bahr Spj

Labour 1 : 14,216.00  
Parts : 7,982.55  
Labour 2 : 0.00  
Excess : 0.00  
Total GST @ 7% : 1,553.90  
Grand Total : 23,752.45



\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

22198.55



## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 54092  
Date Estimated : 11/01/2020  
Prepared By : Joseph Yaguel

## - ESTIMATE REPAIR FOR -

Chong Choong Hian  
9 Dairy Farm Height  
#12-21  
Singapore  
Singapore 677670

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT1291G	WBA8E32010K497936	26/02/2016	318iA/4Dr	0

## DESCRIPTION

## VALUE

Replacing right front door, right wing mirror, right rear door, right rear fender, etc to knock out dents caused by the accident 850

5950 6,800.00

Spray right rear fender, right rear door, right front door and wing mirror

2456 2,729.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs. 785 (photo)

785 873.00

To replace rear windscreen glass.

574.00

To conduct water leak tests.

75.00

To remove and install fuel tank to facilitate repairs including extract fuel and conduct leak tests. 451 (photo)

X ? 531.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00

To replace tyre and wheel rim including balancing. (1X). right rear rim

80 94.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To carry out body cavity preservation. (For cut panel).

451 531.00

Sundries

150.00

To supply and install rear windscreen solar film.

X ? 531.00

To supply and install rear right window glass solar film.

X ? 425.00

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2245269)

315, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

260, Kampong Arang Road  
East Coast Centre  
Singapore 439180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business  
Singapore 159944  
Fax: 64796601  
64796624

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081

## ESTIMATE

Acknowledged by Repairer

Signature:

Date:

Page No. : 2 of 5

Estimate No. : b1 54092  
Date Estimated : 11/01/2020  
Prepared By : Joseph Yaguel

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT1291G	WBA8E32010K497936	26/02/2016	318iA/4Dr	0

### DESCRIPTION

To tow accident vehicle to PML workshop.

VALUE  
195.00

Total Labour 1:

14,216.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND PLUG <del>XX</del> <del>AIN</del>	10	1.00	10.00
RR RH FENDER <del>DD</del>	1	1,643.30	1,643.30
REAR RH DOOR <del>DD</del>	1	1,273.85	1,273.85
FRT RH DOOR <del>DD</del>	1	1,273.85	1,273.85
RH C-PILLAR REINFORCEMENT PLATE <del>XX</del> <del>AIN</del>	1	53.75	53.75
RH SILL REINFORCEMENT PLATE <del>XX</del> <del>AIN</del>	1	53.75	53.75
RH LOWER REAR DOOR HINGE <del>7</del> <del>XX</del> <del>NN</del>	1	58.90	58.90
RH MIRROR GLASS HEATED WIDE ANGLE <del>XX</del> <del>NN</del>	1	683.80	683.80
RH HEATED OUTSIDE MIRROR <del>OR</del>	1	865.35	865.35
REAR WINDOW <del>7</del> <del>XX</del> <del>NN</del>	1	736.80	736.80
FRT DOOR WEATHERSTRIP <del>OR</del>	1	141.40	141.40
REAR DOOR WEATHERSTRIP <del>OR</del>	1	141.40	141.40
REAR RH SIDE WINDOW FIXED <del>7</del> <del>XX</del> <del>NN</del>	1	172.55	172.55
BLIND RIVET HEMLOCK 813 <del>XX</del> <del>NN</del>	10	2.65	26.50
BLIND RIVET AVIBVLB <del>XX</del> <del>NN</del>	12	0.55	6.60
SCREW (SF PLUS M5X15) <del>XX</del> <del>NN</del>	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML) <del>XX</del> <del>NN</del>	1	326.80	326.80
(DG) BODYWORK ADHESIVE K5A (50ML) <del>XX</del> <del>NN</del>	1	112.70	112.70
(DG) CLEANER R1 (100ML) <del>XX</del> <del>NN</del>	1	26.15	26.15
(DG) CLEANER R1 (100ML) <del>XX</del> <del>NN</del>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <del>XX</del> <del>NN</del>	2	131.55	263.10
PUNCH RIVET N4 <del>XX</del> <del>NN</del>	39	0.55	21.45
(DG/SL) ADHESIVE PRIMER VP 206 (30ML) <del>XX</del> <del>NN</del>	1	27.85	27.85
(S/L) SEAM SEAL 300ML <del>XX</del> <del>NN</del>	1	33.80	33.80

Total Parts :

7,982.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 14/1/20, 11.00am Excess S\$

Surveyor's Name STEVE (LKK) Sign

Surveyor's Tel Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend

DD - Not Authorised (Repair)

Excess - \$1000

8-9 days



P/P, Rj Def Smy

Labour 1	:	14,216.00
Parts	:	7,982.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,553.90
Grand Total	:	23,752.45

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 54092**  
Date Estimated : **11/01/2020**  
Prepared By : **Joseph Yaguel**

### - ESTIMATE REPAIR FOR -

**Chong Choong Hian**

**9 Dairy Farm Height**

**#12-21**

**Singapore**

**Singapore 677670**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**

**3 Anson Road**

**#16-00 Springleaf Tower**

**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SGT1291G</b>	<b>WBA8E32010K4979</b>	<b>26/02/2016</b>	<b>318iA/4Dr</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace both right doors, rear right fender and right wing mirror assembly etc including to remove and install body parts in order to carry out painting job.	5,950.00	0.00	5,950.00 ✓
To respray both right doors, rear right fender, right wing mirror cover and right roof frame etc.	2,456.00	0.00	2,456.00 ✓
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	785.00	0.00	785.00 ✓
To conduct water leak tests.	75.00	0.00	75.00 ✓
To check steering geometry and conduct wheel alignment according to BMW specification	451.00	0.00	451.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00 ✓
To carry out body cavity preservation. (For cut panel).	451.00	0.00	451.00 ✓
Sundries	150.00	0.00	150.00 ✓
To Tow accident vehicle to PML workshop	195.00	0.00	195.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR RH FENDER	1,643.30	1.00	0.00	1,643.30 ✓
REAR RH DOOR	1,273.85	1.00	0.00	1,273.85 ✓
FRT RH DOOR	1,273.85	1.00	0.00	1,273.85 ✓
RH HEATED OUTSIDE MIRROR	865.35	1.00	0.00	865.35 ✓
FRT DOOR WEATHERSTRIP	141.40	1.00	0.00	141.40 ✓
REAR DOOR WEATHERSTRIP	141.40	1.00	0.00	141.40 ✓



# Performance Motors Limited

A member of the Sims Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

---

Steve  
Ltk 10/3/20 9

Total Labour :	10,663.00
Total Parts :	5,339.15
Total Labour & Parts :	16,002.15
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	15,002.15
GST @7%:	1,050.15
Grand Total :	<u>16,052.30</u>

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2020		14 Jan 2020 08:45 <a href="#">Edit Adj Rpt</a>	<b>S\$16,002.15</b> <a href="#">Edit Estimates</a>	<b>S\$16,002.15</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	CHONG CHOONG HIAN, ID: S6921936E, Tel: +6598224406, Email: CHONGCHOONGHIAN@GMAIL.COM		
Vehicle Reg. No.:	SGT1291G	Date of Loss:	10/01/2020 16:00 - :59 [46 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM20D200162C01	Policy/Cover Note No.:	DMPCSN3079651800 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 23/01/2020]		
Driver/Custodian:	CHONG CHOONG HIAN (50 / Male) , NRIC: S6921936E, Tel: +6598224406 Email: CHONGCHOONGHIAN@GMAIL.COM		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- CHINA\_TAIPING (15/01/2020): Alert - Adj Mandate Approved (S\$16862.50) - SGT1291G - Claim Handler: Chong Boon...

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SGT1291G (SNM20D200162C01)**

















































**OD**

**Jan 10 2020 4:00PM**

**[CHONG CHOONG HIAN]**

**Performance Motors Limited**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:37	<b>Video - Accident</b> [Linked Accident Report Documents]	Load MP4	<input type="checkbox"/>
2	11/01/20 11:38	<b>Video - Accident</b> [Linked Accident Report Documents]	Load MP4	<input type="checkbox"/>
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:38	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 16:20	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	11/01/20 11:22	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	14/01/20 18:25	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
6	14/01/20 18:25	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
7	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	14/01/20 18:25	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
10	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/20 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	11/03/20 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/03/20 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/03/20 10:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
58	11/03/20 10:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	11/03/20 10:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	11/03/20 10:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	11/03/20 10:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	11/03/20 10:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	11/03/20 10:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/01/20 08:46	od estimate	Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:10	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/20 16:20	estimate	Load PDF	

## Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:37	Video - Accident	Load MP4	
2	11/01/20 11:38	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:38	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	11/01/20 11:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	11/01/20 11:10	Sketch Plan	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI20000831/ETF3S2

Date: 24/03/2020

## REFERENCE

Insured/Claimant: CHONG CHOONG HIAN  
Date of Loss: 10/01/2020

Policy No: DMPCSN3079651800  
Nature of Claim: OD

Claim No: SNM20D200162C01

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGT1291G  
Make & Model: BMW 318i, 1.5 (A)  
Reg. Date: 26/02/2016 (Man. Year: 2015)  
Colour: Black  
Engine Capacity: 1499 cc  
Market Value/New Car Price: S\$87,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: F0021305B38B15A  
Chassis No: WBA8E32010K497936  
Odometer: 76012 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 255/40 R18 Rear Tyre Size: 255/40 R18  
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm  
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,088.55	5,489.15	3,599.40	39.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,110.00	10,513.00	2,597.00	19.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,198.55</b>	<b>16,002.15</b>	<b>6,196.40</b>	<b>27.91</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>21,198.55</b>	<b>15,002.15</b>	<b>6,196.40</b>	<b>29.23</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,483.90</b>	<b>1,050.15</b>	<b>433.75</b>	<b>29.23</b>
<b>Nett Amount (S\$)</b>	<b>22,682.45</b>	<b>16,052.30</b>	<b>6,630.15</b>	<b>29.23</b>

## INSPECTION

Date of Assignment: 14/01/2020

Date Inspected: 14/01/2020 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2020)
<b>Parts:</b>	143	BMW 318I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGT1291G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BLIND PLUG	Not Necessary	10.00 FS	*- FS
2	1		*RR RH FENDER	Dented	1,643.30 FS	*1,643.30 FS
3	1		*REAR RH DOOR	Dented	1,273.85 FS	*1,273.85 FS
4	1		*FRT RH DOOR	Dented	1,273.85 FS	*1,273.85 FS
5	1		*RH C-PILLAR REINFORCEMENT PLATE	Not Necessary	53.75 FS	*- FS
6	1		*RH SILL REINFORCEMENT PLATE	Not Necessary	53.75 FS	*- FS
7	1		*RH LOWER REAR DOOR HINGE	Not Necessary	58.90 FS	*- FS
8	1		*RH MIRROR GLASS HEATED WIDE ANGLE	Not Necessary	683.80 FS	*- FS
9	1		*RH HEATED OUTSIDE MIRROR	Broken	865.35 FS	*865.35 FS
10	1		*REAR WINDOW	Not Necessary	736.80 FS	*- FS
11	1		*FRT DOOR WEATHERSTRIP	Necessary	141.40 FS	*141.40 FS
12	1		*REAR DOOR WEATHERSTRIP	Necessary	141.40 FS	*141.40 FS
13	1		*REAR RH SIDE WINDOW FIXED	Not Necessary	172.55 FS	*- FS
14	10		*BLIND RIVET HEML OCK 813	Not Necessary	26.50 FS	*- FS
15	12		*BLIND RIVET AVIBVLB	Not Necessary	6.60 FS	*- FS
16	5		*SCREW (SF PLUS M5X15)	Not Necessary	2.75 FS	*- FS
17	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	326.80 FS	*- FS
18	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Not Necessary	112.70 FS	*- FS
19	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
20	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
21	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
22	1		*PUNCH RIVET N4	Not Necessary	21.45 FS	*- FS
			39pcs			
23	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Not Necessary	27.85 FS	*- FS
24	1		*(S/L) SEAM SEAL 300ML	Not Necessary	33.80 FS	*- FS
25	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
26	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS
27	1		*REAR RIGHT WINDOW GLASS SOLAR FILM	Not Necessary	425.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>9,088.55</b>	<b>5,489.15</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACING RIGHT FRONT DOOR, RIGHT WING MIRROR, RIGHT REAR DOOR, RIGHT REAR FENDER, ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT.	New	6,800.00	5,950.00
2	SPRAY RIGHT REAR FENDER, RIGHT REAR DOOR, RIGHT FRONT DOOR AND WING MIRROR.	New	2,729.00	2,456.00
3	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS.	New	873.00	785.00
4	TO REPLACE REAR WINDSCREEN GLASS.	New	574.00	0.00
5	TO CONDUCT WATER LEAK TEST.	New	75.00	75.00
6	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING EXTRACT FUEL AND CONDUCT LEAK TEST.	New	531.00	0.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION.	New	531.00	451.00
8	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING RIGHT REAR RIM.	New	94.00	0.00
9	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
10	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
11	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.	New	195.00	195.00
<b>Gross Labour Cost (S\$)</b>			<b>13,110.00</b>	<b>10,513.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >