

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924 INV No. AC2004217

INV Date 29/05/2020

Reference CS/AGI20000832/Asf3q2

Code AGI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLG 5245Z

Insured Veh. SJL 1958Z

Claim No. C10005178

Policy No.

Accident Date 07/01/2020

Inspection Date 15/01/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
		Affiliated to Federation Internation	nale Des Experts En Automobi	le	
AUTO	TO & GENERAL INSURANCE (S) PL Ref : CS/AGI20000832/Asf3q2				
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date: 29-05-2020			
			Code: AGI		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SJL 1958Z	Veh. Inspected	SLG 5245Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10005178	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	14/01/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	CHEVROLET CRUZE	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	KL1JA6961BK175363	Colour	BLACK	
	Odometer	149588	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.	General Information				
	Accident Date	07/01/2020	Inspection Date	15/01/2020	
	Survey held at	1ST AUTOWORKS PTE LTD			
		23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933			
5a.			emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		REPAIRS.	
5b.		Estimate	Days of Repair		

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5245Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	NOT NECESSARY	1,901.00	-
1	BOOT LID EMBLEM	NOT NECESSARY	71.00	-
1	BOOT LID LETTERING "CHEVROLET"	NOT NECESSARY	65.00	-
1	BOOT LID LETTERING "CRUZE"	NOT NECESSARY	45.00	-
1	BOOT LID LETTERING "LS"	NOT NECESSARY	25.00	-
1	BOOT LID LETTERING "TURBO	NOT NECESSARY	52.00	-
1	REAR BOOTLID HANDLE (PLASTIC)	NOT NECESSARY	343.00	-
1	REAR BOOTLID INNER TRIM	NOT NECESSARY	250.00	-
1	BOOT LID LOCK MECHANISM	NOT NECESSARY	310.00	-
1	BOOT LID STRIKER	NOT NECESSARY	42.00	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	189.00	-
1	REAR BUMPER	DISTORTED	1,791.00	1,791.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	50.00	-
1	CENTRE BUMPER GUIDE	NOT NECESSARY	75.00	-
1	RHRC BUMPER GUIDE	NOT NECESSARY	55.00	-
1	LHRC BUMPER GUIDE	NOT NECESSARY	55.00	-
1	RHR BUMPER GUIDE	NOT NECESSARY	65.00	-
1	LHR BUMPER GUIDE	NOT NECESSARY	65.00	-
1	REAR BUMPER REINFORCEMENT	BENT	736.00	736.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	906.00	-
1	REAR END PANEL TRIM	NOT NECESSARY	159.00	-
	LESS 10% DISCOUNT		-725.00	-252.70
			6,525.00	2,274.30
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE & BRACKET (SN)	NOT NECESSARY	45.00	-
10	SET REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
4	REAR BOOTLID HANDLE CLIPS (SN)	NOT NECESSARY	26.00	-
11	INNER BOOTLID TRIM CLIPS (SN)	NOT NECESSARY	71.50	-
5	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	32.50	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-

Report Ref No. CS/AGI20000832/Asf3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	100.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	280.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	592.00	200.00
			1,332.00	230.00
	<u>LABOUR</u>			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		2,000.00	550.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,440.00	450.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.	NOT NECESSARY	250.00	-
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		80.00	30.00
	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID.	NOT NECESSARY	80.00	-
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
	REMOVE AND REPLACE REVERSE CAMERA (LABOUR).	NOT NECESSARY	80.00	-
	REMOVE AND REPLACE REVERSE SENSOR (LABOUR).	NOT NECESSARY	80.00	
			4,420.00	1,080.00
	GRAND TOTAL		12,277.00	3,584.30

RECOMMENDED COST OF LUMP SUM REPAIRS		2,850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI20000832/Asf3q2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLG 5245Z

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





