

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20000849/KES3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994047

Claimant
Vehicle No : SHC5523P **Insured Vehicle No :** SLV7276S

Date of Loss: 06/01/2020 Nature of Claim: TP Claim No: 3937155597SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5523P**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001698

Reg. Date: 15/08/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278863

Colour: Metallic White/Red Odometer: 456713 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 9 mm Rear Left Side: Giti 8 mm

Front Right Side: Sailun 9 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,734.97	3,526.42	26,208.55	88.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,440.00	1,370.00	17,070.00	92.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,174.97	4,896.42	43,278.55	89.84
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	48,174.97	3,900.00	44,274.97	91.90
+ GST 7.00/7.00% (S\$)	3,372.25	273.00	3,099.25	91.90
Nett Amount (S\$)	51,547.22	4,173.00	47,374.22	91.90
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$95.04/day) (S\$)		380.16		
(S\$)		4,753.16		
Liabe Amount (50.00%) (S\$)		2,376.58		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,384.03		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 13/01/2020

Date Inspected: 13/01/2020 Inspected At: Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR LH	Repair	758.70 FL	*- FL
2	1		*DOOR GUIDE REAR LH	Serviceable	136.40 FL	*- FL
3	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	240.50 FL	*- FL
4	1		*DOOR MOULDING REAR LH	Serviceable	100.50 FL	*- FL
5	1		*DOOR FINISHER REAR LH	Serviceable	230.30 FL	*- FL
6	1		*DOOR REGULATOR REAR LH L70Y	Serviceable	657.10 FL	*- FL
7	1		*DOOR REGULATOR MOTOR REAR LH L70Y	Serviceable	450.60 FL	*- FL
8	1		*DOOR WAIST SEAL OUTER REAR LH L70Y	Serviceable	169.60 FL	*- FL
9	1		*DOOR HANDLE OUTER REAR LH L70Y	Serviceable	42.10 FL	*- FL
10	1		*DOOR HANDLE CAP REAR LH L70Y	Serviceable	57.90 FL	*- FL
11	1		*DOOR HANDLE MODULE REAR LH L70Y	Serviceable	133.40 FL	*- FL
12	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
13	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
14	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
15	1		*DOOR CHECK FRT LH	Serviceable	90.90 FL	*- FL
16	1		*DOOR LOCK FRT LH	Repair	453.80 FL	*- FL
17	1		*DOOR REGULATOR FRT LH	Repair	758.10 FL	*- FL
18	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	501.40 FL	*- FL
19	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	69.00 FL	*- FL
20	1		*DOOR MOULDING FRONT LH	Serviceable	100.50 FL	*- FL
21	1		*DOOR FINISHER FRONT LH	Serviceable	258.90 FL	*- FL
22	1		*DOOR WEATHERSTRIP FRONT LH	Serviceable	316.00 FL	*- FL
23	1		*DOOR SEAL FRONT LH	Serviceable	69.60 FL	*- FL
24	1		*DOOR SEAL LOWER FRONT LH	Serviceable	93.90 FL	*- FL
25	1		*DOOR GLASS RUNNER SEAL FRONT LH	Serviceable	332.00 FL	*- FL
26	1		*DOOR WAIST SEAL OUTER FRONT LH	Serviceable	92.20 FL	*- FL
27	1		*DOOR HANDLE OUTER FRONT LH	Serviceable	169.50 FL	*- FL
28	1		*DOOR HANDLE CAP FRONT LH	Serviceable	17.30 FL	*- FL
29	1		*DOOR HANDLE MODULE FRT LH L70Y	Serviceable	133.40 FL	*- FL
30	1		*DOOR MIRROR ASSY LH	Serviceable	727.90 FL	*- FL
31	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
32	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
33	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
34	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
35	1		*ROCKER PANEL CENTER LH	Bent	990.25 FL	*990.25 FL
36	1		*FENDER PANEL FRT LH	Repair	414.40 FL	*- FL
37	1		*WHEELARCH FRT LH	Serviceable	112.30 FL	*- FL
38	1		*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	*- FL
39	1		*FENDER INSULATOR LH	Serviceable	65.50 FL	*- FL
40	1		*FENDER BRACKET FRT LH	Serviceable	38.90 FL	*- FL
41	1		*BUMPER COVER FRT	Serviceable	747.20 FL	*- FL
42	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
43	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
44	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
45	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
46	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
47	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
48	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
49	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
50	1		*HEADLAMP LH	Serviceable	743.60 FL	*- FL
51	1		*HEADLAMP PANEL FRT LH	Repair	127.70 FL	*- FL
52	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
53	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
55	1		*FRAME FULL SUPPORT PANEL	Repair	592.70 FL	*- FL
56	1		*FRAME FULL SUPPORT BRACKET	Serviceable	41.60 FL	*- FL
57	1		*LOWER ARM LH L70Y	Serviceable	192.70 FL	*- FL
58	1		*KNUCKLE ARM LH L70Y	Serviceable	481.50 FL	*- FL
59	1		*ABSORBER FRT LH L70Y	Serviceable	274.10 FL	*- FL
60	1		*DRIVESHAFT LH	Serviceable	1,355.70 FL	*- FL
61	1		*BONNET	Repair	1,312.70 FL	*- FL
62	1		*BONNET STRUT LH	Serviceable	53.30 FL	*- FL
63	1		*BONNET HINGE LH	Repair	236.50 FL	*- FL
64	1		*BONNET LOCK	Repair	152.80 FL	*- FL
65	1		*BONNET CABLE	Serviceable	55.20 FL	*- FL
66	1		*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
67	1		*BONNET SEAL OUTER	Serviceable	83.20 FL	*- FL
68	1		*BONNET CABLE COVER	Serviceable	80.60 FL	*- FL
69	1		*BUMPER COVER REAR	Serviceable	561.70 FL	*- FL
70	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
71	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
72	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
73	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
74	1		*REAR DOOR STICKER 6555-3333	Not Necessary	100.00 FS	*- FS
75	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
76	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
77	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
78	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
79	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
80	1		*DOOR HINGE NUT LH	Not Necessary	14.60 FS	*- FS
81	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
82	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
83	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
84	1		*REAR LEFT TYRE	Serviceable	330.00 FS	*- FS
85	1		*REAR LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
86	1		*FRONT LEFT TYRE	Serviceable	330.00 FS	*- FS
87	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
88	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
89	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
90	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
91	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
92	1		*SET BUMPER GRILLE LOWER CIP	Not Necessary	69.00 FS	*- FS
93	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
94	2		*FRAME FULL SUPPORT PANEL NUT	Serviceable	20.00 FS	*- FS
95	2		*FRAME FULL SUPPORT PANEL STUD	Serviceable	30.00 FS	*- FS
96	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
97	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
98	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
99	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
100	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
101	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
102	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
103	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
104	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
105	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
106	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
107	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **32,690.41** **3,909.91**
- List Item Discount on L Items 10.00/10.00% (\$\$) **2,955.44** **383.49**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	29,734.97	3,526.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	7,500.00	600.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
7	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
13	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
14	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO TRANSFER OF FRONT BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
16	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
17	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (\$\$)			18,440.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >