Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000855/ARS3Q2

Date: 07/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100419038

Claimant
Vehicle No: SME5757L Insured Vehicle No: SKT9442M

Date of Loss: 09/01/2020 Nature of Claim: TP Claim No: 7944858539SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME5757L

Make & Model: HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A) Engine No: G4FJJU495435

Reg. Date: 12/10/2018 (Man. Year: 2018) Chassis No: KMHJ3812VKU805102

Colour: White Odometer: 28032 km

Engine Capacity: 1591 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,173.71	8,217.68	5,956.03	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	2,830.00	2,310.00	44.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,313.71	11,047.68	8,266.03	42.80
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	19,313.71	8,800.00	10,513.71	54.44
+ Loss of Use (7.0 x S\$	420.00			
+ Doc/S	7.45			
Ne	tt Liability (S\$)	9,227.45		

INSPECTION

Date of Assignment: 13/01/2020

Date Inspected: 13/01/2020 Inspected At: Cas Garage Pte Ltd (HQ)

No.1, Kaki Bukit Ave 6, #02-22

Autobay

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: Jaslin Kok Chin Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,698.70 FL	*1,698.70 FL
2	1		*TAILGATE OUTER GARNISH	Deformed	758.20 FL	*758.20 FL
3	1		*TAILGATE OUTER GARNISH BRACKET	Cracked	268.50 FL	*268.50 FL
4	1		*TAILGATE LOGO	Necessary	102.50 FL	*102.50 FL
5	1		*TAILGATE TUCSON EMBLEM	Necessary	98.70 FL	*98.70 FL
6	1		*TAILGATE 1.6T EMBLEM	Necessary	85.60 FL	*85.60 FL
7	1		*TAILGATE S EMBLEM	Necessary	84.70 FL	*84.70 FL
8	2		*TAILGATE REFLECTORS	Not Necessary	1,743.80 FL	*-FL
9	1		*TAILGATE WEATHERSTRIP	Cut	265.80 FL	*265.80 FL
10	1		*TAILGATE INNER TRIM	Cracked	402.80 FL	*402.80 FL
11	1		*TAILGATE INNER LOCK	Damaged	758.90 FL	*758.90 FL
12	1		*TAILGATE SMART KEY ANTENNA	Cracked	285.60 FL	*285.60 FL
13	1		*TAILGATE BOOT RELEASE ANTENNA	Not Necessary	295.74 FL	*-FL
14	1		*TAILGATE INNER LOCK	Repeated	758.90 FL	*-FL
15	1		*REAR END PANEL	Dented	825.60 FL	*825.60 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	245.30 FL	*245.30 FL
17	1		*REAR BUMPER UPPER	Deformed	581.30 FL	*581.30 FL
18	1		*REAR BUMPER LOWER	Deformed	563.20 FL	*563.20 FL
19	1		*REAR BUMPER TOWING COVER	Deformed	52.30 FL	*52.30 FL
20	1		*REAR BUMPER SIDE RADAR SENSOR RH	Not Necessary	1,606.90 FL	*-FL
21	2		*REAR BUMPER SIDE RETAINERS	Necessary	185.00 FL	*185.00 FL
22	1		*REAR BUMPER REINFORCEMENT	Cracked	480.50 FL	*425.00 FL
23	3		*REAR BUMPER REINFORCEMENT BRACKETS	Damaged	209.40 FL	*209.40 FL
24	2		*REAR BUMPER REFLECTORS	Not Necessary	173.00 FL	*- FL
25	2		*REAR FENDERS INNER COWLING	Not Necessary	430.60 FL	*-FL
26	2		*REAR FENDERS OUTER GARNISH	Not Necessary	411.20 FL	*-FL
27	1		*TAILAMPS	O/S Cracked	1,846.20 FL	*593.00 FL
28	1		*REAR SILENCER BOX	Dented	1,456.30 FL	*1,282.00 FL
29	2		*REAR SILENCER BOX MOUNTING	Not Necessary	171.20 FL	*-FL
30	1		*REAR SILENCER BOX PROTECTOR	Not Necessary	145.70 FL	*-FL
31	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
32	2		*END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
33	2		*WINDSCREEN SEALANTS	Necessary	80.00 FS	*60.00 FS
34	1		*SET REAR REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
35	1		*SET REAR NUMBER PLATE WITH CASING	Dented	50.00 FS	*50.00 FS
36	2		*SET REAR FENDER COWLING	Not Necessary	60.00 FS	*-FS
37	1		*SET FRONT FENDER OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*-FS
⊢=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.	Sub Total (St)	17 570 14	10 172 10
			- List Item Discount on L Items 20	Sub Total (S\$)	•	10,172.10 1,954.42
			- List itelli Discount on Littellis 20	J.00/20.00 /0 (3\$)	J,J30.43	1,304.42
				Total Parts (S\$)	14,173.71	8,217.68
					,	-,=

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RENEW DAMAGED PARTS ,REPLACE ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,800.00	920.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	920.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO RESET FAULT CODE ,DIAGNOSE AND RESET FAULT CODE	New	200.00	120.00
5	TO REMOVE AND REPLACE SENSORS AND DISTANCE SETTLING	New	150.00	60.00
6	TO APPLY COATING TO THE VEHICLE	New	500.00	380.00
7	TO CONDUCT WIRING CHECK ON REAR TAILLAMPS	New	120.00	30.00
8	TO REMOVE AND REMOVE REAR SILENCER BOX	New	150.00	80.00
9	TO REMOVE /REFIT INTERIOR UPHOLSTERY	New	150.00	60.00
10	TO REMOVE/TRANSFER BOOTLID LOCK AND MECHANISM	New	150.00	80.00
11	TO REMOVE /REFIT REAR WINDSCREEN	New	120.00	120.00
	Gross Labour Cost (S\$)		5,140.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >