



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6791A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	O/S MIRROR ASSY	CRACKED	911.60	911.60
	LESS 20% DISCOUNT		-182.32	-182.32
			729.28	729.28
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<b><u>LABOUR</u></b>			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME,ETC.		150.00	80.00
	TO PUTTY AND SPRAY PAINTING ON O/S SIDE MIRROR .		150.00	80.00
			300.00	160.00
	<b>GRAND TOTAL</b>		<b>1,079.28</b>	<b>889.28</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>889.28</b>

Report Ref No. CC4/FCI20000867/Fha3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.