## Registration No. QX 1113Z / SLA 2056D

		PARTS				
S/N	ITEM DESCRIPTION	PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR QTY
1	MATERIALS					
1.1	Front Bumper	1	Broken	\$2,891.00	\$2,891.00	
1.2	Front RH Bumper Retainer	1	Broken	\$76.70	\$76.70	
1.3	Front LH Bumper Retainer	1	Broken	\$76.70	\$76.70	
1.4	Front Bumper Reinforcement	1	Dented	\$1,003.00	\$1,003.00	
1.5	Front Bumper Lower Grill	1	Broken	\$413.00	\$413.00	
1.6	Radiator Grill	1	Broken	\$1,947.00	\$1,947.00	
1.7	RHS Headlamp	1	Broken	\$2,242.00	\$2,242.00	
1.8	LHS Headlamp	1	Broken	\$2,242.00	\$2,242.00	
1.9	Bonnet Cover	1	Dented	\$4,248.00	\$4,248.00	
	COSTING		TOTAL PARTS COST		\$15,139.40	
2	SCOPE OF REPAIRS					
2.1	Remove, Replace & Spray Paint for Front Complete Bumper including replacing Front RH & LH Bumper Retainer & Front Bumper Lower Grill					5.5
2.2	Remove & Replace Front Bumper Reinforcement					3
2.3	Remove & Replace Radiator Grill					0.5
2.4	Remove, Replace & Wiring for RHS Headlamp					1
2.5	Remove, Replace & Wiring for LHS Headlamp					1
2.6	Remove, Replace & Spray Paint for Bonnet Cover					6
2.7	Panel Beat & Spray Paint for Front RH Fender					2
	COSTING		TOTAL MAN-HOUR			19.00