



CVR Accident Photos

VEHICLE DETAIL

Vehicle No	QX1113Z / SLA2056D	Date Of accident	
Date Booked In		Date of Submission	

REPAIR DESCRIPTIONS

- 1. Remove Front Bumper (Pic 1-3)
- 2. Remove Front Bumper Reinforcement
- 3. Remove Front RH Bumper Retainer (Pic 4)
- 4. Remove Front LH Bumper Retainer (Pic 5)
- 5. Remove Front Bumper Lower Grill (Pic 6)
- 6. Remove Radiator Grill (Pic 7-8)
- 7. Remove RHS Headlamp (Pic 9)
- 8. Remove LHS Headlamp (Pic 10)
- 9. Remove Bonnet Cover (Pic 11-12)
- 10. Replace Front Bumper (Pic 1-3)
- 11. Replace Front Bumper Reinforcement
- 12. Replace Front RH Bumper Retainer (Pic 4)
- 13. Remove Front LH Bumper Retainer (Pic 5)
- 14. Replace Front Bumper Lower Grill (Pic 6)
- 15. Replace Radiator Grill (Pic 7-8)
- 16. Replace RHS Headlamp (Pic 9)
- 17. Replace LHS Headlamp (Pic 10)
- 18. Replace Bonnet Cover (Pic 11-12)
- 19. Wiring for RHS & LHS Headlamp (Pic 9-10)
- 20. Panel Beating for Front RH Fender (Pic 13)
- 21. Putty & Spray Paint for Front Complete Bumper (Pic 1-3)
- 22. Putty & Spray Paint for Bonner Cover (Pic 11-12)
- 23. Putty & Spray Paint for Front RH Fender (Pic 13)

PHOTOS OF DAMAGED PARTS

Front LH Bumper Dented & Scratched (Pic 1)	Front LH Bumper Scratched (Pic 2)	
Howal H Bumper Dented & Scratched	Front LH Bumper Scratched	
Front Bumper Cracked (Pic 3)	Front RH Bumper Misaligned (Pic 4)	
Front Cracked	Front RH Bumper Misaligned	
Front LH Bumper Dislodged (Pic 5)	Front Bumper Lower Grill Dislodged (Pic 6)	



CVR Accident Photos

