

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Registration No. QX 1113Z / SLA 2056D

s/n	ITEM DESCRIPTION	PARTS				
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN- HOUR QTY
1	MATERIALS					
1.1	Front Bumper	1	Broken	\$2,891.00	\$2,891.00	
1.2	Front RH Bumper Retainer	1	Broken	\$76.70	\$76.70	
1.3	Front LH Bumper Retainer	1	Broken	\$76.70	\$76.70	
1.4	Front Bumper Reinforcement	1	Dented	\$1,003.00	\$1,003.00	
1.5	Front Bumper Lower Grill	1	Broken	\$413.00	\$413.00	
1.6	Radiator Grill	1	Broken	\$1,947.00	\$1,947.00	
1.7	RHS Headlamp	1	Broken	\$2,242.00	\$2,242.00	
1.8	LHS Headlamp	1	Broken	\$2,242.00	\$2,242.00	
1.9	Bonnet Cover	1	Dented	\$4,248.00	\$4,248.00	
	COSTING		TOTAL PARTS CO	OST	\$15,139.40	
2	SCOPE OF REPAIRS					
2.1	Remove, Replace & Spray Paint for Front Complete Bumper including replacing Front RH & LH Bumper Retainer & Front Bumper Lower Grill					5.5
2.2	Remove & Replace Front Bumper Reinforcement					3
2.3	Remove & Replace Radiator Grill					0.5
2.4	Remove, Replace & Wiring for RHS Headlamp					1
2.5	Remove, Replace & Wiring for LHS Headlamp					1
2.6	Remove, Replace & Spray Paint for Bonnet Cover					6
2.7	Panel Beat & Spray Paint for Front RH Fender					2
	COSTING		TOTAL MAN-HO	NIP.		19.00

Vehicle Inspected By

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.