

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000876/ACF3E2

Date: 27/01/2021

REFERENCE

Insured/Claimant:	SEOW YEN CHOON KELVIN	Policy No:	1800098325	
Date of Loss:	13/01/2020	Nature of Claim:	OD	Claim No: 1642241715SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE6183J	Engine No:	CYG023275
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G3JN036761
Reg. Date:	17/08/2018 (Man. Year: 2017)	Odometer:	25712 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$152,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	58,583.00	26,970.88	31,612.12	53.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,532.00	7,802.00	7,730.00	49.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,115.00	34,772.88	39,342.12	53.08
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	73,715.00	34,372.88	39,342.12	53.37
+ GST 7.00/7.00% (S\$)	5,160.05	2,406.10	2,753.95	53.37
Nett Amount (S\$)	78,875.05	36,778.98	42,096.07	53.37

INSPECTION

Date of Assignment:	14/01/2020		
Date Inspected:	14/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,787.00 FS	*2,229.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	491.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	116.00 FS	*- FS
4	14		*LOCKING CLIP	Necessary	51.00 FS	*40.32 FS
5	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	68.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	199.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER TRIM	Not Necessary	860.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,412.80 FS
10	1		*RADIATOR GRILLE COVER	Cracked	33.00 FS	*26.08 FS
11	2		*RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT	Cracked	122.00 FS	*96.96 FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,034.00 FS	*- FS
13	2		*AIR GUIDE GRILLE COVER - LH / RH	Not Necessary	92.00 FS	*- FS
14	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	484.00 FS	*- FS
15	2		*HEADLIGHT COVER CAP - LH / RH	Not Necessary	104.00 FS	*- FS
16	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	754.00 FS	*602.80 FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	215.00 FS	*172.00 FS
18	2		*FRONT BUMPER BRACKET HOLDER - LH / RH	Damaged	474.00 FS	*378.40 FS
19	1		*FRONT BUMPER COVER	Cracked	112.00 FS	*89.20 FS
20	2		*FRONT BUMPER SUPPORT	Damaged	23.00 FS	*17.92 FS
21	1		*AIRCON STICKER	Necessary	18.00 FS	*14.00 FS
22	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
23	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	419.00 FS	*- FS
24	2		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	462.00 FS	*- FS
25	1		*SET FRONT BUMPER WIRING	Not Necessary	532.00 FS	*- FS
26	1		*SIGNAL HORN - LH LOW TONE	Not Necessary	262.00 FS	*- FS
27	1		*SIGNAL HORN - RH HIGH TONE	Not Necessary	215.00 FS	*- FS
28	2		*SPRING SHACKLE - LH / RH	Not Necessary	86.00 FS	*- FS
29	1		*BONNET	Dented	4,965.00 FS	*3,972.00 FS
30	1		*BONNET ATTACHMENT PARTS	Not Necessary	161.00 FS	*- FS
31	2		*BONNET LID HINGE - LH / RH	Not Necessary	292.00 FS	*- FS
32	2		*BONNET GAS FILLED STRUT	Not Necessary	217.00 FS	*- FS
33	1		*BONNET CATCH HOOK	Not Necessary	127.00 FS	*- FS
34	2		*BONNET LOCK BAR	Not Necessary	90.00 FS	*- FS
35	1		*BONNET CATCH HOOK	Not Necessary	16.00 FS	*- FS
36	2		*BONNET LID LOCK	Not Necessary	391.00 FS	*- FS
37	2		*HOOD MICRO SWITCH	Not Necessary	133.00 FS	*- FS
38	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	53.00 FS	*- FS
39	1		*BONNET LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
40	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	214.00 FS	*171.20 FS
41	2		*LED HEADLIGHT - LH / RH	Cracked	17,214.00 FS	*13,771.20 FS
42	1		*DIPPED BEAM POWER MODULE	Not Necessary	508.00 FS	*- FS
43	1		*DAY DRIVING LIGHTS POWER MODULE	Damaged	520.00 FS	*415.60 FS
44	1		*HEADLAMP FANS - RH	Not Necessary	363.00 FS	*- FS
45	1		*HEADLAMP REPAIR KIT - RH	Not Necessary	31.00 FS	*- FS
46	2		*HEADLAMP ASSEMBLY SPACER	Not Necessary	77.00 FS	*- FS
47	1		*HEADLAMP ASSEMBLY ADJUSTER	Not Necessary	42.00 FS	*- FS
48	1		*HEADLAMP HOSE	Not Necessary	38.00 FS	*- FS
49	1		*HEADLAMP BRACKET	Not Necessary	26.00 FS	*- FS
50	2		*LIFT CYLINDER - LH / RH	Not Necessary	432.00 FS	*- FS
51	1		*HEADLIGHT HOSE	Not Necessary	426.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LOCK CARRIER	Cracked	1,140.00 FS	*912.00 FS
53	2		*COOLANT REGULATOR SUPPORT	Not Necessary	67.00 FS	*- FS
54	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	57.00 FS	*- FS
55	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
56	1		*AIRCON CONDENSER	Dented	689.00 FS	*551.20 FS
57	1		*HIGH PRESSURE SAFETY SWITCH VALVE	Not Necessary	48.00 FS	*- FS
58	1		*PRESSURE SENDER	Not Necessary	175.00 FS	*- FS
59	1		*RADIATOR	Bent	775.00 FS	*632.80 FS
60	2		*RADIATOR RUBBER BUSH - UPPER	Necessary	12.00 FS	*9.92 FS
61	2		*RADIATOR RUBBER BUSH - CENTRE	Necessary	18.00 FS	*14.56 FS
62	2		*RADIATOR RUBBER BUSH - LOWER	Necessary	24.00 FS	*19.36 FS
63	4		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
64	1		*CHARGE AIR COOLER	Not Necessary	513.00 FS	*- FS
65	1		*PRESSURE HOSE - RH	Not Necessary	320.00 FS	*- FS
66	1		*PRESSURE HOSE - LH	Not Necessary	150.00 FS	*- FS
67	1		*RADIATOR TWIN FAN RING	Not Necessary	237.00 FS	*- FS
68	1		*RADIATOR FAN	Not Necessary	811.00 FS	*- FS
69	1		*RADIATOR FAN	Not Necessary	700.00 FS	*- FS
70	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	50.00 FS	*41.28 FS
71	1		*RADIATOR COVER - UPPER CENTRE	Not Necessary	27.00 FS	*- FS
72	1		*RADIATOR SEALING STRIP	Not Necessary	21.00 FS	*- FS
73	1		*RADIATOR AIR GUIDE - RH FRONT	Cracked	24.00 FS	*18.64 FS
74	1		*RADIATOR INTAKE AIR DUCT - RH FRONT	Not Necessary	79.00 FS	*- FS
75	1		*RADIATOR AIR FILTER	Not Necessary	266.00 FS	*- FS
76	1		*RADIATOR AIR INTAKE HOSE	Not Necessary	150.00 FS	*- FS
77	1		*RADAR SENSOR COVER FRAME - RH	Not Necessary	12.00 FS	*- FS
78	1		*RADAR SENSOR COVERFRAME - LH	Not Necessary	12.00 FS	*- FS
79	1		*DISTANCE REGULATION CONTROL UNIT - RH	Not Necessary	6,177.00 FS	*- FS
80	1		*DISTANCE REGULATION CONTROL UNIT - LH	Not Necessary	5,432.00 FS	*- FS
81	2		*FENDER STONE GUARD FILM - LH / RH	Necessary	220.00 FS	*176.00 FS
82	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
83	1		*SUNDRIES	Necessary	500.00 FS	*20.08 FS
84	1		*RHS FRONT FENDER	Buckled	1,310.00 FS	*1,048.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 58,583.00 26,970.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
2	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND RENEW AIRCOND CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, HINGES, BOTH FRONT FENDER AND BONNET	New	5,300.00	2,200.00
6	TO RENEW AND CONFIGURE BOTH FRONT BUMPER AND RADAR SENSOR	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND RENEW RHS FRONT FENDER	New	1,200.00	500.00
9	TO REPAIR LHS FRONT FENDER	New	800.00	0.00
Gross Labour Cost (S\$)			15,532.00	7,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >