

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20000879/ACF3E2

**Date:** 23/03/2021

### REFERENCE

Insured/Claimant:	LIM TSEN YONG	Policy No:	2100329576		
Date of Loss:	10/01/2020	Nature of Claim:	OD	Claim No:	3800884517SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH9813P		
Make & Model:	AUDI A4, 1.8 TFSI MU (B8) (A)	Engine No:	CJE017590
Reg. Date:	31/01/2013 (Man. Year: 2012)	Chassis No:	WAUZZZ8K6DA057923
Colour:	Gold	Odometer:	108099 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,170.00	3,451.60	3,718.40	51.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	1,852.00	2,100.00	53.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,122.00</b>	<b>5,303.60</b>	<b>5,818.40</b>	<b>52.31</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>10,322.00</b>	<b>4,503.60</b>	<b>5,818.40</b>	<b>56.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>722.54</b>	<b>315.25</b>	<b>407.29</b>	<b>56.37</b>
<b>Nett Amount (S\$)</b>	<b>11,044.54</b>	<b>4,818.85</b>	<b>6,225.69</b>	<b>56.37</b>

### INSPECTION

Date of Assignment:	14/01/2020		
Date Inspected:	14/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,041.00 FS	*1,688.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	207.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	123.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	177.00 FS	*- FS
6	1		*FRONT BUMPER SUPPORT ELEMENT - UPPER	Not Necessary	54.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,005.00 FS	*804.00 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	123.00 FS	*98.00 FS
9	1		*FRONT WHEEL SPOILER - LH	Not Necessary	45.00 FS	*- FS
10	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	802.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
12	2		*FRONT BUMPER SUPPORT	Not Necessary	23.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
14	1		*FRONT BUMPER COVER	Not Necessary	116.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
16	1		*AIRCON STICKER	Not Necessary	22.00 FS	*- FS
17	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	184.00 FS	*- FS
18	1		*SPRING SHACKLE - LH HIGH TONE	Not Necessary	23.00 FS	*- FS
19	1		*HEADLIGHT MOUNTING - LH	Not Necessary	107.00 FS	*- FS
20	1		*HEADLIGHT BRACKET	Not Necessary	96.00 FS	*- FS
21	1		*HEADLIGHT COUPLING ELEMENT	Not Necessary	29.00 FS	*- FS
22	1		*HALOGEN HEADLIGHT - LH	Cut	994.00 FS	*821.60 FS
23	1		*HALOGEN FOG LAMP - LH	Not Necessary	242.00 FS	*- FS
24	1		*RADIATOR AIR GUIDE - LH	Not Necessary	24.00 FS	*- FS
25	1		*FRONT NO PLATE	Necessary	40.00 FS	*40.00 FS
26	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 7,170.00 3,451.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,952.00</b>	<b>1,852.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >