

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000894/GGA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJP8160R	Insured Vehicle No :	SHC1731G
Date of Loss: 30/12/2019	Nature of Claim: TP	Claim No: MCT19120750

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP8160R	Engine No:	R16A14002912
Make & Model:	HONDA CIVIC, 1.6 5AT (A)	Chassis No:	JHMF46209S200743
Reg. Date:	13/04/2009 (Man. Year: 2008)	Odometer:	122865 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,302.41	1,272.41	30.00	2.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	2,475.00	505.00	16.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,282.41	3,747.41	535.00	12.49
+ GST 7.00/7.00% (S\$)	299.77	262.32	37.45	12.49
Nett Amount (S\$)	4,582.18	4,009.73	572.45	12.49
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,445.18		

INSPECTION

Date of Assignment:	14/01/2020	Inspected At:	Kah Motor Co Sdn Bhd (Ubi)
Date Inspected:	04/02/2020		15 Ubi Road 4
			Singapore 408610
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)
Parts: 143	HONDA CIVIC 1.6 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP8160R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANELL FR DR	Buckled	697.95 FS	*697.95 FS
2	1		*TAPE SETL.FR.DR	Necessary	41.17 FS	*41.17 FS
3	1		*MIRROR ASSYL.DR	Distorted	355.87 FS	*355.87 FS
4	1		*PROTECTORL.FR.DR	Necessary	90.52 FS	*90.52 FS
5	1		*MLDGL FR DR	Necessary	66.90 FS	*66.90 FS
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 1,302.41 1,272.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESET VEHICLE SMART ENTRY SYSTEM	New	480.00	350.00
2	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	New	600.00	450.00
3	STRAIGHTEN ALIGN LEFT SILL PANEL	New	800.00	675.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,100.00	1,000.00
			Gross Labour Cost (\$\$)	2,475.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >