

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

SINGAPORE 0/9909

INV No. AC2007074

INV Date 19/10/2020

Reference CC6/CTI20000915/Uda3q2

Code CT

PROFESSIONAL SERVICE FEE

Vehicle No. SLC 4489P

Insured Veh. GBC 25P

Claim No. SNM20D200037/C02

Policy No. DMCVSN3000201800

Accident Date 01/01/2020

Inspection Date 15/01/2020

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | | | |
|---|---|---|--------------------|------------|--|--|--|--|
| CHIN | NA TAIPING INSURANCE (S) PTE LTD Ref: CC6/CTI20000915/Uda3q2 | | | | | | | |
| 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | Date: 19-10-2020 Code: CTI | | | | | | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | | |
| | Insured Veh. | GBC 25P | Veh. Inspected | SLC 4489P | | | | |
| | Policy No. | DMCVSN3000201800 | Coverage (\$) | 0.00 | | | | |
| | Claim No. | SNM20D200037/C02 | Excess (\$) | 0.00 | | | | |
| | Assign From | | Assign Date | 15/01/2020 | | | | |
| 2. | | Vehicle Partic | culars & Condition | | | | | |
| | Make & Model | B.M.W 520I (A) | c.c | 1997 | | | | |
| | Engine No. | HIDDEN | Year of Reg. | 2016 | | | | |
| | Chassis No. | WBA5A32050D829136 | Colour | GREY | | | | |
| | Odometer | 72677 | Steering | IN ORDER | | | | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | | | | |
| | General | GOOD | | | | | | |
| 3. | | Condition | ons of Tyres | | | | | |
| | | Size | Make | Balance | | | | |
| | R/H Front Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | | | | |
| | L/H Front Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | | | | |
| | R/H Rear Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | | | | |
| | L/H Rear Tyre | 225/55 R17 | BRIDGESTONE | 6 mm | | | | |
| 4. | | • | on of Damages | | | | | |
| | THE VEHICLE SUS | STAINED DAMAGES AT THE FRO | ONT PORTION. | | | | | |
| | DAMAGES SEE DI | ETAILS. | | | | | | |
| 5. | | General | Information | | | | | |
| | Accident Date | 01/01/2020 | Inspection Date | 15/01/2020 | | | | |
| | Survey held at | eld at LEE BROTHERS AUTOMOTIVE PTE LTD | | | | | | |
| | | 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883 | | | | | | |
| 5a. | | Re | emarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | | |
| 5b. | | | | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 4489P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|----------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER | DISTORTED | 1,550.00 | 1,550.00 |
| 1 | FRONT BUMPER EMBLEM LOGO | SCRATCHED | 79.50 | 79.50 |
| 2 | FRONT BUMPER PDC SENSOR @\$348.15 | O/S SHORTED | 696.30 | 295.00 |
| 1 | FRONT BUMPER LOWER CENTRE GRILLE | NOT NECESSARY | 99.15 | - |
| 1 | FRONT BUMPER TOP HOLDER | CRACKED | 171.23 | 171.23 |
| 1 | FRONT BUMPER TOP RUBBER | NECESSARY | 115.00 | 115.00 |
| 1 | FRONT BUMPER FOAM | TORN | 199.08 | 199.08 |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | 684.75 | - |
| 1 | FRONT BUMPER INNER AIR VENT | TORN | 293.50 | 293.50 |
| 2 | FRONT BUMPER SIDE RETAINER RH/LH @\$39.30 | NOT NECESSARY | 78.60 | - |
| 2 | FRONT GRILLE RH/LH @\$165.00 | CRACKED | 330.00 | 330.00 |
| 2 | FRONT HEADLAMP RH/LH @\$2662.90 | O/S SCRATCHED | 5,325.80 | 2,662.90 |
| | LESS 5% DISCOUNT | | -481.15 | -284.81 |
| | | | 9,141.76 | 5,411.40 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET FRONT NUMBER PLATE WITH CASING (SN) | BENT | 50.00 | 40.00 |
| 1 | SET FRONT BUMPER CLIPS (SN) | NECESSARY | 45.00 | 45.00 |
| | | | 95.00 | 85.00 |
| | <u>LABOUR</u> | | | |
| | TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS. | | 350.00 | 250.00 |
| | TO SPRAY PAINTING ON ACCIDENT PORTION. | | 350.00 | 250.00 |
| | TO CHECK WIRING. | | 30.00 | 20.00 |
| | | | 730.00 | 520.00 |
| | GRAND TOTAL | | 9,966.76 | 6,016.40 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 4,800.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CC6/CTI20000915/Uda3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 4489P



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 4489P







