

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20000931/KQD3E2

Date: 28/07/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKV686A

Insured Vehicle No : GBF7486H

Date of Loss: 12/01/2020

Nature of Claim:

TP

Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV686A**

Make &amp; Model: M.G. MGA 1600, 1.6 (M)

Engine No: 15GDUH4561

Reg. Date: 12/09/1959 (Man. Year: 1959)

Chassis No: GHN74866

Colour: Metallic Red

Odometer: 5719 km

Engine Capacity: 1588 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 165/80 R15

Rear Tyre Size:

165/80 R15

Front Left Side: Toyo 9 mm

Rear Left Side:

Toyo 9 mm

Front Right Side: Toyo 9 mm

Rear Right Side:

Toyo 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,445.00	2,445.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,750.00	250.00	12.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,445.00</b>	<b>4,195.00</b>	<b>250.00</b>	<b>5.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,300.00</b>		
<b>(S\$)</b>	4,445.00	3,300.00	1,145.00	25.76
<b>+ GST 7.00/7.00% (S\$)</b>	311.15	231.00	80.15	25.76
<b>Nett Amount (S\$)</b>	<b>4,756.15</b>	<b>3,531.00</b>	<b>1,225.15</b>	<b>25.76</b>

### INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 31/01/2020 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #04-01, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 8.0 days

---

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2020)
<b>Parts:</b>	M1-COUPE	M.G. MGA 1600 1.6 (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKV686A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER BEADING LH	Necessary	150.00 F	*150.00 F
2	1		*REAR FENDER BEADING RH	Necessary	150.00 F	*150.00 F
3	2		*REAR TAIL LAMP GASKETS	Necessary	120.00 F	*120.00 F
4	1		*REAR BUMPER ASSY	Bent	2,000.00 F	*2,000.00 F
5	1		*REAR NUMBER PLATE	Necessary	25.00 FS	*25.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>2,445.00</b>	<b>2,445.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE + REFIX REAR TAIL LAMPS (x2) + REAR FENDERS LH & RH (FOR RESPRAY PURPOSE)	New	400.00	400.00
2	TO KNOCK DENTS ON REAR END PANEL AND RENEW OF PARTS	New	400.00	350.00
3	TO SPRAY PAINT	New	1,200.00	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>2,000.00</b>	<b>1,750.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**