

ASS. REC. BY:

REF: CS/MSG 20000933/kyf3ⁿ²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tan Goh Ing of MSIG

Date/Time: 15.1.2020 13.56 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 6074

Insured: YK 81924

at Workshop m/s Chung Hoi Motor

Tel: 6755 6142

of BIK 1019 # 01-374/382 Yishun Ind Park A

Policy No: B29021585 TMV

Claim No: 617485

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp1

H.O.D. Endorsement

Date/Time: 15.1.2020 2.05 p.m

Person Contacted:

Fidah

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBF 6074 - X
	YK 81924 - NA/MSG 20000690/r3 DOM - 09/01/2020

ASS. REC. BY:

REF: MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF-6074 Yr Regn: 06, 16Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /

Truck / Trailer or _____ 2853

Make: NIS Corolla c.c. 2800Colour: White A/C: Insured / Std / NI / NASp. Reading: 147149 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2F2480858723Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 175/80R15R: 155R12 X 80

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 9/1/20

Survey held at

Rear

R/Bal. 55 mmL/Bal. 35 mmD.O.I. 6/3/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ US \$1150/- (Red \$386-91, 25%)

17/3 Sent Rele by Merimen

RECEIVED 17 MAR 2020

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

17/3/20 TypistDays Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

\$1150/-

161

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 17 Mar 2020

Preliminary Advice

Insured Vehicle No	: YK8192Y	Accident Date	: 09/01/2020
TP Vehicle No	: GBF607U	Assignment Date	: 15/01/2020
Make	: NISSAN CABSTAR	Est. Duration of Repair	: 3.00
Date of Inspection	: 06/03/2020		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,644.49
Revised Amount	:S\$	1,441.91
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,441.91

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2020		15 Jan 2020 13:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GITI TIRE GLOBAL TRADING PTE LTD , Co. Reg. No.: 200208873N		
Main Claimant:	800 SUPER WASTE MANAGEMENT PTE LTD , Co. Reg. No.: 198601155H		
Vehicle Reg. No.:	GBF607U	Date of Loss:	09/01/2020 13:00 - :59 [8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 617485	Policy/Cover Note No.:	B29021585TMV (Third Party Only) Coverage: 01/12/2019 - 30/11/2020
Vehicle Reg. No. (Insured):	YK8192Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/01/2020]		
Driver/Custodian (Insured):	SOH KIM MENG (), NRIC: S0099285B, Tel: +6583812542 Email:		
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 15/01/2020, (Manual Assign). Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd, Contact: June @ 6755 6142.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Date Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	155H

Vehicle Details

Vehicle No.:	GBF607U
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	ZD30012215N
Chassis No.:	JN1SC2F24Z0858723
Maximum Power Output:	-
Open Market Value:	\$24,867.00
Original Registration Date:	06 Jun 2016
First Registration Date:	06 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$1,244.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	05 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,302.00
COE Rebate Amount:	\$27,088.00
Total Rebate Amount:	\$27,088.00

The information contained herein is correct as at 10 Jan 2020

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF6074
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 09/01/2020

TP Veh Reg No: YK8192Y

Estimate No: ES2090219/YISHUN

Date: 06 Mar 2020

Policy No: 5109900713

Veh Reg No: GBF607U

Make/Model: NISSAN CABSTAR 3.0

Chassis No: JN1SC2F24Z0858723

Engine No: ZD30012215N

Reg. Date: 06/06/2016

Estimate Repair Cost to Vehicle No :GBF607U

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT RH SIDE MIRROR SQUARE	183.20	1 PC	183.20	✓
2 TAILGATE RH SAFETY LOCK	33.30	1 PC	33.30	—
3 TAILGATE RH OPENNER	163.40	1 PC	163.40	✓
4 REAR TRUCK RAILING	350.00	1 PC	350.00	✓ S/N
			729.90	
	Less 10%		72.99	656.91
Labour				
5 REMOVE & REFIX REAR TRUCK RH SIDE GATE,REPLACE TAILGATE RH SIDE LOCK & OPENNER	400.00	1 LA	400.00	350
6 PUTTY & RESPRAY RH SIDE GATE,TAILGATE	480.00	1 LA	480.00	400
			880.00	880.00
			Total	S\$ 1,536.91
			Add GST @ 7%	107.58
			Total Amount Payable	S\$ 1,644.49

Parti #379.90N
Less 10% 37.99
#341.91
350 SN
750
#1441.91
#1150/ ✓ dc

For Cheng Hoe Motor Pte Ltd

1571.91

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF6074
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 09/01/2020

TP Veh Reg No: YK8192Y

Estimate No: ES2090219/YISHUN

Date: 06 Mar 2020

Policy No: 5109900713

Veh Reg No: GBF607U

Make/Model: NISSAN CABSTAR 3.0

Chassis No: JN1SC2F24Z0858723

Engine No: ZD30012215N

Reg. Date: 06/06/2016

Estimate Repair Cost to Vehicle No :GBF607U

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT RH SIDE MIRROR SQUARE	183.20	1 PC	183.20	✓
2 TAILGATE RH SAFETY LOCK	33.30	1 PC	33.30	✓
3 TAILGATE RH OPENER	163.40	1 PC	163.40	✓
4 REAR TRUCK RAILING	350.00	1 PC	350.00	✓
			729.90	
		Less 10%	72.99	656.91
Labour				
5 REMOVE & REFIX REAR TRUCK RH SIDE GATE, REPLACE TAILGATE RH SIDE LOCK & OPENER	400.00	1 LA	400.00	350
6 PUTTY & RESPRAY RH SIDE GATE, TAILGATE	480.00	1 LA	480.00	400
			880.00	880.00
			Total	S\$ 1,536.91
			Add GST @ 7%	107.58
			Total Amount Payable	S\$ 1,644.49

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000933/KYF3N2
Date: 20/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29021585TMV

Claimant Vehicle
No: GBF607U

Insured Vehicle No: YK8192Y

Date of Loss: 09/01/2020

Nature of Claim: TP

Claim No: 617485

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF607U
Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)
Reg. Date: 06/06/2016 (Man. Year: 2016)
Colour: White
Engine Capacity: 2953 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

Engine No: ZD30012215N
Chassis No: JN1SC2F24Z0858723
Odometer: 147149 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Footbrake (Serviceable): Yes
Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/80R15
Front Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm
Rear Tyre Size: 155R12X8 (D)
Rear Left Side: Yokohama 5/5 mm
Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	691.91	691.91	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	750.00	130.00	14.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,571.91	1,441.91	130.00	8.27
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	1,571.91	1,150.00	421.91	26.84
+ GST 7.00/7.00% (S\$)	110.03	80.50	29.53	26.84
Nett Amount (S\$)	1,681.94	1,230.50	451.44	26.84

INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 06/03/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Mar 2020)		
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBF607U)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH SIDE MIRROR SQUARE	Broken	183.20 FN	*183.20 FN
2	1		*TAILGATE RH SAFETY LOCK	Dented	33.30 FN	*33.30 FN
3	1		*TAILGATE RH OPENNER	Distorted	163.40 FN	*163.40 FN
4	1		*REAR TRUCK RAILING	Bent	350.00 FS	*350.00 FS
					Sub Total (S\$)	729.90
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	37.99
					Total Parts (S\$)	691.91

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR TRUCK RH SIDE GATE,REPLACE TAILGATE RH SIDE LOCK & OPENNER	New	400.00	350.00
2	PUTTY & RESPRAY RH SIDE GATE,TAILGATE	New	480.00	400.00
Gross Labour Cost (S\$)			880.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >