

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000937/KRA3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994189
Claimant Vehicle No :	SBW8288P	Insured Vehicle No :	SMK5203L
Date of Loss:	12/01/2020	Nature of Claim:	TP
		Claim No:	9191274288SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBW8288P		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030954071
Reg. Date:	26/07/2017 (Man. Year: 2017)	Chassis No:	WDD2050402R281279
Colour:	White	Odometer:	29726 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,760.00	3,032.33	5,727.67	65.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,810.00	750.00	29.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,320.00	4,842.33	6,477.67	57.22
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		

(S\$)	5,242.33
Liable Amount (50.00%) (S\$)	2,621.17
+ Doc/Search Fee (S\$)	7.45
Nett Liability (S\$)	2,628.62

INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 15/01/2020 Inspected At:

Seng Kin Motor Works (HQ)
BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636
Singapore 575636

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT N/S DOOR	Bent	1,920.00 FN	*1,755.73 FN
2	1		*FRT N/S DOOR LOWER MOULDING	Necessary	115.00 FN	*115.00 FN
3	1		*FRT N/S DOOR RUBBER	Necessary	325.00 FN	*270.00 FN
4	1		*FRT N/S DOOR OUTER HANDLE	Serviceable	515.00 FN	*- FN
5	1		*REAR N/S DOOR	Repair	2,380.00 FN	*- FN
6	1		*REAR N/S DOOR LOWER CHROME MOULDING	Necessary	75.00 FN	*75.00 FN
7	1		*REAR N/S DOOR RUBBER	Serviceable	325.00 FN	*- FN
8	1		*REAR N/S DOOR OUTER HANDLE	Serviceable	515.00 FN	*- FN
9	1		*REAR BUMPER	Repair	1,740.00 FN	*- FN
10	1		*RIVERT (30 PCS)	Necessary	105.00 FN	*105.00 FN
11	1		*REAR N/S TYRE SPORT RIM (LOCAL REPAIR)	Scratched	660.00 FS	*150.00 FS
12	1		*FRT N/S FENDER	Bent	985.00 FN	*881.86 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	9,660.00	3,352.59
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	900.00	320.26
Total Parts (\$\$)	8,760.00	3,032.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE FRT N/S DOOR GLASS DOOR DOOR LOCK MECHANISM ,TRANSFER PARTS TO NEW DOOR	New	80.00	80.00
2	LABOUR CHARGES TO REMOVE REAR N/S DOOR GLASS DOOR LOCK MECHANISM TRANSFER PARTS TO NEW DOOR	New	80.00	0.00
3	LABOUR CHARGES TO KNOCK & STRAIGHTEN REAR N/S FENDER ,AND DISTORTED PARTS .TO REMOVE BODY DAMAGED PARTS REPLACE NEW & REFIX SAME	New	800.00	600.00
4	TO PUTTY AND SPRAY PAINTING	New	1,500.00	1,100.00
5	TO SPRAY UNDERSEAL	New	100.00	30.00
Gross Labour Cost (\$\$)			2,560.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >