Page 1 of 5 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000939/EQD3E2

Date: 03/03/2020

REFERENCE

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSN30445619055

Claimant Vehicle SMM3846J

Insured Vehicle SGL189T No:

Date of Loss: 10/01/2020 Nature of Claim: TP

Claim SNM20D200177C02 No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM3846J

LAND ROVER RANGE ROVER EVOQUE, 2.0 TSS Make & Model:

Reg. Date: 22/07/2015 (Man. Year: 2015) Engine No: 010914123218204PT

Chassis No: SALVA2AG4FH046184 Odometer: 39102 km

Colour: White

1999 cc **Engine Capacity:**

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 235/60 R18 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,899.60	2,098.30	3,801.30	64.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,440.00	1,530.00	5,910.00	79.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,339.60	3,628.30	9,711.30	72.80
+ GST 7.00/7.00% (S\$)	933.77	253.98	679.79	72.80
Nett Amount (S\$)	14,273.37	3,882.28	10,391.09	72.80

INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 16/01/2020 Inspected At: Wearnes Automotive Pte Ltd

> 45 Leng Kee Road Singapore 159103

Estimated Period of Repair: 1.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen p... 3/3/2020

Adjuster Report Page 2 of 5

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$413.20 NETT) Adjuster Report Page 4 of 5

REPAIR DETAILS

Reference			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2020)	
Parts:	M1-SUV	LAND ROVER RANGE ROVER EVOQUE 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	: (Unsubmitted, no print-code for SMM3846J)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LLR058060/BUMPER - R	Not Necessary	2,705.60 FS	*- FS
2	1		*BRACKET - BUMPER MOU	* Check	62.10 FS	*-FS
3	1		*BUMPER BRACKET REAR	* Check	122.80 FS	*-FS
4	1		*LLR048461/WHEEL - AL	Cut	1,830.90 FS	*1,830.90 FS
5	1		*DOOR TRIM REAR RH EV	Cut	64.40 FS	*64.40 FS
6	1		*WHEEL MOULDING REAR	Cut	203.00 FS	*203.00 FS
7	1		*LLR053218/MOULDING -	* Check	228.30 FS	*-FS
8	1		*ADHESIVE SEALER FL2	Not Necessary	682.50 FS	*-FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	5,899.60	2,098.30

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	TO REPLACE REAR BUMPER, QUARTER PANEL MOULDING RH, REAR DOOR MOULDING RH, REAR DOOR LOWER MOULDING RH, REPAIR REAR DOOR RH, ETC	New	3,600.00	1,200.00			
2	TO PUTTY SPRAYPAINT AND BLENDING OF PAINT ON REAR BUMPER, REAR DOOR RH, ETC	R New	3,000.00	0.00			
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	510.00	0.00			
4	TO REPLACE REAR RIM RH	New	50.00	50.00			
5	WHEEL ALIGNMENT	New	280.00	280.00			
	Gross Labou	ır Cost (S\$)	7,440.00	1,530.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >