

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20000941/KPS3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMF9487J	Insured Vehicle No :	SHD3162E
Date of Loss:	08/01/2020	Nature of Claim:	TP
		Claim No:	MCT20010156

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9487J	Engine No:	HRA2339254A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Chassis No:	SJNFEAJ11U1800169
Reg. Date:	20/12/2016 (Man. Year: 2016)	Odometer:	50582 km
Colour:	Metallic Blue		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,634.28	1,634.28	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	600.00	160.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,394.28	2,234.28	160.00	6.68
+ GST 7.00/7.00% (S\$)	167.60	156.40	11.20	6.68

Nett Amount (S\$)	2,561.88	2,390.68	171.20	6.68
		+ Medical Costs (S\$)	375.60	
		+ Car Rental (3.0 x S\$100.00/day) (S\$)	300.00	
		+ Doc/Search Fee (S\$)	7.49	
		Nett Liability (S\$)	3,073.77	

INSPECTION

Date of Assignment: 14/01/2020

Date Inspected: 14/01/2020

Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #04-01, Sin Ming AutoCity
 Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference

Recommended Parts

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER REVERSING SENSOR	New	60.00	60.00
2	TO DISMANTLE +RENEW ABOVE PARTS	New	400.00	300.00
3	TO SPRAY PAINT	New	300.00	240.00
Gross Labour Cost (\$\$)			760.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >