



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2008085  
INV Date 02/12/2020  
Reference CC4/EQI20000943/Kpa3q2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SLJ 2624S  
Insured Veh. SJM 36K  
Claim No. DM20HO00121-JG  
Policy No. DMPPHQ19-007137  
Accident Date 13/01/2020  
Inspection Date 14/01/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

EQ INSURANCE COMPANY LTD	Ref : CC4/EQI20000943/Kpa3q2
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110	Date : 02-12-2020
	Code : EQI



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SJM 36K	<b>Veh. Inspected</b>	SLJ 2624S
<b>Policy No.</b>	DMPPHQ19-007137	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM20HO00121-JG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOEL	<b>Assign Date</b>	14/01/2020

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	TOYOTA PRIUS (A)	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JTDKB3FU003538307	<b>Colour</b>	METALLIC SILVER
<b>Odometer</b>	165988	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	YOKOHAMA	8 mm
<b>L/H Front Tyre</b>	195/65 R15	YOKOHAMA	8 mm
<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	8 mm
<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	8 mm

**4. Description of Damages**

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.
--	---------------------------------------------------------------------------------------------------

**5. General Information**

<b>Accident Date</b>	13/01/2020	<b>Inspection Date</b>	14/01/2020
<b>Survey held at</b>	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

**5a. Remarks**

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	----------------------------------------------------------------------------------------------------------------------------------------

**5b. Estimate Days of Repair**

	ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
--	-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2624S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT SUPPORT PANEL RH	TO REPAIR SEE LABOUR	213.50	-
1	HEADLAMP PANEL RH	TO REPAIR SEE LABOUR	89.20	-
1	HEADLAMP RH	MTG CRACKED	2,531.60	2,531.60
1	FRONT BUMPER	CRACKED	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	107.20	107.20
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	107.20	-
1	FRONT BUMPER UPPER GRILLE	SERVICEABLE	321.90	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	148.60	-
1	FOG LAMP RH	MISSING	910.70	910.70
1	WASHER TANK	CRACKED	195.60	195.60
1	WASHER TANK MOTOR	SERVICEABLE	196.74	-
1	ENGINE UNDER COVER RH	CRACKED	87.70	87.70
1	RH FRONT FENDER	BENT	868.70	868.70
1	RH FRONT FENDER UNDERSHIELD	CRACKED	185.64	185.64
10	RH FRONT FENDER UNDERSHIELD CLIP	NECESSARY	25.00	25.00
1	RHF FENDER WORDING "HYBRID"	NECESSARY	44.17	44.17
1	RH FRONT FENDER QUARTER GARNISH	MISSING	122.70	122.70
1	RH FRONT LOWER ARM	SERVICEABLE	492.65	-
1	RH FRONT SHOCK ABSORBER	SERVICEABLE	462.70	-
1	RH FRONT SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	195.07	-
1	RH FRONT SHOCK ABSORBER STOPPER	SERVICEABLE	37.02	-
1	RH FRONT KNUCKLE ARM	SERVICEABLE	476.75	-
1	RH FRONT KNUCKLE BEARING }	SERVICEABLE	573.20	-
1	RH FRONT WHEEL HUB }		-	-
1	RH FRONT WHEEL HUB LOCK NUT	NOT NECESSARY	28.02	-
1	RH FRONT TIE ROD END	SERVICEABLE	116.40	-
1	RH FRONT HUB CAB	SERVICEABLE	195.62	-
1	RH FRONT RIM	DENTED	1,555.10	1,555.10

Report Ref No. CC4/EQI20000943/Kpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,694.87	-1,781.23
			8,084.61	5,343.68
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	RH FRONT TYRE (SN)	SERVICEABLE	250.00	-
			250.00	-
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHF DOOR,BONNET,SUPPORT PANEL).INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL RH AND HEADLAMP PANEL RH.		1,000.00	400.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,RHF FENDER,RHF DOOR,BONNET,SUPPORT PANEL).		1,200.00	600.00
	TO CHECK WIRING,FOCUS HEADLAMP.		50.00	20.00
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO TUFF COAT.		150.00	30.00
	TOWING.		60.00	50.00
			2,830.00	1,160.00
	<b>GRAND TOTAL</b>		<b>11,164.61</b>	<b>6,503.68</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,200.00</b>

Report Ref No. CC4/EQI20000943/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 2624S

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 2624S

RE-INSPECTION

