

ASS. REC. BY:

REF: 2Q/

943/104

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Estium

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ 26245 Yr Regn: 12, 16

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Prox c.c. 1788

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 165988 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB 3FU003538307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insider / Jammed / Leaked / Burnt or

Brake: Insider / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 8 mm

Rear R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 13/1/20 D.O.I. 14/1/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

OLS FR & UL

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

\$ - RS. SI

Fuel/OS

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Not Authorized
11 Aug 07
Resurvey After Paint

Repair Estimates

SLJ 2624 S

Parts	(a) Cost / List Price Items	\$	10,779.48
	Plus/Less 25%	\$	2,694.87
	Total of Cost / List	\$	8,084.61
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	8,334.61
Labour		\$	2,830.00
Total		\$	11,164.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 14/1/20 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 05 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : [Signature] Date: 14/1/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemp.com.sg

Spare Parts

Vehicle No. : SLJ 2624 S
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU003538307

Submit By : JENNY
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front support panel RH	1	\$213.50		?
2	Headlamp panel RH	1	\$89.20		X
3	Headlamp RH	1	\$2,531.60		✓
4	Front bumper	1	\$450.80		✓
5	Front bumper clip	10	\$40.00		✓
6	Front bumper side retainer RH	1	\$107.20		✓
7	Front bumper side retainer LH	1	\$107.20		X
8	Front bumper upper grille	1	\$321.90		X
9	Front bumper lower grille	1	\$148.60		X
10	Fog lamp RH	1	\$910.70		✓
11	Washer tank	1	\$195.60		✓
12	Washer tank motor	1	\$196.74		?
13	Engine under cover RH	1	\$87.70		✓
14	RH front fender	1	\$868.70		✓
15	RH front fender undershield	1	\$185.64		✓
16	RH front fender undershield clip	10	\$25.00		✓
17	RHF fender wording "HYBRID"	1	\$44.17		✓
18	RH front fender quarter garnish	1	\$122.70		✓
19	RH front lower arm	1	\$492.65		?
20	RH front shock absorber	1	\$462.70		?
21	RH front shock absorber top mouting	1	\$195.07		?
22	RH front shock absorber stopper	1	\$37.02		?
23	RH front knuckle arm	1	\$476.75		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLJ 2624 S
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU003538307

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front knuckle bearing]	1	\$573.20		?
25	RH front wheel hub	1			
26	RH front wheel hub lock nut <i>nn</i>	1	\$28.02		X
27	RH front tie rod end	1	\$116.40		?
28	RH front hub cap	1	\$195.62		?
29	RH front rim <i>nd</i>	1	\$1,555.10		✓
30	RH front tyre	1	\$250.00	S.N	?
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLJ 2624 S Submit By : Carmen Lim
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RHF DOOR, BONNET,SUPPORT PANEL)	\$1,000.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RHF DOOR, BONNET,SUPPORT PANEL)	\$1,200.00	600
3	To check wiring, focus headlamp	\$50.00	20
4	To remove & refit undercarriage to assist work load.	\$250.00	7
5	To do wheel alignment.	\$120.00	60
6	To tuff coat.	\$150.00	30
7	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.