

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000946/EVF3E2

Date: 10/09/2020

REFERENCE

Insured/Claimant: ANG HOCK LEONG (HONG FULIANG)	Policy No: 1700017523	
Date of Loss: 31/12/2019	Nature of Claim: OD	Claim No: 7657634820SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM6778B		
Make & Model: AUDI A4, 1.4 T (A)	Engine No: CVN038597	
Reg. Date: 14/06/2017 (Man. Year: 2017)	Chassis No: WAUZZZF44HA162874	
Colour: Grey	Odometer: 32907 km	
Engine Capacity: 1395 cc		
Market Value/New Car Price: S\$100,000.00		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18	Rear Tyre Size: 245/40 R18	
Front Left Side: Bridgestone 5 mm	Rear Left Side: Bridgestone 5 mm	
Front Right Side: Bridgestone 5 mm	Rear Right Side: Bridgestone 5 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,914.00	2,155.84	2,758.16	56.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,502.00	3,362.00	4,140.00	55.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,416.00	5,517.84	6,898.16	55.56
+ GST 7.00/7.00% (\$\$)	869.12	386.25	482.87	55.56
Nett Amount (\$\$)	13,285.12	5,904.09	7,381.03	55.56

INSPECTION

Date of Assignment: 15/01/2020		
Date Inspected: 15/01/2020	Inspected At: 281 ALEXANDRA ROAD	
	Repairer : Premium Automobiles Pte Ltd	
Estimated Period of Repair: 5.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Dented	2,152.00 FS	*1,721.60 FS
2	1		*REAR DOOR OUTER SEAL - RH	Necessary	185.00 FS	*147.60 FS
3	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
4	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
5	1		*SEALING STRIP	Necessary	15.00 FS	*12.08 FS
6	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	515.00 FS	*- FS
7	1		*REAR DOOR CATCH	Not Necessary	109.00 FS	*- FS
8	1		*DOOR HANDLE TRIM PLATE - RH	Not Necessary	80.00 FS	*- FS
9	1		*WINDOW REGULATOR	Not Necessary	250.00 FS	*- FS
10	1		*WINDOW REGULATOR MOTOR	Not Necessary	309.00 FS	*- FS
11	1		*ALUMINIUM RIM - RHR	Not Necessary	609.00 FS	*- FS
12	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
13	1		*SUNDRIES	Necessary	400.00 FS	*6.96 FS
					Total Parts (\$\$)	4,914.00 2,155.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. CHECK FUNCTION AND RENEW IF NECESSARY	New	280.00	280.00
2	TO DISMANTLE AND RENEW RHS REAR DOOR. TO REPAIR RHS FRONT DOOR, RHS SILL PANEL AND RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	240.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	300.00	0.00
6	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL AND RHS FENDER	New	4,000.00	1,650.00
Gross Labour Cost (S\$)			7,502.00	3,362.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >