



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102729

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 19/04/2021  
Reference CC6/CTI20000947/Kea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SKS 9694H  
Insured Veh. PA 5005J  
Claim No. SNM20D200150  
Policy No. DMB1SN3064171900  
Accident Date 09/01/2020  
Inspection Date 14/01/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20000947/Kea3q2	
			Date: 19/04/2021	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PA 5005J	Veh. Inspected	SKS 9694H	
Policy No.	DMB1SN3064171900	Coverage (\$)	0.00	
Claim No.	SNM20D200150	Excess (\$)	0.00	
Assign From		Assign Date	14/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU LEGACY (A)	c.c	2498	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JF1BN9KC2FG003329	Colour	METALLIC GREY	
Odometer	120810 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	235/50 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	235/50 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	235/50 R18	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/01/2020	Inspection Date	14/01/2020	
Survey held at	K KIM HIN AUTO PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9694H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BENT	594.00	594.00
1	FRONT BUMPER SPONGE	SERVICEABLE	57.60	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	288.30	-
2	FRONT BUMPER SIDE RETAINER (LH/RH) @\$18.30	N/S DISTORTED	36.60	18.30
1	N/S FRONT BUMPER FOG LAMP	SERVICEABLE	272.00	-
1	N/S FRONT BUMPER FOG LAMP COVER	SERVICEABLE	50.40	-
1	N/S FRONT BUMPER SPRAY NOZZLE	CRACKED	86.40	86.40
1	N/S FRONT BUMPER SPRAY NOZZLE PUMP	CRACKED	160.00	160.00
1	N/S FRONT BUMPER SPRAY NOZZLE COVER	SERVICEABLE	54.30	-
1	N/S FRONT BUMPER TOP SEAL	NECESSARY	27.00	27.00
1	FRONT BUMPER CENTRE BRACKET-LOWER	SERVICEABLE	57.60	-
10	FRONT BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	N/S HEAD LAMP ASSY	MTG BROKEN	1,870.00	1,870.00
1	N/S HEAD LAMP LOWER BRACKET	DISTORTED	32.80	32.80
1	N/S FRONT FENDER	BUCKLED	270.00	270.00
1	N/S FRONT FENDER INNER SHIELD	SERVICEABLE	108.00	-
10	N/S FRONT FENDER INNER SHIELD CLIPS @\$3.50	NOT NECESSARY	35.00	-
1	N/S FRONT FENDER TOP GARNISH	DEFORMED	18.00	18.00
1	WIPER WASHER TANK	SERVICEABLE	97.20	-
1	WIPER WASHER TANK MOTOR	SERVICEABLE	68.40	-
1	WIPER WASHER TANK MOTOR BUSH	SERVICEABLE	4.50	-
1	BATTERY COVER	SERVICEABLE	30.40	-
1	BATTERY BRACKET	TO REPAIR SEE LABOUR	14.40	-
	LESS 20% DISCOUNT		-853.58	-622.30
			3,414.32	2,489.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BATTERY (SN)	SERVICEABLE	280.00	-
			280.00	-

Report Ref No. CC6/CTI20000947/Kea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND BATTERY BRACKET.		400.00	360.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	500.00
	TO FOCUS HEADLAMPS.TO CHECK FRONT WIRING AND LIGHTING OPERATION.		30.00	20.00
			1,030.00	880.00
<b>GRAND TOTAL</b>			<b>4,724.32</b>	<b>3,369.20</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,369.20</b>

Report Ref No. CC6/CTI20000947/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SKS 9694H**

**INSPECTION**







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKS 9694H

### RE-INSPECTION

