

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000948/KES3Q2

Date: 04/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SGB7373J

Insured Vehicle No : SMH2663C

Date of Loss: 13/01/2020

Nature of Claim: TP

Claim No: 3187803158SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGB7373J**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4023416

Reg. Date: 26/11/2015 (Man. Year: 2015)

Chassis No: RU11103411

Colour: Metallic Grey

Odometer: 67331 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Yokohama 4 mm

Rear Left Side:

Yokohama 4 mm

Front Right Side: Yokohama 4 mm

Rear Right Side:

Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,450.00	1,284.00	1,166.00	47.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,220.00	630.00	34.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,300.00	2,504.00	1,796.00	41.77
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,804.00		

INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 15/01/2020 Inspected At:

Jin Huat & Co (HQ)

176 SIN MING DRIVE #05-01, SIN

MING AUTOCARE

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR T/GATE	Bent	860.00 F	*860.00 FL
2	1		*REAR T/GATE LOCK	Repair	185.00 F	*- FL
3	1		*REAR BUMPER	Bent	365.00 F	*365.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Serviceable	40.00 F	*- FL
5	1		*REAR END PANEL	Repair	620.00 F	*- FL
6	1		*REAR BUMPER SENSOR	Dented	120.00 F	*120.00 FL
7	1		*REAR W/SCREEN MOULDING	Necessary	260.00 F	*260.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,450.00	1,605.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	321.00
Total Parts (\$)	2,450.00	1,284.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR & REPLACE PARTS	New	950.00	500.00
2	TRANSFER REAR W/SCREEN	New	150.00	120.00
3	SPRAY PAINTING	New	750.00	600.00
Gross Labour Cost (\$\$)			1,850.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >