

ASS. REC. BY:

REF: CS/UOI 20000954/ Dtd 3/12/2020 Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Josephine Wong of UOI Date/Time: 15/01/2020 @ 2:45pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 3110R Insured: SKW 63A1E

at Workshop in/s: Bifrost Auto Tel: 9792 1329

of Blk 9 Sector C # 01-42 Sin Ming Ind. Est.

Policy No: Claim No: M12D12612001

Sum Insured: Excess:

Make of Veh: D.O.A. 13/01/2026
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:42pm @ 15/1/2020 Person Contacted: Ms. Lee Vehicle IN/OUT

Date/Time	Action/Instruction
	Johny / ✓
	SHB 3110R - X
	SKW 63A1E - X

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SHB 31102

Yr Regn:

2017 May

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

290374

T/Radio:

Insured / Std / NI / NA

Eng/No:

2ZR3044656

C/No:

5TDKB3FU203557487

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Devanti

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

13/01/2020

D.O.I.

16/01/2020

Survey held at

Brigist Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rent y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

UOI SKW 6391E

11/02/2020

Inspected 2/5 13900/- with 9 days of repair (led. 4375.84; 23%)

RECEIVED 12 FEB 2020

Date/Time, File Pass 1/2



Preli. Report



Final Report

12/2 Typst

Date/Time, File Return 1/2

3

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

3 x \$5 = \$15

Photos 500

Others

TOTAL

26 x 25 = 650

250 + 650

60

80

220

1260

Report Format:

Lump 0

TP

13900

Nivitha (LKK Auto)

From: WONG JOSEPHINE <josephinewong@uoi.com.sg>
Sent: Wednesday, 15 January 2020 2:45 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: claims_ltm@bifrostauto.com; LEE KATIE
Subject: FW: FW: RE : PRS FOR OUR CLIENT SHB 3110 R and your insured's vehicle SKW 6391 E on 13.01.2020. Survey Vehicle
Attachments: TP SAS SHB3110R.zip

Without Prejudice

Dear LKK

Please attend to the survey.

Details of survey as email below. Thanks .

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9029 | Fax • (65) 6327 3889 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Claims Dept [mailto:claims_ltm@bifrostauto.com]
Sent: Wednesday, January 15, 2020 2:27 PM
To: WONG JOSEPHINE <josephinewong@uoi.com.sg>; Assessment <claims@bifrostauto.com>; Claims Dept <claims_ltm@bifrostauto.com>
Subject: Re: FW: RE : PRS FOR OUR CLIENT SHB 3110 R and your insured's vehicle SKW 6391 E on 13.01.2020.

WITHOUT PREJUDICE

Hi,

We select LKK Consultants.

Pls assign them asap.

Ms Lim
Bifrost Auto Pte Ltd
Accident Claims Dept

From: Claims Dept [mailto:claims_ltm@bifrostable.com]

Sent: Tuesday, 14 January, 2020 5:25 PM

To: LEE KATIE <katielee@uoi.com.sg>

Cc: Assessment <claims@bifrostable.com>; Claims Dept <claims_ltv@bifrostable.com>

Subject: RE : PRS FOR OUR CLIENT SHB 3110 R and your insured's vehicle SKW 6391 E on 13.01.2020.

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Ng Chor Wah, to notify you of the aforesaid accident involving our client's vehicle SHB 3110 R and your insured's vehicle SKW 6391 E on 13.01.2020.

Please find enclosed our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SKW 6391 E for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle.

PLEASE LET US HAVE A LIST OF YOUR EXTERNAL SURVEYORS FOR OUR SELECTION AS A SINGLE JOINT EXPERT.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Singapore 575644

Contact Person: Ms Lim / Ms Lee

Contact Email: claims_ltv@bifrostable.com / claims_ltm@bifrostable.com

VEH JN (Date & Time)

: 14/01/2020

PRS ARRANGEMENT (Date & Time)

: AS SOON AS POSSIBLE

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank you.

You can protect our environment. Think before you print.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential.

The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it.

If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Denise Tay (LKKAuto)

From: WONG JOSEPHINE <josephinewong@uoi.com.sg>
Sent: Wednesday, 12 February 2020 11:53 AM
To: Denise Tay (LKKAuto); assignments; SUR
Cc: LEE KATIE
Subject: RE: FW: RE : PRS FOR OUR CLIENT SHB 3110 R and your insured's vehicle SKW 6391 E on 13.01.2020. Survey Vehicle

Claim ref no: M12D12612001

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

B EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, February 12, 2020 11:44 AM
To: WONG JOSEPHINE <josephinewong@uoi.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: FW: RE : PRS FOR OUR CLIENT SHB 3110 R and your insured's vehicle SKW 6391 E on 13.01.2020. Survey Vehicle

Dear Josephine,

Please provide your ref no. / claim no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2020 11:11
Date Of Accident	13/01/2020 14:10
Exact Location Of Accident	PIE TWDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB3110R
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	TAN MUI GEK
NRIC No	SXXXX387G
Date Of Birth	08/07/1964
Occupation	OUTDOOR
Date Of Driving Pass	16/08/1983
Driving Experience	36 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92705846
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 475A UPP SERANGOON CRESCENT #06-519
Postcode	531475
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW6391E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG PECK YEOK MARGARET
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	UNITED OVERSEAS INSURANCE LTD
Nature Of Damage	FRT

No. Of Passenger (Including Driver)


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLX97C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH CHOON HEONG PATRICK
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN MUI GEK
Approximate Age	56
Injuries Sustain	RIGHT LEG PAIN
Injured person in which vehicle?	SHB3110R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

A - 2HB31NR
B - 8KW639IE
C - 2LX97C



Along PIE TWDS Chinnai Before Eng NED Exit .

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13.01.2020 @ 14:40 hours . I was travelling along PIE TWDS Airport Before Eng NED Exit with one female Passenger onboard .

While travelling straight on the second lane from the Right , I see veh (C) 2LX97C in front of me slowed down and stopped I followed too . Suddenly I felt an impact from my taxi A - Rear Portion , causing my taxi to surge forward .

As it took place too fast I could not prevent .

After the accident I suffered pain at my leg area . will consult a doctor later on .

I have company video & photos at scene to support my claims .

DECLARATION

I/We declare the foregoing to be true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 16-Jan-20

INSURANCE:

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHB3110R

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>St</i>	1	\$1,126.60	✓
REAR TRUNK LID LOCK <i>Down</i>	1	\$457.90	✓
REAR TRUNK LID COVER TRIM BOARD <i>NH</i>	1	\$216.50	X
REAR TRUNK LID RUBBER <i>deformed</i>	1	\$365.20	✓
BOARD ASSY, BACK DOOR TRIM <i>NH</i>	1	\$254.40	X
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>Crack/broken</i>	1	\$889.70	✓
REAR TRUNK LID LOGO (PRIUS) <i>Nec</i>	1	\$60.80	✓
REAR TRUNK LID LOGO (HYBRID) <i>Nec</i>	1	\$52.40	✓
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Nec</i>	1	\$52.90	✓
REAR BUMPER <i>fine</i>	1	\$458.60	✓
REAR BUMPER RE-INFORCEMENT <i>Dented</i>	1	\$318.80	✓
REAR BUMPER UNDER COVER <i>fine</i>	1	\$552.60	✓
REAR BUMPER SIDE RETAINER <i>SN</i>	2	\$112.70	X
REAR BUMPER UNDER SIDE COVER (RH) <i>NH</i>	1	\$232.00	X
REAR BUMPER UNDER SIDE COVER (LH) <i>broken windy</i>	1	\$232.00	✓
REAR BUMPER UNDER SIDE CENTRE COVER <i>broken</i>	1	\$552.60	✓
REAR BUMPER TOWING COVER <i>distorted/broken</i>	1	\$82.70	✓
REAR BUMPER CLIPS <i>Nec</i>	1	\$22.00	✓
REAR BUMPER SIDE CLIP <i>NH</i>	1	\$25.00	X
ARM SUB-ASSY, REAR BUMPER, RH <i>NH</i>	1	\$139.60	X
ARM SUB-ASSY, REAR BUMPER, LH <i>NH</i>	1	\$139.60	X
RETAINER, REAR BUMPER, UPPER SIDE <i>NH</i>	1	\$30.70	X
RETAINER, REAR BUMPER, SIDE, RH <i>NH</i>	1	\$94.80	X
RETAINER, REAR BUMPER, SIDE, LH <i>NH</i>	1	\$94.80	X
SEAL, REAR BUMPER SIDE, RH <i>NH</i>	1	\$148.40	X
SEAL, REAR BUMPER SIDE, LH <i>Cond</i>	1	\$148.40	✓
TAIL LAMP ASSY (UPPER) <i>Crack/windy crack</i>	2	\$557.90	✓
TAIL LAMP ASSY (LOWER) <i>Crack/windy crack</i>	2	\$548.40	✓
TAIL LAMP QUARTER PANEL <i>Dented</i>	2	\$216.00	✓
TAIL LAMP SIDE COVER <i>NH</i>	2	\$256.00	X
LAMP ASSY, SIDE TURN SIGNAL, RH <i>NH</i>	2	\$65.30	X
LAMP ASSY, SIDE TURN SIGNAL, L H <i>NH</i>	2	\$65.30	X
BULB, BACK UP LAMP & REAR FOG LAMP, NO. 1 <i>NH</i>	2	\$4.90	X
BULB, REAR TURN SIGNAL LAMP <i>NH</i>	2	\$8.90	X
REAR END PANEL <i>fine</i>	1	\$602.10	✓
REAR END PANEL GARNISH <i>deformed/mounting deformed</i>	1	\$161.80	✓
REAR SPARE TYRE PANEL <i>Dented</i>	1	\$667.70	✓
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>NH</i>	1	\$101.40	X
REAR FIBER TOOL BOX TRIM <i>Scr</i>	1	\$398.00	X
REAR EXHAUST PIPE <i>Dented</i>	1	\$1,163.40	✓
REAR EXHAUST PIPE (FRONT) <i>NH</i>	1	\$2,966.20	X

REAR EXHAUST PIPE HANGER	NH	1	\$40.70	X
REAR EXHAUST PIPE INSULATOR	KT	1	\$314.60	✓
REAR FENDER, LH	Dented	1	\$836.70	✓
REAR FENDER, RH	Dented	1	\$836.70	✓
REAR FENDER OUTER PANEL, LH	NH	1	\$486.00	X
REAR FENDER OUTER PANEL, RH	NH	1	\$486.00	X
REAR FENDER SIDE PANEL	NH	2	\$165.00	X
REAR FENDER SHIELD (LH/RH)	NH	2	\$134.20	X
REAR FENDER TRIMBOARD (LH/RH)	1st dented	2	\$725.00	✓
REAR FLOOR PANEL SIDE (LH)	NH	1	\$276.20	X
REAR FLOOR PANEL SIDE (LRH)	NH	1	\$276.20	X
REAR FENDER AIR DUCT	NH	2	\$165.10	X
REAR WINDSCREEN GLASS W/ MOULDING	NH	1	\$1,778.30	X
REAR WINDSCREEN SEALANT	Hec	1	\$46.00	✓
RADIATOR GRILLE	Crack	1	\$438.00	✓
RADIATOR GRILLE EMBLEM	SVC	1	\$88.00	X
FRONT BUMPER COVER	mondy crack	1	\$499.90	✓
FRONT BUMPER REINFORCEMENT	NH	1	\$696.40	X
FRONT BUMPER REINFORCEMENT ABSORBER	NH	1	\$115.70	X
FRONT BUMPER LOWER REINFORCEMENT BRACKET	NH	1	\$330.00	X
FRONT BUMPER SPONGE	NH	1	\$78.80	X
FRONT BUMPER CENTRE GRILLE	NH	1	\$301.90	X
FRONT BUMPER LOWER GRILLE	Crack	1	\$148.60	✓
LAMP ASSY, FOG, RH	NH	1	\$920.00	X
LAMP ASSY, FOG, LH	NH	1	\$920.00	X
FRONT BUMPER CLIPS	Hec	1	\$22.00	✓
FRONT BUMPER SIDE RETAINER	NH	2	\$77.00	X
FRONT LOWER CROSSMEMBER	NH	1	\$357.70	X
FRONT UNDER COVER	NH	1	\$180.80	X
ENGINE UNDER COVER (RR)	NH	1	\$457.40	X
FRONT BUMPER TOP GARNISH	NH	1	\$225.40	X
REINFORCEMENT, FRONT BUMPER LOWER	NH	1	\$236.10	X
BRACKET, FRONT BUMPER EXTENSION MOUNTING	NH	1	\$110.40	X
SUPPORT FR BUMPER, RH	NH	1	\$81.70	X
SUPPORT FR BUMPER, LH	NH	1	\$81.70	X
FRONT BUMPER CENTRE FRAME	NH	1	\$236.90	X
BRACKET, FRONT BUMPER SIDE, RH	NH	1	\$82.30	X
BRACKET, FRONT BUMPER SIDE, LH	NH	1	\$82.30	X
BRACKET, FRONT BUMPER MOUNTING	NH	1	\$29.60	X
BRACKET, FRONT BUMPER MOUNTING, NO. 2	NH	1	\$97.80	X
ABSORBER, FRONT BUMPER, LOWER	NH	1	\$127.70	X
UNIT ASSY, HEADLAMP, RH (LED)	mondy crack	1	\$3,455.00	✓
UNIT ASSY, HEADLAMP, LH (LED)	mondy crack	1	\$3,455.00	✓
HEAD LAMP PANEL (RH)	NH	1	\$240.10	X
HEAD LAMP PANEL (LH)	NH	1	\$240.10	X
TOP PANEL CENTRE	NH	1	\$364.98	X
TOP PANEL SIDE	NH	1	\$145.90	X
TOP PANEL SIDE	NH	1	\$145.90	X
BRACE PANEL	NH	1	\$75.20	X
BRACKET, HEADLAMP MOUNTING, RH	NH	1	\$25.50	X
BRACKET, HEADLAMP MOUNTING, LH	NH	1	\$25.50	X
RADIATOR ASSY	NH	1	\$1,841.80	X

-1186428

CONDENSER ASSY, W/RECEIVER NH		1	\$1,336.60	X
SUB TOTAL	20068.00		\$16,207.68	39587.38
LESS 20% 25%			\$3,241.54	7917.48
DISCOUNTED TOTAL	15051.00		\$12,966.14	31669.90
FRONT NO. PLATE 13+	Nett	1	\$25.00	45/-
FRONT NO. PLATE TRIM COVER 13+	Nett	1	\$30.00	
FRONT NO. PLATE GARNISH NH	Nett	1	\$99.00	X
REAR BUMPER REVERSE SENSOR Dem 280.70	Nett	1	\$135.70	✓
REAR NO. PLATE WITH TRIM COVER 44	Nett	1	\$100.00	X
REAR TRUNK LID APPS STICKER Hec	Nett	1	\$40.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER Hec	Nett	1	\$60.00	✓
SUB TOTAL			\$489.70	
Labour Charge				
Panel Beating			\$1,600.00	900/-
Spray Painting Charge			\$1,800.00	900/-
Wiring Charge			\$120.00	30/-
Tuff Kote			\$200.00	40/-
Towing Charge			\$50.00	NH
Remove/Refix Cushion & Upholstery Rear			\$150.00	80/-
Remove/Refix Rear Windscreen Glass			\$120.00	80/-
Remove/Refix Reverse Sensor 2130.00			\$120.00	40/-
Remove/Refix Fuel Tank			\$150.00	NH
Remove/Refix Exhaust Pipe			\$150.00	60/-
Rear Wheel Alignment			\$120.00	NH
Remove/Refix Radiator			\$90.00	NH
Remove/Refix Aircon & Refill Gas			\$150.00	NH
TOTAL LABOUR			\$4,820.00	
ESTIMATE TOTAL			\$18,275.84	36979.60
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

16/01/2020 20930hrs
 Not Antm
 2/sun 9 days.

17461.70
 L/S 13900/-

you
 LKK Ande

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD		Ref : CS/DOI20000954/Dtd3n2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 12-02-2020		
		Code : DOI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKW 6391E	Veh. Inspected	SHB 3110R
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D12612001	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	15/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU203557487	Colour	YELLOW
	Odometer	290374	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	5 mm
	L/H Front Tyre	195/65 R15	DAVANTI	5 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/01/2020	Inspection Date	16/01/2020
	Survey held at	BLK 9 SECTOR C # 01-42 SIN MING IND EST		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3110R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TRUNK LID COVER	BENT	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	DAMAGED	457.90	457.90
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	216.50	-
1	REAR TRUNK LID RUBBER	DEFORMED	365.20	365.20
1	BOARD ASSY, BACK DOOR TRIM	NOT NECESSARY	254.40	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	CRACKED / BROKEN	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	TORN	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	DENTED	318.80	318.80
1	REAR BUMPER UNDER COVER	TORN	552.60	552.60
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER UNDER SIDE COVER (RH)	NOT NECESSARY	232.00	-
1	REAR BUMPER UNDER SIDE COVER (LH)	MOULDING BROKEN	232.00	232.00
1	REAR BUMPER UNDER SIDE CENTRE COVER	BROKEN	552.60	552.60
1	REAR BUMPER TOWING COVER	DISLODGE / BROKEN	82.70	82.70
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE CLIP	NOT NECESSARY	25.00	-
1	ARM SUB-ASSY, REAR BUMPER, RH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY, REAR BUMPER, LH	NOT NECESSARY	139.60	-
1	RETAINER, REAR BUMPER, UPPER SIDE	NOT NECESSARY	30.70	-
1	RETAINER, REAR BUMPER, SIDE, RH	NOT NECESSARY	94.80	-
1	RETAINER, REAR BUMPER, SIDE, LH	NOT NECESSARY	94.80	-
1	SEAL, REAR BUMPER SIDE, RH	NOT NECESSARY	148.40	-
1	SEAL, REAR BUMPER SIDE, LH	CUT	148.40	148.40
2	TAIL LAMP ASSY (UPPER)	CRACKED / MOUNTING CRACKED	557.90	557.90
2	TAIL LAMP ASSY (LOWER)	CRACKED / MOUNTING CRACKED	548.40	548.40
2	TAIL LAMP QUARTER PANEL	DENTED	216.00	216.00

Report Ref No. CS/UOI20000954/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAIL LAMP SIDE COVER	NOT NECESSARY	256.00	-
2	LAMP ASSY,SIDE TURN SIGNAL,RH	NOT NECESSARY	65.30	-
2	LAMP ASSY,SIDE TURN SIGNAL,LH	NOT NECESSARY	65.30	-
2	BULB,BACK UP LAMP & REAR FOG LAMP,NO 1	NOT NECESSARY	4.90	-
2	BULB,REAR TURN SIGNAL LAMP	NOT NECESSARY	8.90	-
1	REAR END PANEL	BUCKLED	602.10	602.10
1	REAR END PANEL GARNISH	DEFORMED / MOUNTING DEFORMED	161.80	161.80
1	REAR SPARE TYRE PANEL	DENTED	667.70	667.70
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	101.40	-
1	REAR FIBER TOOL BOX TRIM	SERVICEABLE	398.00	-
1	REAR EXHAUST PIPE	DENTED	1,163.40	1,163.40
1	REAR EXHAUST PIPE (FRONT)	NOT NECESSARY	2,966.20	-
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	BENT	314.60	314.60
1	REAR FENDER,LH	DENTED	836.70	836.70
1	REAR FENDER,RH	DENTED	836.70	836.70
1	REAR FENDER OUTER PANEL,LH	NOT NECESSARY	486.00	-
1	REAR FENDER OUTER PANEL,RH	NOT NECESSARY	486.00	-
2	REAR FENDER SIDE PANEL	NOT NECESSARY	165.00	-
2	REAR FENDER SHIELD (LH/RH)	NOT NECESSARY	134.20	-
2	REAR FENDER TRIMBOARD (LH/RH)	BENT / DEFORMED	725.00	725.00
1	REAR FLOOR PANEL SIDE (LH)	NOT NECESSARY	276.20	-
1	REAR FLOOR PANEL SIDE (LRH)	NOT NECESSARY	276.20	-
2	REAR FENDER AIR DUCT	NOT NECESSARY	165.10	-
1	REAR WINDSCREEN GLASS W/MOULDING	NOT NECESSARY	1,778.30	-
1	REAR WINDSCREEN SEALANT	NECESSARY	46.00	46.00
1	RADIATOR GRILLE	CRACKED	438.00	438.00
1	RADIATOR GRILLE EMBLEM	SERVICEABLE	88.00	-
1	FRONT BUMPER COVER	MOUNTING CRACKED	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	696.40	-
1	FRONT BUMPER REINFORCEMENT ABSORBER	NOT NECESSARY	115.70	-
1	FRONT BUMPER LOWER REINFORCEMENT BRACKET	NOT NECESSARY	330.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	78.80	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	301.90	-

Report Ref No. CS/UOI20000954/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GRILLE	CRACKED	148.60	148.60
1	LAMP ASSY,FOG,RH	NOT NECESSARY	920.00	-
1	LAMP ASSY,FOG,LH	NOT NECESSARY	920.00	-
1	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
2	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	77.00	-
1	FRONT LOWER CROSSMEMBER	NOT NECESSARY	357.70	-
1	FRONT UNDER COVER	NOT NECESSARY	180.80	-
1	ENGINE UNDER COVER (RR)	NOT NECESSARY	457.40	-
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	225.40	-
1	REINFORCEMENT,FRONT BUMPER LOWER	NOT NECESSARY	236.10	-
1	BRACKET,FRONT BUMPER EXTENSION MOUNTING	NOT NECESSARY	110.40	-
1	SUPPORT FR BUMPER,RH	NOT NECESSARY	81.70	-
1	SUPPORT FR BUMPER,LH	NOT NECESSARY	81.70	-
1	FRONT BUMPER CENTRE FRAME	NOT NECESSARY	236.90	-
1	BRACKET,FRONT BUMPER SIDE,RH	NOT NECESSARY	82.30	-
1	BRACKET,FRONT BUMPER SIDE,LH	NOT NECESSARY	82.30	-
1	BRACKET,FRONT BUMPER MOUNTING	NOT NECESSARY	29.60	-
1	BRACKET,FRONT BUMPER MOUNTING,NO 2	NOT NECESSARY	97.80	-
1	ABSORBER,FRONT BUMPER,LOWER	NOT NECESSARY	127.70	-
1	UNIT ASSY,HEADLAMP,RH (LED)	MOUNTING CRACKED	3,455.00	3,455.00
1	UNIT ASSY,HEADLAMP,LH (LED)	MOUNTING CRACKED	3,455.00	3,455.00
1	HEAD LAMP PANEL (RH)	NOT NECESSARY	240.10	-
1	HEAD LAMP PANEL (LH)	NOT NECESSARY	240.10	-
1	TOP PANEL CENTRE	NOT NECESSARY	364.98	-
1	TOP PANEL SIDE	NOT NECESSARY	145.90	-
1	TOP PANEL SIDE	NOT NECESSARY	145.90	-
1	BRACE PANEL	NOT NECESSARY	75.20	-
1	BRACKET,HEADLAMP MOUNTING,RH	NOT NECESSARY	25.50	-
1	BRACKET,HEADLAMP MOUNTING,LH	NOT NECESSARY	25.50	-
1	RADIATOR ASSY	NOT NECESSARY	1,841.80	-
1	CONDENSER ASSY,W/RECEIVER	NOT NECESSARY	1,336.60	-
	LESS 20% DISCOUNT		-7,917.48	-
	LESS 25% DISCOUNT		-	-5,017.00
			31,669.90	15,051.00

Report Ref No. CS/UOI20000954/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE TRIM COVER (SN) }	BENT	30.00	45.00
1	FRONT NO PLATE (SN) }	BENT	25.00	-
1	FRONT NO PLATE GARNISH (SN)	NOT NECESSARY	99.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR NO PLATE WITH TRIM COVER (SN)	NOT NECESSARY	100.00	-
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
			489.70	280.70
	LABOUR			
	PANEL BEATING.		1,600.00	900.00
	SPRAY PAINTING CHARGE.		1,800.00	900.00
	WIRING CHARGE.		120.00	30.00
	TUFF KOTE.		200.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	REMOVE/REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
			4,820.00	2,130.00
	GRAND TOTAL		36,979.60	17,461.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,900.00

Report Ref No. CS/UOI20000954/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.