

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20000956/KPS3Q2

Date: 12/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant	Insured Vehicle No :	SHD4833X
Vehicle No : SLN737S		
Date of Loss: 13/01/2020	Nature of Claim: TP	Claim No: MCT20010288

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN737S	Engine No:	G6EA6A666439
Make & Model:	HYUNDAI SANTA FE, 2.7 (CM) (A)	Chassis No:	KMHS81DR6U087927
Reg. Date:	12/03/2007 (Man. Year: 2006)	Odometer:	298059 km
Colour:	Metallic Blue		
Engine Capacity:	2656 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/40 R20	Rear Tyre Size:	275/40 R20
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,046.40	6,820.32	3,226.08	32.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	2,300.00	1,140.00	33.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,486.40	9,120.32	4,366.08	32.37
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	13,486.40	7,200.00	6,286.40	46.61
+ GST 7.00/7.00% (S\$)	944.05	504.00	440.05	46.61
Nett Amount (S\$)	14,430.45	7,704.00	6,726.45	46.61
+ Car Rental (8.0 x S\$140.00/day + 7.00% GST) (S\$)		1,198.40		
Nett Liability (S\$)		8,902.40		
Global Sum Settlement (S\$)		8,900.00		

INSPECTION

Date of Assignment:	15/01/2020	Inspected At:	Optima Werkz Pte Ltd (HQ)
Date Inspected:	15/01/2020		6 Kung Chong Road
			Singapore 159143
Estimated Period of Repair:	7.0 days		

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2020)
Parts: M1-SUV	HYUNDAI SANTA FE 2.7 (CM) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN737S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Mtg Cracked	927.00 FL	*927.00 FL
2	1		*FRONT BUMPER	Cracked	677.00 FL	*650.00 FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Distorted	45.60 FL	*45.60 FL
4	10		*FRONT BUMPER CLIPS	Necessary	58.00 FL	*58.00 FL
5	1		*FRONT LH	Bent	653.00 FL	*653.00 FL
6	1		*FRONT FENDER BRACE BRACKET LH	Distorted	112.00 FL	*112.00 FL
7	1		*FRONT FENDER INNER LINER LH	Cracked	146.00 FL	*146.00 FL
8	8		*FRONT FENDER INNER LINER CLIPS LH	Necessary	49.60 FL	*49.60 FL
9	1		*FRONT FENDER 4WD EMBLEM LH	Necessary	38.20 FL	*38.20 FL
10	1		*FRONT DOOR LH	Dented / Warped	1,740.00 FL	*1,335.00 FL
11	1		*FRONT DOOR OUTER HANDLE LH	Missing	116.00 FL	*116.00 FL
12	1		*FRONT DOOR OUTER HANDLE BASE LH	Missing	48.00 FL	*48.00 FL
13	1		*FRONT DOOR OUTER HANDLE COVER LH	Missing	65.00 FL	*65.00 FL
14	1		*FRONT DOOR OUTER HANDLE INNER BASE SUPPORT LH	Missing	96.20 FL	*96.20 FL
15	1		*FRONT DOOR LOWER PROTECTOR COVER LH	Serviceable	149.60 FL	*- FL
16	1		*FRONT DOOR FRAME PROTECTOR STICKER LH	Serviceable	65.00 FL	*- FL
17	1		*REAR DOOR LOWER PROTECTOR COVER LH	Dented	146.80 FL	*146.80 FL
18	1		*FRONT ALLOY RIM LH (REPAIR)	Dented	150.00 FL	*150.00 FL
19	1		*FRONT WHEEL BEARING LH	Necessary	410.00 FL	*230.00 FL
20	1		*FRONT KNUCKLE ARM LH	Bent	642.00 FL	*349.20 FL
21	1		*POWER STEERING RACK ASSY	Bent / Jammed	2,412.00 FL	*1,953.80 FL
22	1		*FRONT DRIVE SHAFT LH	Bent	1,356.00 FL	*1,356.00 FL
23	1		*FRONT SUPPORT PANEL ASSY	Repair	1,230.00 FL	*- FL
24	1		*REAR DOOR LH (NPA)	Repair	0.00 FL	*- FL
25	1		*REAR QUARTER PANEL LH (NPA)	Repair	0.00 FL	*- FL
26	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
27	1		*SIDE SILL STEP PANEL ASSY LH	Repair	980.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,313.00	8,525.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,266.60	1,705.08
Total Parts (\$\$)	10,046.40	6,820.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REPAIR ,REFIX ,READJUST ACCIDENT AREAS & ETC	New	1,000.00	700.00
2	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX FRONT KNOCKLE AREA LH ,DRIVESHAFT LH ,POWER STEERING RACK ,WHEEL BEARING ,FRONT SUSPENSION FRAME & ETC	New	380.00	200.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC.BACK TO ORIGINAL OPERATIONS	New	100.00	60.00
4	LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC	New	80.00	20.00
5	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER LH ,FRONT DOOR LH ,REAR DOOR LH ,REAR QUARTER PANEL LH ,REAR BUMPER & ETC	New	1,400.00	1,200.00
6	LABOUR CHARGES TO REMOVE & REPLACE SIDE SILL STEP PANEL ASSY LH & ETC	New	200.00	0.00
7	TO WHEEL ALIGNMENT & BALANCING	New	80.00	60.00
8	TO TUFF KOTE & UNDERSEAL MATERIALS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,440.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >