

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000958/AKS3Q2

Date: 12/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100481454

Claimant
Vehicle No : SLU7535A **Insured Vehicle No :** SGP3580E

Date of Loss: 11/01/2020 Nature of Claim: TP Claim No: 5130959385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7535A	Engine No:	1NR0A84569
Make & Model:	PERODUA BEZZA, 1.3 Premium (A)	Chassis No:	PM2B301S003078734
Reg. Date:	13/12/2017 (Man. Year: 2017)	Odometer:	27756 km
Colour:	Silver		
Engine Capacity:	1329 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,668.20	4,945.00	2,723.20	35.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	2,050.00	1,080.00	34.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,798.20	6,995.00	3,803.20	35.22
Approved Total (Overridden) (\$\$)		5,600.00		
(\$\$)	10,798.20	5,600.00	5,198.20	48.14
+ GST 7.00/7.00% (\$\$)	755.87	392.00	363.87	48.14
Nett Amount (\$\$)	11,554.07	5,992.00	5,562.07	48.14
+ Loss of Use (10.0 x S\$100.00/day) (\$\$)		1,000.00		
+ Doc/Search Fee (\$\$)		10.00		
Nett Liability (\$\$)		7,002.00		

INSPECTION

Date of Assignment: 14/01/2020

Date Inspected: 14/01/2020 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	950.00 FL	*885.00 FL
2	1		*BOOT LID LOGO	Necessary	78.00 FL	*78.00 FL
3	1		*BOOTLID BEZZA EMBLEM	Necessary	80.00 FL	*80.00 FL
4	1		*BOOT LID VVTI EMBLEM	Necessary	45.00 FL	*45.00 FL
5	1		*BOOTLID X EMBLEM	Necessary	38.00 FL	*38.00 FL
6	1		*BOOT LID CHROME	Not Necessary	480.00 FL	*- FL
7	1		*BOOT LID LOCK	Damaged	360.00 FL	*295.00 FL
8	1		*BOOT LID LOCK CHECKER	Not Necessary	69.00 FL	*- FL
9	1		*BOOT LID RUBBER	Cut	313.00 FL	*285.00 FL
10	2		*BOOT LID HINGE	Not Necessary	200.00 FL	*- FL
11	1		*BOOTLID TRIM	Not Necessary	254.00 FL	*- FL
12	1		*REAR PANEL	Dented	720.00 FL	*665.00 FL
13	1		*REAR PANEL TRIM	Deformed	340.00 FL	*275.00 FL
14	1		*REAR FENDER INNER TRIM LH	Not Necessary	480.00 FL	*- FL
15	1		*TAIL LAMP LH	Cracked	470.00 FL	*365.00 FL
16	1		*REAR BUMPER	Deformed	980.00 FL	*795.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	380.00 FL	*90.00 FL
18	2		*REVERSE SENSOR	Damaged	672.00 FL	*260.00 FL
19	1		*REAR BUMPER LOWER SPOILER	Deformed	750.00 FL	*750.00 FL
20	1		*REAR BUMPER REFLECTOR -LH	Cracked	140.00 FL	*65.00 FL
21	1		*TOOL TRAY SPONGE	Deformed	298.00 FL	*298.00 FL
22	1		*SPARE TYRE PANEL TOP COVER	Torn	181.00 FL	*181.00 FL
23	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
24	1		*SET BOOTLID TRIM CLIPS	Not Necessary	40.00 FS	*- FS
25	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
26	1		*SET REAR FENDER INNER TRIM CLIPS LH	Not Necessary	40.00 FS	*- FS
27	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,496.00	5,490.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	827.80	545.00
Total Parts (\$\$)	7,668.20	4,945.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT INER TRIM	New	150.00	80.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	60.00
4	TO SPRAY UNDERSEAL	New	150.00	80.00
5	(REAR) TO SPRAY PAINTING	New	1,300.00	900.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,400.00	900.00
Gross Labour Cost (\$\$)			3,130.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >