

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG20000960/T1SF3E2**Date:** 15/07/2020REFERENCE

Insured/Claimant:	OH YAM GIM	Policy No:	1700052489
Date of Loss:	12/01/2020	Nature of Claim:	OD
		Claim No:	2512027065SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS4295Y	Engine No:	CHZ359880
Make & Model:	AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Chassis No:	WAUZZZ8X7HB088657
Reg. Date:	22/09/2017 (Man. Year: 2017)	Odometer:	56588 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R16	Rear Tyre Size:	215/45 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,236.08	29,806.40	24,429.68	45.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	33,804.00	12,924.00	20,880.00	61.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	88,040.08	42,730.40	45,309.68	51.46
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	87,440.08	42,130.40	45,309.68	51.82
+ GST 7.00/7.00% (S\$)	6,120.81	2,949.13	3,171.68	51.82
Nett Amount (S\$)	93,560.89	45,079.53	48,481.36	51.82

INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 14/01/2020 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 19.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,407.00 FS	*1,125.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	224.00 FS	*- FS
3	2		*WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	30.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Deformed	178.00 FS	*142.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Deformed	152.00 FS	*121.60 FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	734.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	894.00 FS	*715.20 FS
8	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	630.00 FS	*504.00 FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	107.00 FS	*85.60 FS
10	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	54.00 FS	*- FS
11	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	17.00 FS	*- FS
12	1		*SIGNAL HORN - RH HIGH TONE	Not Necessary	206.00 FS	*- FS
13	1		*SIGNAL HORN - LH LOW TONE	Not Necessary	206.00 FS	*- FS
14	2		*FRONT FENDER - LH / RH	Bent	1,618.00 FS	*647.20 FS
15	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	41.00 FS	*- FS
16	2		*FRONT FENDER CENTRE BRACKET - LH / RH	Not Necessary	22.00 FS	*- FS
17	2		*FRONT FENDER FRONT BRACKET - LH / RH	Bent	108.00 FS	*88.96 FS
18	2		*FRONT FENDER FRONT BRACE - LH / RH	Not Necessary	98.00 FS	*- FS
19	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	46.00 FS	*- FS
20	2		*FRONT WHEEL HOUSING LINER SEAL - UPPER	Not Necessary	61.00 FS	*- FS
21	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	316.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
23	1		*BONNET	Bent	2,063.00 FS	*1,650.40 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	126.00 FS	*- FS
25	2		*BONNET LID HINGE - LH / RH	Bent	232.00 FS	*184.80 FS
26	1		*BONNET GAS FILLED STRUT	Not Necessary	133.00 FS	*- FS
27	2		*BONNET COVER - LH / RH	Not Necessary	58.00 FS	*- FS
28	2		*BONNET EDGE PROTECTION - FRONT	Deformed	36.00 FS	*29.76 FS
29	1		*BONNET CATCH HOOK	Bent	60.00 FS	*48.00 FS
30	2		*BONNET LOCK BAR	Bent	90.00 FS	*72.00 FS
31	1		*BONNET CATCH HOOK	Bent	58.00 FS	*46.40 FS
32	2		*BONNET LID LOCK	Bent	391.00 FS	*317.60 FS
33	2		*MICRO SWITCH	Not Necessary	133.00 FS	*- FS
34	1		*BONNET BOWDEN CABLE - CENTRE	Distorted	53.00 FS	*43.20 FS
35	1		*BONNET LID LOCK CABLE	Not Necessary	43.00 FS	*- FS
36	1		*BONNET BRACKET	Not Necessary	53.00 FS	*- FS
37	1		*BONNET LID LOCK CABLE GRIP	Not Necessary	22.00 FS	*- FS
38	1		*BONNET SOUND ABSORBER	Deformed	185.00 FS	*148.00 FS
39	1		*PLENUM CHAMBER COVER	Not Necessary	174.00 FS	*- FS
40	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	214.00 FS	*178.40 FS
41	2		*HEADLIGHT - LH / RH	Cracked	3,584.00 FS	*2,867.20 FS
42	2		*GAS DISCHARGE LAMP CONTROL UNIT	Cut	2,102.00 FS	*859.20 FS
43	2		*DAY DRIVING LIGHTS POWER MODULE	Shorted	1,044.00 FS	*427.60 FS
44	2		*GAS DISCHARGE LAMP	Not Necessary	796.00 FS	*- FS
45	2		*LED WITH HEAT SINK - LH / RH	Not Necessary	714.00 FS	*- FS
46	2		*SET GAS DISCHARGE BULB WIRING	Not Necessary	200.00 FS	*- FS
47	1		*HEADLIGHT HOSE - LH / RH		54.00 FS	*22.32 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				O/S Cut / N/S Not Necessary		
48	2		*LIFT CYLINDER - LH / RH	Cracked	256.00 FS	*214.40 FS
49	1		*HEADLIGHT HOSE	Not Necessary	170.00 FS	*- FS
50	1		*HEADLIGHT DISTRIBUTOR	Not Necessary	13.00 FS	*- FS
51	1		*HEADLIGHT ELBOW FITTING	Not Necessary	23.00 FS	*- FS
52	1		*HEADLIGHT PUMP	Not Necessary	147.00 FS	*- FS
53	1		*WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	118.00 FS	*- FS
54	1		*WASH WATER RESERVOIR	Deformed	197.00 FS	*159.60 FS
55	1		*LOCK CARRIER	Bent	936.00 FS	*748.80 FS
56	2		*CROSS MEMBER REINFORCEMENT	Bent	24.00 FS	*21.52 FS
57	1		*AIRCON CONDENSER	Bent	503.00 FS	*402.40 FS
58	1		*REFRIGERANT LINE	Bent	445.00 FS	*363.60 FS
59	1		*REFRIGERANT LINE	Bent	342.00 FS	*279.60 FS
60	1		*COOLANT LINE BRACKET	Cracked	23.00 FS	*18.40 FS
61	1		*RADIATOR	Bent	768.00 FS	*614.40 FS
62	2		*RADIATOR BRACKET	Bent	77.00 FS	*61.60 FS
63	2		*RADIATOR BUSH - LOWER	Bent	18.00 FS	*14.40 FS
64	4		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
65	1		*ADDITIONAL RADIATOR	Bent	609.00 FS	*487.20 FS
66	1		*ADDITIONAL RADIATOR SEAL - LOWER	Necessary	25.00 FS	*20.00 FS
67	1		*RADIATOR SEAL - LOWER	Necessary	13.00 FS	*10.40 FS
68	2		*RADIATOR SEAL - LH / RH	Necessary	36.00 FS	*28.80 FS
69	1		*RADIATOR FAN RING	Cracked	127.00 FS	*101.60 FS
70	1		*RADIATOR FAN	Distorted	690.00 FS	*552.00 FS
71	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	56.00 FS	*46.56 FS
72	1		*AIR INTAKE AIR FILTER	Not Necessary	252.00 FS	*- FS
73	1		*AIR INTAKE AIR GUIDE	Cracked	47.00 FS	*38.16 FS
74	1		*AIR INTAKE WATER DRAINAGE HOSE	Not Necessary	19.00 FS	*- FS
75	1		*AIR INTAKE MANIFOLD	Not Necessary	129.00 FS	*- FS
76	1		*VENT HOSE	Not Necessary	11.00 FS	*- FS
77	1		*AIR INTAKE MANIFOLD	Not Necessary	588.00 FS	*- FS
78	1		*INTER COOLER GASKET	Not Necessary	13.00 FS	*- FS
79	1		*CHARGE AIR COOLER	Not Necessary	692.00 FS	*- FS
80	1		*INTAKE MANIFOLD GASKET	Not Necessary	13.00 FS	*- FS
81	1		*INTER COOLER GASKET	Not Necessary	13.00 FS	*- FS
82	1		*THROTTLE VALVE CONTROL ELEMENT	Not Necessary	973.00 FS	*- FS
83	1		*THROTTLE VALVE SEAL	Not Necessary	16.00 FS	*- FS
84	1		*THROTTLE VALVE CONNECTING TUBE	Not Necessary	307.00 FS	*- FS
85	1		*FRONT DOOR - RH	Repair	1,841.00 FS	*- FS
86	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
87	1		*FRONT DOOR CATCH	Not Necessary	81.00 FS	*- FS
88	1		*AIRCON STICKER	Necessary	35.00 FS	*28.00 FS
89	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.40 FS
90	1		*TYRE PRESSURE DATA PLATE	Not Necessary	35.00 FS	*- FS
91	1		*FRONT DOOR - LH	Not Necessary	1,841.00 FS	*- FS
92	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
93	1		*FRONT DOOR CATCH	Not Necessary	81.00 FS	*- FS
94	1		*STEERING WHEEL AIRBAG UNIT	Activated	3,242.00 FS	*2,593.60 FS
95	1		*AIRBAG UNIT	Activated	3,548.00 FS	*2,838.40 FS
96	1		*AIRBAG CONTROL UNIT	Activated	1,480.00 FS	*1,184.00 FS
97	1		*ACCELERATION SENSOR	Not Necessary	273.00 FS	*- FS
98	1		*CENTRAL PROTECTION	Distorted	432.00 FS	*357.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	2		*SEAT BELT - LH / RH	Activated	1,904.00 FS	*1,523.20 FS
100	2		*SEAT BELT HEIGHT ADJUSTER	Not Necessary	361.00 FS	*- FS
101	1		*STEERING WHEEL	Not Necessary	1,749.00 FS	*- FS
102	1		*DASHBOARD	Deformed	3,570.00 FS	*2,856.00 FS
103	1		*AIR VENT - UPPER CENTRE	Not Necessary	105.00 FS	*- FS
104	1		*LOUDSPEAKER MOUNTING	Not Necessary	59.00 FS	*- FS
105	1		*LOUDSPEAKER COVER	Not Necessary	86.00 FS	*- FS
106	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
107	1		*SUNDRIES	Necessary	800.00 FS	*75.04 FS
108	1		*BONNET INNER TOP COVER LHS	Cracked	23.92 FS	*23.92 FS
109	1		*HOLDER FOR FILTER PIPE	Deformed	21.60 FS	*21.60 FS
110	1		*FLAT CONTACT HOUSING	Cracked	19.04 FS	*19.04 FS
111	1		*RADIATOR COOLANT HOSE (FLANGE>COOLANT RADIATOR)	Not Necessary	99.00 FS	*- FS
112	1		*RADIATOR COOLANT HOSE	Distorted	48.72 FS	*48.72 FS
113	1		*SPRING BAND CLAMP	Not Necessary	19.00 FS	*- FS
114	1		*MECHATRONIC WITH SOFTWARE	Bent	3,043.20 FS	*3,043.20 FS
115	1		*SOCKET HEAD BOLT WITH INNER	Necessary	21.12 FS	*21.12 FS
116	1		*ROUND HEAD SCREW	Necessary	6.72 FS	*6.72 FS
117	1		*TRANSMISSION FLUID	Necessary	95.04 FS	*95.04 FS
118	1		*COOLANT PIPE	Deformed	22.56 FS	*22.56 FS
119	1		*REFRIGERANT LINE	Bent	398.80 FS	*398.80 FS
120	1		*FLAT CONTACT HOUSING WITH CONTACT LOCKING MECHANISM	Cracked	23.36 FS	*23.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **54,236.08** **29,806.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	0.00
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
4	TO REMOVE AND RENEW AIRCOND CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
5	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT	New	3,200.00	3,200.00
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS	New	2,800.00	0.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	0.00
8	TO PLACE VEHICLE ON CAR O-LINER	New	2,400.00	0.00
9	TO REMOVE AND TRANSFER BOTH FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	0.00
10	TO DISMANTLE BOTH FRONT PANEL TRIMS. TO REMOVE AND REINSTALL BOTH FRONT WING MIRROR ASSY	New	700.00	0.00
11	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS AND BOTH FRONT DOORS. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,100.00	3,500.00
12	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, ENGINE COMPARTMENT, BOTH FRONT UPPER A-PILLARS AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	8,400.00	3,300.00
13	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
14	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
15	TO REMOVE AND RENEW MECHATRONIC WITH SOFTWARE	New	980.00	980.00
Gross Labour Cost (S\$)			33,804.00	12,924.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >