

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20000961/KKA3Q2

**Date:** 29/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993933

**Claimant**  
**Vehicle No :** SLM2836G **Insured Vehicle No :** SKN1741J

Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: 0276849198SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM2836G</b>	Engine No:	2ZRS029337
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDBK3FU803554254
Reg. Date:	27/03/2017 (Man. Year: 2017)	Odometer:	158150 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>RePAIRer's</b>	<b>ADJuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,483.59	879.48	1,604.11	64.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,646.05	977.27	668.78	40.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,129.64</b>	<b>1,856.75</b>	<b>2,272.89</b>	<b>55.04</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	289.07	129.97	159.10	55.04
<b>Nett Amount (\$\$)</b>	<b>4,418.71</b>	<b>1,986.72</b>	<b>2,431.99</b>	<b>55.04</b>
<b>+ Car Rental (6.0 x S\$49.95/day) (\$\$)</b>		299.70		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>2,293.87</b>		

### INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 15/01/2020 Inspected At: Esteem Performance Pte Ltd (HQ)  
Blk 5033 Ang Mo Kio Ind Park 2, #01-259  
Singapore 569536

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/R DOOR	Bent	1,211.40 FL	*1,211.40 FL
2	1		*L/R UPPER DOOR HINGE	Repair	78.34 FL	*- FL
3	1		*R/R LOWER DOOR HINGE	Repair	78.34 FL	*- FL
4	1		*L/R DOOR CHECK	Serviceable	145.50 FL	*- FL
5	1		*L/R DOOR SEAL FRONT	Not Necessary	79.80 FL	*- FL
6	1		*L/R DOOR SEAL	Not Necessary	198.70 FL	*- FL
7	1		*L/R OUT CHANNEL SEAL	Not Necessary	107.80 FL	*- FL
8	1		*L/SILL PANELLING	Not Necessary	721.50 FL	*- FL
9	1		*L/R SIDE PANEL	Repair	881.60 FL	*- FL
10	1		*CLIP	Necessary	45.00 FL	*45.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,547.98</b>	<b>1,256.40</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	1,064.39	376.92
<b>Total Parts (\$\$)</b>	<b>2,483.59</b>	<b>879.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TUFF COAT TUFF COAT	New	120.00	30.00
2	TO ASSIT WORK LOAD R&R REAR SEAT	New	300.00	100.00
3	TO ASSIST WORK LOAD R&R PETROL TANK	New	150.00	0.00
4	119.0 WU X50.00 SGD/H	New	595.00	390.00
5	LABOUR COST 71.0 WU X 50.00 SGD/H	New	355.00	345.00
6	MATERIAL COST	New	126.05	112.27
<b>Gross Labour Cost (\$)</b>			<b>1,646.05</b>	<b>977.27</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**