Esteem Performance Pte Ltd 385 Sin Ming Drive, Vicom Vehicle **Inspection Centre (575718)**

Insurer Reference: SKN1741J Repairer Reference: 026470

Date calculated: 18/02/2020 5:06 PM

Full Report Registration: SLM2836G Printed: 18/02/2020 5:06 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

AIG Asia Pacific Insurance

Pte Ltd

Printed by:

Claim Reference:

Carmen SG SKN1741J

Currency: Date of Incident: SGD 04/01/20

Estimated Repair Time:

Actual Repair Days:

Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number: Registration:

VIN number: Odometer:

Model Specs TWO COAT METALLIC TOYOTA PRIUS IV LKK Auto Consultants hence notify

BASE MODEL 70 P5 01

SLM2836G

Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

AII Underbody

Supplementary item(s) must be resurveyed a is subject to final approval from insurance Co Acknowledged by Repairer Signature:

the Repairer of the following: To resurvey before/after spray painting

To display damaged part(s) during resun

Parts prices are subject to confirmation

No illegal modification(s) is allowed

Third party survey is on a "Without Prejudice"

1 -	h	-		204
La	u	U	u	г

	Time Base 10 W	10 WU/h Price =		ce = 50	50.00 SGD/h	
Code	Description			WU	Price SGD	
B210	RENEW L/R DOOR			26.0	130.00	
B210	R + R L/R DOOR WINDOW FRAME SEAL			2.0	10.00	
B380	R + R TAILGATE			10.0	50.00	
3481	L/R SIDE PANEL REPAIR			40.0*	200.00	
	Z/N 0102 / MEE KEI MIN			40.0	200.00	
	Labour Cost		Hrs	WU		
	Panel / Mechanical Labour		7.80	78.0	390.00	
	Total of Labour				390.00	
Paint						
Paint Work	SYSTEM AZT		Tir	ne Basis	10 WU/h	
Code	Description - TWO COAT METALLIC			WU	Price SGD	
	L/R DOOR NEW PART PAINTING			15.0		
	L/SILL PANELLING REPAIR PAINT PLASTIC			12.0		
	L/R SIDE PANEL REPAIR PAINTING <50%			13.0		
Paint Material	Per Part					
Code	Description				Duine CCD	
Code	Description				Price SGD	
1781	L/R DOOR NEW PART PAINTING				39.73	
2185	L/SILL PANELLING REPAIR PAINT PLASTIC				24.30	
3481	L/R SIDE PANEL REPAIR PAINTING <50%				17.44	
	Labour Cost - Paint Factor	50.00 SGD/h	Hrs	wu	Price SGD	
	Time Paint	30.00 300/11		40.0		
	Preparation Main Work Metal		2.10	21.0	105.00	
	Preparation Comp. Work Plastic		0.80	8.0	40.00	
	Total	10 WU/h	6.90	69.0	345.00	
	Total	10 110/11	0.50	09.0	343.00	
	Material Cost - Paint				Duine CCD	
					Price SGD	
	New Part Painting				39.73	
	Repair Painting				17.44	
	Repair Painting Plastic				24.30	
	Material constant Metal				18.10	
	Material-constant Plastic				12.70	
	Total				112.27	
Canus Davis						
Spare Parts				-		

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
1000	CLIP	LH SIDE SKIRT		45.00
1781	L/R DOOR	67004 47210		1,211.40

Code	Description	Part Number	Supplier		Price SGD
		, are realisely	Заррнег		FIICE SGD
f: OEM Parts n: Non-OEM Parts	Savings				0.00
u: Used parts	Subtotal Discou	·m+(20 000/)			1,256.40
	Subtotal Discou	1111(+30.00%)			-376.92
	Total		e.	,	879.48
Extras		8			
Code [Description				Price SGD
1001 T	UFF COAT TUFF COAT				30.00*
	O ASSIT WORK LOAD				100.00*
1003 T	O ASSIST WORK LOA	D R&R PETROL TANK		N	N 60.00*
1	otal Extras				190.00
Final Calculat	tion			SGD	SCD
				SGD	SGD
Parts				1,256.40	
Total Discount((+30.00%)			-376.92	
Total Parts					879.48
Labour Time B	ase 10 WII/h				
	J X 50.00 SGD/h			390.00	
Total of Labour	x 20100 300/11			330.00	390.00
Total Of Extras					190.00
Paint Work Tin	ne Base 10 WU/h				5
	0.0 WU X 50.00 SGD/I	า		345.00	
Material Cost				112.27	
Total Paint Incl	uding Material				457.27
Dannin Coat Torri	ludes CCT			1856-75	4 04 0 ==
Repair Cost Exc	ludes GST			10-0-7)	1,916.75

Comments

* - USER SUPPLIED DATA

Repair Cost Included GST

GST (+7.0%)

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

2,050.92