



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFZ 2686A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	CLAMP (SN)	NECESSARY	33.50	33.50
1	RH CLOSED GRID (BASIS) (SN)	CUT	88.00	88.00
1	GRILLE MIDDLE BOTTOM (SN)	NOT NECESSARY	125.70	-
1	FRT BUMPER LH INSERT (SN)	NOT NECESSARY	60.45	-
1	FRT BUMPER RH INSERT (SN)	NOT NECESSARY	60.45	-
1	FRONT BUMPER TOWING COVER PRIMED (SN)	NOT NECESSARY	39.15	-
1	FRT BUMPER PANEL PRIMED (SN)	DENTED	829.65	829.65
1	SET PDC HOLDER FRONT (SN)	NECESSARY	25.75	25.75
1	SET PMA HOLDERS FRT/REAR (SN)	NOT NECESSARY	23.25	-
1	RH DEFLECTOR LIP (SN)	NOT NECESSARY	20.85	-
1	(DG/SL) ADHESIVE SET K6 (SN)	NECESSARY	53.05	53.05
1	PLAQUE 82MM (SN) (ADDITIONAL)	NECESSARY	71.60	71.60
			1,511.40	1,181.55
	<u>LABOUR</u>			
	TO REPLACE BUMPER FRONT PANEL AND ATTACHMENTS.		1,275.00	850.00
	TO SPRAY PAINT BUMPER FRONT PANEL.		1,038.00	934.00
	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION .		177.00	150.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS .		177.00	150.00
			2,667.00	2,084.00
	GRAND TOTAL		4,178.40	3,265.55
	RECOMMENDED COST OF REPAIRS			3,265.55

Report Ref No. CC4/FCI20000970/Eka3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.