

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000977/AYD3E2

Date: 09/07/2020

REFERENCE

Insured/Claimant:	NUR SHAMSUDIN BIN MD ESA	Policy No:	1900152820
Date of Loss:	14/01/2020	Nature of Claim:	OD Claim No: 5385133076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7397G		
Make & Model:	AUDI A3, 999cc TFSI (A)	Engine No:	CHZC28451
Reg. Date:	27/08/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V4K1026449
Colour:	Grey	Odometer:	5100 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,598.00	5,314.32	5,283.68	49.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,942.00	6,492.00	4,450.00	40.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,540.00	11,806.32	9,733.68	45.19
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	20,740.00	11,006.32	9,733.68	46.93
+ GST 7.00/7.00% (S\$)	1,451.80	770.44	681.36	46.93
Nett Amount (S\$)	22,191.80	11,776.76	10,415.04	46.93

INSPECTION

Date of Assignment:	16/01/2020		
Date Inspected:	15/01/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Dented	778.00 FS	*622.00 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
3	1		*FRONT DOOR - LH	Distorted	2,279.00 FS	*1,823.20 FS
4	1		*FRONT DOOR OUTER SEAL	Necessary	146.00 FS	*116.80 FS
5	1		*BONDING AGENT	Necessary	45.00 FS	*36.72 FS
6	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
7	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
8	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	218.00 FS	*- FS
9	1		*FRONT DOOR EXTERIOR HANDLE - LH	Repair	331.00 FS	*- FS
10	1		*EXTERIOR DOOR HANDLE HOUSING - LH	Not Necessary	47.00 FS	*- FS
11	1		*WINDOW REGULATOR - LH	Not Necessary	241.00 FS	*- FS
12	1		*WINDOW REGULATOR MOTOR - LH	Not Necessary	224.00 FS	*- FS
13	1		*EXTERIOR MIRROR MOUNTING - LH	Not Necessary	929.00 FS	*- FS
14	1		*MIRROR CAP - LH	Repair	136.00 FS	*- FS
15	1		*MIRROR GLASS - LH	Not Necessary	1,132.00 FS	*- FS
16	1		*REAR DOOR - LH	Dented	2,279.00 FS	*1,823.20 FS
17	1		*REAR DOOR OUTER SEAL	Necessary	146.00 FS	*116.80 FS
18	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
19	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
20	1		*REAR DOOR CATCH	Not Necessary	85.00 FS	*- FS
21	1		*REAR ALUMINIUM RIM - LH	Cut	666.00 FS	*532.40 FS
22	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
23	1		*SUNDRIES	Necessary	400.00 FS	*63.20 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					10,598.00	5,314.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	350.00	0.00
3	TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	560.00
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, LHS FRONT AND REAR DOORS. TO RENEW LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. REINSTALL FRONT BUMPER AND ALL PARTS REMOVED	New	4,200.00	2,000.00
5	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL AND LHS REAR FENDER AND LHS WING MIRROR COVER	New	5,000.00	3,100.00
6	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,942.00	6,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >