

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/FWD20000985/AGA3Q2**Date:** 24/06/2020REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00010898  
**Claimant**  
**Vehicle No :** SKX782U **Insured Vehicle No :** SMC8297M  
Date of Loss: 13/01/2020 Nature of Claim: TP Claim No: 1202000002470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX782U**  
Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20785012B  
Reg. Date: 26/11/2015 (Man. Year: 2015) Chassis No: JN1JANT32Z0001187  
Colour: Black Odometer: 78951 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,783.00	6,933.70	1,849.30	21.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,920.00	1,560.00	44.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,263.00</b>	<b>8,853.70</b>	<b>3,409.30</b>	<b>27.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,000.00</b>		
<b>(S\$)</b>	12,263.00	7,000.00	5,263.00	42.92
<b>+ GST 7.00/7.00% (S\$)</b>	858.41	490.00	368.41	42.92
<b>Nett Amount (S\$)</b>	<b>13,121.41</b>	<b>7,490.00</b>	<b>5,631.41</b>	<b>42.92</b>
<b>+ Loss of Use (9.0 x S\$100.00/day) (S\$)</b>		900.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>8,397.45</b>		

INSPECTION

Date of Assignment: 14/01/2020  
Date Inspected: 16/01/2020 Inspected At: MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933  
Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 May 2020)	
<b>Parts:</b>	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKX782U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	4,200.00 FL	*4,200.00 FL
2	1		*TAILGATE LOGO	Necessary	62.00 FL	*62.00 FL
3	1		*TAILGATE EMBLEM X-TRAIL	Necessary	110.00 FL	*110.00 FL
4	1		*TAILGATE LOCK	Damaged	570.00 FL	*570.00 FL
5	1		*TAILGATE WEATHERSTRIP	Cut	140.00 FL	*140.00 FL
6	1		*TAILGATE WINDSCREEN MOULDING	Necessary	90.00 FL	*90.00 FL
7	1		*REAR BUMPER	Deformed	1,550.00 FL	*893.00 FL
8	1		*REAR BUMPER LOWER LID	Not Necessary	450.00 FL	*- FL
9	1		*REAR BUMPER LOWER LID CENTER GARNISH	Deformed	70.00 FL	*70.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
11	1		*REAR BUMPER TOWING COVER	Not Necessary	110.00 FL	*- FL
12	2		*REAR BUMPER REFLECTOR	Not Necessary	140.00 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	560.00 FL	*560.00 FL
14	1		*REAR BUMPER TOP CHROME	Not Necessary	320.00 FL	*- FL
15	1		*END PANEL TOP GARNISH	Deformed	90.00 FL	*90.00 FL
16	1		*END PANEL	Dented	450.00 FL	*450.00 FL
17	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
18	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
19	1		*SET REAR BUMPER CLIPS	Necessary	22.00 FS	*22.00 FS
20	1		*REAR END PANEL INSULATOR SEAL	Necessary	150.00 FS	*60.00 FS
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	150.00 FS	*10.00 FS
22	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,682.00</b>	<b>7,665.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	899.00	731.30
<b>Total Parts (\$\$)</b>	<b>8,783.00</b>	<b>6,933.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	120.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
6	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	180.00	60.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	220.00	120.00
8	TO REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>3,480.00</b>	<b>1,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >