

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 17 Jan 2020

Preliminary Advice

Vehicle No	: SLE8285Z	Accident Date	: 13/01/2020
Make	: LEXUS ES250	Policy No.	: A80436762QMY
Assignment Date	: 17/01/2020	Excess	: S\$800.00
Date of Inspection	: 16/01/2020	Est. Duration of Repair	: 21 days
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & rooftop portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	60,943.58
Revised Amount	:S\$	29,726.75
Check Items (Estimated)	:S\$	19,754.42
Total	:S\$	49,481.17

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	74,581.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,419.00

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Remarks : Please be inform the margin for repair is \$ 40,419.00